

BY REGD. AD/ SPEED POST

F. No. B-190019/CPCB/WQM-II/2017-18/ 8161

August 14, 2017

To

**M/s Shakti Bleaching & Dyeing Works,
Plot No. 16- A, Industrial Area,
Dada Nagar,
Kanpur**

Sub: Directions under Section 5 of the Environment (Protection) Act, 1986 regarding installation of on-line effluent monitoring system –reg.

WHEREAS, Textile industries are identified as Grossly Polluting industries (GPIs) which have been discharging environmental pollutants directly or indirectly into the ambient air and water, having potential threat to cause adverse effect on the water and air quality; and

WHEREAS, M/s **Shakti Bleaching & Dyeing Works**, Kanpur (hereinafter referred as 'the Unit') is involved in the process of textile bleaching & dyeing

WHEREAS, the Ministry of Environment & Forests, Government of India, vide Notifications No.S.O.157(E) of 27.02.1996 and S.O.730(E) dated 10.07.2002, has delegated the powers vested under Section 5 of the Environment (Protection) Act, 1986 (29 of 1986) to the Chairman, Central Pollution Control Board, to issue directions to any industry or any local body or any other authority for violations of the standards and rules notified under the Environment (Protection) Rules, 1986 and amendment thereof; and

WHEREAS, CPCB issued Directions dated 30.7.2015 to the unit to comply with the following Directions:

1. The unit shall submit documentary evidence regarding status of installation of online monitoring system
2. The unit shall submit the status of connectivity for submission of online 24X7 monitoring data to SPCBs/PCC and CPCB
3. The unit shall submit information as per Annexure I (Enclosed with Directions dated June 30, 2015) to Member Secretary, CPCB

Whereas, the unit was inspected on 21.04.2017 by a team of officials deputed by CPCB and it has been found that:

1. The electromagnetic flowmeter installed in the unit is not connected with CPCB server.
2. The quality of effluent discharged from the ETP does not comply with the notified standards

3. ETP is not being operated properly and septic conditions have developed in the ETP
4. Bypass arrangement was found for direct discharge of bleaching effluent without any treatment

NOW, THEREFORE, in view of the above and in exercise of the powers delegated to the Chairman, Central Pollution Control Board under section 5 of the Environment (Protection) Act, 1986, the unit is hereby directed to comply with the following directions:

1. The unit shall immediately close down its operations and remain closed till it has adequate arrangements for treating effluent, installs & connects online effluent monitoring system and possesses valid consent
2. The unit shall seek permission from CPCB before resumption of manufacturing operation.

In case of default in compliance with the above directions CPCB will be constrained to initiate appropriate actions against the unit, without giving any further notice, in accordance with provisions of Environment (Protection) Act, 1986.

(S P SINGH PARIHAR)
CHAIRMAN

Copy to:

| | | |
|---|---------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------|
| 1 | Member Secretary Uttar Pradesh Pollution Control Board, Building No. TC-12V, Vibhuti Khand, Gomti Nagar, Lucknow – 226 010 | With a request to ensure compliance of the directions. |
| 2 | Advisor (CP Division) Ministry of Environment, Forest & Climate Change Prithvi Block, Indira Paryavaran Bhawan, Jorbagh Road, New Delhi – 110 003 | For kind information pls. |
| 3 | Incharge, Regional Office (North), Central Pollution Control Board, PICUP Bhawan, Ground Floor, Vibhuti Khand, Gomti Nagar, Lucknow – 226 010. | For information please |
| 4 | In-charge, IPC-III Div., CPCB Delhi | For information please |
| 5 | In-charge, IT Division, CPCB | For information please. |
| 6 | In-charge, WQM-II Div., CPCB Delhi | For information please. |


(A.B.Akolkar)
Member Secretary