

SPEED POST

F. No. B-751(483)/Textile/WQM-II/CPCB/2017-18 31st October, 2017

To

M/s Rakam Export,
D-9, Industrial Estate,
Farrukhabad.

Directions under Section 5 of the Environment (Protection) Act, 1986 –reg.

WHEREAS, the Textile dyeing and bleaching industries are identified as one of the Grossly Polluting industries (GPIs) which have been discharging environmental pollutants directly or indirectly into the ambient air and water, having potential threat to cause adverse effect on the water and air quality; and

WHEREAS, the Central Government has notified the general discharge standards of environmental pollutants from various categories of industries under the Environment (Protection) Act, 1986 and the rules framed there under;

WHEREAS, the Ministry of Environment & Forests, Government of India, vide Notifications No.S.O.157(E) of 27.02.1996 and S.O.730(E) dated 10.07.2002, has delegated the powers vested under Section 5 of the Environment (Protection) Act, 1986 (29 of 1986) to the Chairman, Central Pollution Control Board, to issue directions to any industry or any local body or any other authority for violations of the standards and rules notified under the Environment (Protection) Rules, 1986 and amendment thereof; and

WHEREAS, M/s Rakam Export, D-9, Industrial Estate, Farrukhabad (here in after referred as 'the unit') is a textile processing unit; and

WHEREAS, the unit was inspected on 1st April, 2017 and was issued closure directions dated 31st May, 2017 for not having valid consent to operate and not installing OCEMS;

WHEREAS, the unit was re-inspected on 21st June, 2017 to verify the compliance of CPCB directions and the following observations were made:

- 1) The unit was found operational at the time of the inspection.
- 2) As reported, the dyeing process was closed a year ago.
- 3) The ETP was not in operation at the time of inspection and the untreated effluent was being bypassed into the drain outside the premises.
- 4) The unit did not provide any consent under Water or Air Acts.
- 5) OCEMS/ EMF were not installed in the unit.
- 6) The analysis results of the unit are given below which indicate **non-compliance of the unit** with the prescribed standards :

Parameters	pH	TSS	BOD	COD	TDS
Outlet of ETP	7.21	647	889	2594	1700
Standards	6.5-8.5	100	30	250	2100

Contd..

AND WHEREAS, the unit in its reply dated 10th July, 2017 had stated that

1. It has stopped its dyeing, printing and processing operations and had informed to UPPCB.
2. The unit is involved in dry process (steaming) only and thus does not involve any water pollution.

AND WHEREAS, the unit was found in operation on 21st June, 2017 which is in violation of CPCB closure directions dated 31st May, 2017 issued under Section 5 of the Environment (Protection) Act, 1986 for which appropriate legal action shall be initiated separately.

NOW, THEREFORE, in view of the above and in exercise of the powers delegated to the Chairman, Central Pollution Control Board under Section 5 of the Environment (Protection) Act, 1986, the unit, **M/s Rakam Export, D-9, Industrial Estate, Farrukhabad** is hereby directed to close down all manufacturing operations till the compliance of the CPCB directions dated 31st May, 2017.

In case of default in compliance with the above directions CPCB may initiate appropriate actions against the unit, without giving any further notice, in accordance with provisions of Environment (Protection) Act, 1986.


(S P SINGH PARIHAR)
CHAIRMAN

Copy to:

1. The Member Secretary,
Uttar Pradesh Pollution Control
Board,
Building No. TC-12V, Vibhuti
Khand,
Gomati Nagar, Lucknow.
2. The Regional Directorate,
Central Pollution Control Board,
Lucknow,
PICUP Bhawan, Ground Floor,
Vibhuti Khand, Gomati Nagar,
Lucknow-226010
3. The Advisor (CP Division)
Ministry of Environment, Forests
& Climate Change,
Indra Paryavaran Bhavan,
Jor Bagh Road, New Delhi - 110
003

For kind information

4. The Incharge, IT Division, CPCB | For uploading on CPCB's website

5. Master File WQM-II, CPCB


(A SUDHAKAR)
MEMBER SECRETARY