



केन्द्रीय प्रदूषण नियंत्रण बोर्ड
CENTRAL POLLUTION CONTROL BOARD
पर्यावरण, वन एवं जलवायु परिवर्तन विभाग भारत सरकार
MINISTRY OF ENVIRONMENT, FOREST & CLIMATE CHANGE GOVT. OF INDIA

July 02, 2018

B-Tannery/IPC-IV/2018-19/

To

M/s Shameel Tanners,
H.No.22/5, Deshaipet Village,
Warangal District - 506 002,
Telangana

Sub.: Directions under Section 5 of the Environment (Protection) Act, 1986 regarding non-compliance of notified norms.

WHEREAS, the tanneries are identified as one of the 17 categories of highly polluting industries which have been discharging environmental pollutants directly or indirectly into the ambient air and water, having potential threat to cause adverse effect on the water and air quality; and

WHEREAS, the Central Government has notified the standards for discharge of environmental pollutants from various categories of industries under the Environment (Protection) Act, 1986 and the rules framed there under; and

WHEREAS, there is need to inculcate habit of self-monitoring within the industries for complying with the prescribed standards and this can be achieved by the methods like installing online effluent and emission monitoring devices; and

WHEREAS, for strengthening the monitoring and compliance through self-regulatory mechanism, online source emission and effluent monitoring systems need to be installed and operated by the industries on 'polluter pays principle'; and

WHEREAS, a direction under section 18 (1) (b) of the Water (Prevention & Control of Pollution) Act, 1974 and the Air (Prevention & Control of Pollution) Act, 1981 was issued on February 05, 2014 to all the State Pollution Control Boards (SPCBs)/ Pollution Control Committees (PCCs) for installation of online effluent monitoring system w.r.t. pH, BOD, COD, TSS, and Flow parameters in Tanneries; and

WHEREAS, considering the requests/ representations received from industries/ industrial associations/ SPCBs / PCCs, an extension of time up to June 30, 2015 for installation of online monitoring systems was granted vide direction dated March 02, 2015 under section 18 (1) (b) of the Water (Prevention & Control of Pollution) Act, 1974 and the Air (Prevention & Control of Pollution) Act, 1981; and

WHEREAS, a letter vide dated May 29, 2015 was issued by the Chairman CPCB to all the SPCBs/ PCCs informing that no further extension of time will be given after June 30, 2015 and withdrawal of consent to operate along with forfeiture of bank guarantee of non-complying units; and

'परिवेश भवन' पूर्वी अर्जुन नगर, दिल्ली-110032

Parivesh Bhawan, East Arjun Nagar, Delhi-110032

दूरभाष/Tel : 43102030, 22305792, वेबसाइट/Website : www.cpcb.nic.in

WHEREAS, concerned SPCB/ PCC issued directions under section 33A of the Water (Prevention & Control of Pollution) Act, 1974 and section 31A of the Air (Prevention & Control of Pollution) Act, 1981 to install the online monitoring system by June 30, 2015 and to submit bank guarantee of 100% of the cost of online emission & effluent monitoring system; and

WHEREAS, the Ministry of Environment & Forests, Government of India, vide Notifications No. S. O. 157 (E) of 27.02.1996 and S. O. 730 (E) dated 10.07.2002, has delegated the powers vested under Section 5 of the Environment (Protection) Act, 1986 (29 of 1986) to the Chairman, Central Pollution Control Board, to issue directions to any industry or any local body or any other authority for violations of the standards and rules notified under the Environment (Protection) Rules, 1986 and amendment thereof; and


WHEREAS, your industry, M/s Shameel Tanners, H. No. 22/5, Deshaipet Village, Warangal District - 506 002, Telangana was inspected by a team of Scientists from Regional Directorate - South, CPCB, Bangalore on 26.5.2018 based on OCEMS readings and made following observations requiring attention of CPCB:

1. Although ETP was in operation but it was observed that effluent carrying concrete channel has been damaged completely.
2. Sample collected at the outlet of ETP was analysed and observed that it is meeting with the prescribed standards in respect of TSS - 02mg/l (standard - 100 mg/l), BOD - 52mg/l (standard - 100 mg/l), and Oil & Grease - 6.9 (standard - 10mg/l). However, Unit is not meeting the land discharge norms in respect of TDS - 5166mg/l (standard- 2100mg/l).
3. ETP is being operated in an unscientific manner as sulphide correction and pH correction tanks are not maintained. The process effluent is being blended with domestic sewage before treating in ETP.
4. The Unit has installed OCEMS for all parameters at the ETP outlet however, pH sensor was found out of order due to power fluctuations. Also, the online system values are not matching with the laboratory analytical report.
5. The Unit has not provided space/shed for storage of hazardous waste and housekeeping in soaking area and dyeing area was not satisfactory.

NOW, THEREFORE, in exercise of powers delegated to the Chairman, CPCB under Section 5 of the Environment (Protection) Act, 1986, M/s Shameel Tanners, H. No. 22/5, Deshaipet Village, Warangal District - 506 002, Telangana, is hereby directed to explain reasons within 7 days from the date of issue of these directions as to why your unit should not be closed down for the shortcomings as observed during inspection on 26.05.2018. The unit is further directed for the following :

1. The unit shall immediately initiate the process for rectification of shortcomings observed during inspection on 26.05.2018 as detailed in previous para on page 2/-. All steps shall be completed within 21 days from the date of issue of these directions.
2. The unit shall submit the action plan and action taken report in this respect within 7 days from the date of issue of these directions.

In case of default in compliance with the above directions, CPCB will be constrained to initiate appropriate actions against the Unit, without giving any further opportunity, in accordance with provisions of the Environment (Protection) Act, 1986.


[S. P. S. Parihar]
Chairman

27/5/18



Copy for kind information & Compliance to :

1.	The Chairman, Telangana State Pollution Control Board Paryavaran Bhavan, A-III, Industrial Estate, Sanath Nagar, Hyderabad, Telangana
2.	The Joint Secretary - CP Division Ministry of Environment, Forests and Climate Change Indira Paryavaran Bhawan, Aliganj, Jor Bagh Road, New Delhi - 110003
3.	The Regional Director, Central Pollution Control Board Regional Directorate (South) 1st & 2nd Floors, Nisarga Bhavan A-Block, Thimmaiah Main Road, 7th D Cross, Shivanagar, Bengaluru -560 079
4. ✓	The Divisional Head , IT Division, CPCB-HO., Delhi
5.	The Divisional Head , IPC-VI Division, CPCB-HO., Delhi



02/7/18

[N.K. Gupta]

Divisional Head - IPC-IV