

SPEED POST

F.N. B-751(563)/Textile/WQM-II/CPCB/2017-18 (13984)

Dated: 24.11.2017

To,
M/s Handloom Bhandar
1315, Kundan Road,
UNNAO, Uttar Pradesh

Sub.: Directions under Section 5 of the Environment (Protection) Act, 1986 –reg.

WHEREAS, the **Textile dyeing and bleaching** industries are identified as one of the Grossly Polluting industries (GPIs) which have been discharging environmental pollutants directly or indirectly into the ambient air and water, having potential threat to cause adverse effect on the water and air quality; and

WHEREAS, M/s Handloom Bhandar (here in after referred as ‘the Unit’) located at 1315, Kundan Road, Uttar Pradesh is involved in the processing of Hosiery clothes; and

WHEREAS, inspection of the unit was conducted on March 24, 2017 by CPCB to check the compliance. The inspection report was examined and the following observations are made:-

- (i) The unit was found operational. The unit has not obtained NOC from CGBA for extraction of Ground water from the bore well.
- (ii) The unit has not installed OCEMS.
- (iii) The unit has installed ETP. effluent samples connected and analysed. The outlet sample was found non-complying w.r.t. the notified effluent discharge standards with BOD-228 mg/l (against norms of 30 mg/l), COD-463 mg/l (against norms of 250 mg/l), Sulphate as S- 19.5 mg/l (against norms of 2 mg/l), TDS-3100 mg/l (against norms of 2100 mg/l), MLSS and MLVSS in aeration tank are not satisfactory and found below 2300 mg/l.
- (iv) The Unit discharges its treated effluent into city Jail drain which meets river Ganga. The unit has to achieve zero liquid discharge.
- (v) The unit has not provided information regarding Hazardous Waste authorization. The unit has not made any separate HW storage yard and no log book was maintained regarding HW generation and disposal. However, unit has sent their ETP sludge to TSDF.

WHEREAS, the Ministry of Environment & Forests, Government of India, vide Notifications No.S.O.157(E) of 27.02.1996 and S.O.730(E) dated 10.07.2002, has delegated the powers vested under Section 5 of the Environment (Protection) Act, 1986 (29 of 1986) to the Chairman, Central Pollution Control Board, to issue directions to any industry or any local body or any other authority for violations of the standards and rules notified under the Environment (Protection) Rules, 1986 and amendment thereof; and

WHEREAS, CPCB issued closure direction dated: 15.05.2017 to the unit, to close down operation with immediate effect till valid consent and authorization is granted by UPPCB, ETP effluent meets the stipulated norms and the Unit shall install OCEMS to get its connected to CPCB server, and

Contd.

WHEREAS, the unit was again inspected by the CPCB on 22.06.2017 and was found closed, and

WHEREAS, the unit replies vide letters dated 20.07.2017, 24.07.2017 and 21.08.2017 were examined and following observations are made:-

- (i) The unit has submitted Self Certificate mentioning that it has closed the operations from 20.07.2017.
- (ii) The unit has installed OCEMS and provided connectivity to CPCB server;
- (iii) The unit has submitted Affidavit dated 21.08.2017 in the required format;
- (iv) The unit has made changes (a tube settler, PSF and ACF) for improvement in performance of existing ETP.
- (v) The unit has applied for NOC from CGWA for extraction of ground water;
- (vi) The unit has authorization for Hazardous Waste disposal through M/s Bharat Oil Ltd.
- (vii) The unit has consent to operate (valid upto 31.12.2018) under the Water Act 1974 and Air Act 1981.

WHEREAS, CPCB Constituted a Three-Member Committee vide office order dated 27/09/2017 having representative from CPCB, MoEF&CC and NMCG for examination and recommendation for revocation of the closure direction issued by CPCB; and

WHEREAS, The Three Member Committee in its meeting held on 21/11/17 examined the replies dated 20.07.2017, 24.07.2017 & 21.08.2017 and recommended for the revoke of the closure direction.

NOW THEREFORE, in view of the above and in exercise of the powers delegated to the Chairman, Central Pollution Control Board under section 5 of the Environment (Protection) Act 1986, the closure directions dated 15.05.2017 is revoked and the unit M/s Handloom Bhandar, 1315, Kundan road, Unnao, U.P. is permitted to resume manufacturing operations and directed to comply with the following:-

- (i) The unit shall immediately inform to the CPCB on resumption of manufacturing operation; and.
- (ii) The unit shall submit effluent analysis report to CPCB within 30 days from resuming the operation from an EPA recognised laboratory.
- (iii) The Unit shall ensure all time compliance of the standards of treated effluent for Textile industries as per Gazette notification dated 10.10.2016 under Environment (Protection) Rules, 1986.

In case of failure of the unit to comply with the directions, action will be taken in accordance with the provisions under Environment (Protection) Act, 1986.

(S P SINGH PARIHAR)
CHAIRMAN

Copy to:

- 1 **Member Secretary**
Uttar Pradesh Pollution Control Board,
Building No. TC-12V, Vibhuti Khand,
Gomti Nagar, **Lucknow – 226 010**
With a request to ensure
compliance of the directions.
- 2 **Advisor (CP Division)**
Ministry of Environment, Forest & Climate Change
Prithvi Block, Indira Paryavaran Bhawan,
Jorbagh Road,
New Delhi – 110 003
For kind information
pls.
- 3 **District Magistrate,**
Collectorate Office, dist. Unnao,
Unnao (Uttar Pradesh)
The ensure compliance
of the direction.
- 4 **Managing Director,**
Madhyanchal Vidyut Vitaran Nigam Ltd.
Head Office:- 4-, Gokhle Marg,
Lucknow (UP)- 226001
To connect the power/
electricity supply
- 5 The In-charge, Regional Office (North),
Central Pollution Control Board,
PICUP Bhawan, Ground Floor,
Vibhuti Khand, Gomti Nagar,
Lucknow- 226 010, U.P
For information.
- ✓ 6 In-charge, IT Division, CPCB
- 7 Master Copy WQM-II, CPCB Delhi
For information
- 8 In-charge, WQM- II Division, CPCB



(A. SUDHAKAR)
MEMBER SECRETARY