

Speed Post

File No. B-190194/Textile/New/WQM-II/CPCB/2017-18

Date: 08-01-2018

16481

15-01-2018

To,

**M/s Shobha Woollens,
Village- Hariyaon,
Distt. Bhadohi, U.P.**

**DIRECTION UNDER SECTION 5 OF THE ENVIRONMENT (PROTECTION) ACT,
1986**

WHEREAS, the Textile, Dyeing & Bleaching industries are identified as one of the Grossly Polluting industries (GPIs) which have been discharging environmental pollutants directly or indirectly into the ambient air and water, having potential threat to cause adverse effect on the water and air quality; and

WHEREAS, The central Government has notified the standards for discharge of environmental pollutants from various categories of industries under the Environment (Protection) act, 1986 and the rules framed there under; and

WHEREAS, the Ministry of Environment & Forests, Government of India, vide Notifications No. S.O. 157 (E) of 27.02.1996 and S.O. 730 (E) dated 10.07.2002, has delegated the powers vested under Section 5 of the Environment (Protection) Act, 1986 (29 of 1986) to the Chairman, Central Pollution Control Board, to issue directions to any industry or any local body or any other authority for violations of the standards and rules notified under the Environment (Protection) Rules, 1986 and amendment thereof; and

WHEREAS, M/s Shobha Woollens, Village- Hariyaon, Distt. Bhadohi, U.P. (here in after referred as 'the unit') is a textile processing unit; and

WHEREAS, inspection of the unit was conducted on 23-03-2017 by a team deputed by CPCB to check the status of compliance of prescribed norms and was issued closure direction date 17-05-2017 under section 5 of the Environment (Protection) Act, 1986 for not allowing the inspection team in the industry premises; and

WHEREAS, the unit was inspected on 20-07-2017 to verify the compliance of CPCB directions and following observations were made:

1. The unit was found operational at the time of inspection; however wet activities were closed on the day of visit due to boiler maintenance. Other dry activities were going on as a normal day.
2. The unit does not have valid consent to operate from UPPCB under Water and Air Acts.
3. Bypass arrangement for untreated effluent discharge was noticed near the ETP.
4. The unit has not installed Online continuous effluent monitoring system (OCEMS).

AND WHEREAS, the unit was found operational on 20.07.2017 which is in violation of CPCB closure direction dated 17-05-2017 for which separate legal action shall be initiated separately; and

WHEREAS, CPCB issued closure direction dated 08.11.2017 to the unit under section 5 of the Environment (Protection) Act, 1986; and

WHEREAS, the unit replies vide letters dated 25-05-2017, 05.10.2017, 18.10.2017, 26.10.2017 and 21.11.2017 were examined and following observations are made:

1. The unit has informed about removal of all bypasses arrangement.
2. The unit has applied for consent to operate from UPPCB.
3. The unit has provided OCEMS data connectivity to CPCB server.

AND WHEREAS, CPCB constituted a three-member committee vide office order dated 27.09.2017 having representative from CPCB, MoEF & CC and NMCG for examination and recommendation for revocation of the closure direction issued by CPCB; and

WHEREAS, the three member committee in its meeting held on 21.12.2017 examined the replies of the Unit and recommended that the Unit may be allowed to resume operation and the unit shall submit treated effluent analysis report from laboratory recognized under Environment (Protection) Act, 1986 within 30 days of resumption of operations; and

NOW THEREFORE, in view of the above and in exercise of the powers, delegated to the Chairman, CPCB under Section 5 of the Environment (Protection) Act, 1986, the unit **M/s Shobha Woollens, Village- Hariyaon, Distt. Bhadohi, U.P.** is directed to comply with the following directions:

1. The Unit shall remain closed and may resume manufacturing operations after seeking valid consent to operate from Uttar Pradesh Pollution Control Board.
2. The Unit shall immediately inform to CPCB regarding the resumption of operations.
3. The Unit shall operate ETP properly so as to ensure compliance with the effluent discharge norms notified under Environment (Protection) Act, 1986.
4. The Unit shall submit one month treated effluent analysis report by the Laboratory recognized under the Environment (Protection) Act, 1986 within 30 days of resumption of the unit.
5. The Unit shall ensure continuous connectivity OCEMS with CPCB server.
6. The unit shall obtained permission form CGWA for extraction of groundwater.

In case of default in compliance with the above directions CPCB will be constrained to initiate appropriate actions against the unit, without giving any further notice, in accordance with provisions of Environment (Protection) Act, 1986.


(S. P. SINGH PARIHAR)
CHAIRMAN

Copy to:

- 1 **The Member Secretary**
Uttar Pradesh Pollution Control Board
Building No-TC- 12 V, Vibhuti Khand,
Gomati Nagar, Lucknow-226010

: [To ensure compliance of the
direction please]

- 2 **The Advisor (CP Division)**
Ministry of Environment, Forests & Climate Change,
Indra Paryavaran Bhavan,
Jor Bagh Road, New Delhi - 110 003 : [For kind information please]
- 3 **The District Magistrate**
Collectorate Office, District; Bhadohi
Uttar Pradesh : [For kind information please]
- 4 **The Regional Director,**
Lucknow Zonal Office,
Central Pollution Control Board,
Ground Floor, PICUP Bhawan,
Vibhuti Khand, Gomti Nagar,
Lucknow-226010 (U.P.) : [with direction that unit may be
randomly inspected within 30
days of resumption]
- 5 ✓ The Incharge IT Division, CPCB, Delhi :[For uploading the direction at
CPCB website]
- 6 The Incharge WQM-II, CPCB, Delhi :[For kind information please]


(A.SUDHAKAR)
MEMBER SECRETARY