



केन्द्रीय प्रदूषण नियंत्रण बोर्ड
CENTRAL POLLUTION CONTROL BOARD
पर्यावरण, वन एवं जलवायु परिवर्तन मंत्रालय भारत सरकार
MINISTRY OF ENVIRONMENT, FOREST & CLIMATE CHANGE GOVT. OF INDIA

Speed Post

No. Tannery online/IPC-IV/2017-18/14828

December 20, 2017

To:

M/s H.J. Tannery Pvt. Ltd,
9th Km Stone, Jansath Road,
Muzaffarnagar, Uttar Pradesh

Sub: Show-cause notice under section 5 of the Environment (Protection) Act, 1986

WHEREAS, the Central Government has notified the standards for discharge of environmental pollutants from various categories of industries under the Environment (Protection) Act, 1986 and Rules framed there under; and

WHEREAS, all industries are required to install and regularly operate the requisite pollution control facilities to comply with the standards for discharge of environmental pollutants; and

WHEREAS, CPCB has developed a protocol for selection of industries for inspection based on SMS alerts generated from OCEMS due to non-compliance of effluent discharge norms and non-connectivity of OCEMS; and

WHEREAS, M/s H.J. Tannery Pvt. Ltd, 9th Km Stone, Jansath Road, Muzaffarnagar, Uttar Pradesh was selected for inspection in view of SMS alerts generated from OCEMS due to non-compliance of effluent discharge norms; and

WHEREAS, inspection of M/s H.J. Tannery Pvt. Ltd, 9th Km Stone, Jansath Road, Muzaffarnagar, Uttar Pradesh (hereafter referred as "Unit") was conducted by a team of officials from CPCB Regional Directorate Lucknow on November 7, 2017 to check the status of compliance of prescribed norms; and

WHEREAS, the Unit was found not carrying out any wet operation during the inspection and only dry operation i.e. finishing operation was carried out. The inspecting team made the following observations:

1. The Unit was carrying out operation without valid consent from UPPCB.
2. The Unit has not installed flow meter at bore well used for groundwater extraction. The Unit has not obtained NOC for groundwater extraction from CGWA.
3. Proper mixing arrangements are not provided in the equalization tank.
4. Proper arrangement for segregation of chrome bearing stream not provided by the Unit.
5. ETP sludge was not stored in covered area and indiscriminately disposed in low lying area.
6. DG set was not provided with acoustic enclosure.
7. Drain provided for conveyance of treated effluent was found damaged.

'परिवेश भवन' पूर्वी अर्जुन नगर, दिल्ली-110032
Parivesh Bhawan, East Arjun Nagar, Delhi-110032

दूरभाष/Tel : 43102030, 22305792, वेबसाइट/Website : www.cpcb.nic.in

WHEREAS, the Ministry of Environment & Forests, Government of India, vide Notifications No. S. O. 157 (E) of 27.02.1996, has delegated the powers vested under Section 5 of the Environment (Protection) Act, 1986 (29 of 1986) to the Chairman, Central Pollution Control Board, to issue directions to any industry or any local body or any other authority for violations of the standards and rules notified under the Environment (Protection) Rules, 1986 and amendment thereof; and

NOW, THEREFORE, in view of the above and in exercise of the powers delegated to the Chairman, CPCB under Section 5 of the Environment (Protection) Act, 1986, notice is hereby served to the Unit - M/s H.J. Tannery Pvt. Ltd, 9th Km Stone, Jansath Road, Muzaffarnagar, Uttar Pradesh to show cause why the Unit should not be closed down until necessary steps are taken to rectify the short-comings;

The Unit is hereby given an opportunity to file its reply within 15 days from the date of issue of this notice, failing which it will be presumed that the Unit has nothing to say in this matter and action will be initiated against the Unit under the provision of the Environment (Protection) Act, 1986 and amendments thereof.



(S.P. Singh Parihar)
Chairman

21.12.17 *Alc*

Copy to:

1. **The Chairman,**
Uttar Pradesh Pollution Control Board
Third Floor, PICUP Bhawan
Vibhuti Khand, Gomti Nagar
Lucknow - 226 010

:for information please

2. **The Regional Director,**
Central Pollution Control Board
Regional Directorate (Lucknow)
Ground Floor, PICUP Bhawan
Vibhuti Khand, Gomti Nagar
Lucknow - 226 010


: for information please

3. **The Joint Secretary, CP Division**
Ministry of Environment, Forests and Climate Change
Indira Paryavaran Bhavan, Jorbagh Road
New Delhi - 110 003

:for information please

4. **The Divisional Head, IT Division, CPCB**

:for information please


(A. Sudhakar)

Member Secretary *Alc*

M/s H.J. Tannery Pvt. Ltd, 9th Km Stone, Jansath Road, Muzaffarnagar, Uttar Pradesh

