



By Speed Post

F.No. B-23012/1/IPC-IV/ 15525

December 29, 2017

To

M/s Bhartiya Leather Udyog,
B-7 MIE, Part II. Jhajjar,
Haryana

DIRECTION UNDER SECTION 5 OF THE ENVIRONMENT (PROTECTION) ACT, 1986

WHEREAS, the Central Government has notified the standards for discharge of environmental pollutants from various categories of industries under the Environment (Protection) Act, 1986 and the rules framed there under; and

WHEREAS, the Ministry of Environment, Forest and Climate Change, Govt. of India, vide notification S.O.157(E) of 27.02.1996 has delegated powers vested under Section 5 of the Environment (Protection) Act, 1986 (29 of 1986) to the Chairman, Central Pollution Control Board (CPCB), to issue direction to any industry, Municipal Corporation, Municipal Council, Cantonment Board to any local or other Authority for the violation of emission and effluent standards notified under the Environment (Protection) Rules, 1986 and other standards and norms; and

WHEREAS, M/s Bhartiya Leather Udyog, B-7 MIE, Part II. Jhajjar, Haryana (hereinafter referred as 'the Unit') is engaged in processing of wet blue skin to finished leather through dyeing and fat liquoring process at a processing capacity of 800 skin of (sheep/goat) per day; and

WHEREAS, CPCB conducted inspection of the Unit on July 3, 2017 to verify the compliance status of discharge standards and made the following observations:

1. The Unit has ETP based on ASP at a capacity of 25 kld.
2. The Unit found complying the prescribed effluent norms with pH – 7.47 (Standards: 6.5 to 9) and TSS – 27.9 mg/l (Standards: 100mg/l) but not complying for the parameter of BOD – 36mg/l (Standards: 30mg/l) and treated effluent is partially recycled into process and rest discharged into HUDA drain.
3. The Unit has installed DG sets which are not equipped with acoustic enclosure and exhaust pipe.
4. The Unit has valid consent under Air/Water acts upto 30.9.2020 and Authorisation under the Hazardous and other Wastes (Management, & Transboundary Movement) Rules, 2016.
5. The Unit has installed OCEMS at final outlet of ETP, and OCEMS data indicates improper maintenance.

WHEREAS, in view of the non-compliance of prescribed norms, Chairman, CPCB vide letter dated August 16, 2017 issued following directions under section 5 of the Environment (Protection) Act, 1986 to M/s Bhartiya Leather Udyog, B-7 MIE, Part II. Jhajjar, Haryana for compliance:

1. The Unit shall operate and maintain effluent treatment plant (ETP) properly to treat the entire generated effluent and shall provide proper mixing arrangement at equalization tank of ETP and shall ensure compliance with the prescribed effluent discharge standards.
2. The Unit shall ensure proper maintenance and operation & calibration of OCEMS so as to obtain continuous accurate results.
3. The Unit shall install electromagnetic flow meter at the water consumption point and shall maintain records of the same.
4. The Unit shall install acoustic enclosures and adequate exhaust pipe system at DG sets.
5. The Unit shall submit compliance report to CPCB on the direction points 1 to 4 within 45 days.

Contd..2/

'परिवेश भवन' पूर्वी अर्जुन नगर, दिल्ली-110032
Parivesh Bhawan, East Arjun Nagar, Delhi-110032

दूरभाष/Tel : 43102030, 22305792, वेबसाइट/Website : www.cpcb.nic.in

WHEREAS, the Unit vide letter dated 24/9/2019 and e-mail dated 26/9/2017 submitted compliance report to CPCB on aforementioned directions; and

WHEREAS, officials from CPCB Regional Directorate, Lucknow, carried out inspection of the Unit on 28/11/2017 to verify compliance of CPCB directions issued on 16.08.2017 and following compliance status was observed:

1. The treated effluent discharged by the Unit was found complying with the notified effluent discharge norms for parameters: pH – 6.9 (Standards: 6.5 to 9), TSS – 80 mg/l (Standard: 100mg/l) and Total Cr.: BDL but not complying for the parameter of BOD – 115 mg/l (Standard: 30mg/l). The Unit has provided proper mixing arrangement at equalization tank of ETP.
2. The OCEMS was found in operation but there is substantial difference in OCEMS data and laboratory results:

Sampling location	Analysis results	Date\ time	Parameters (All parameters are in mg/l except pH)			
			pH	TSS	COD	BOD
Final outlet	Lab data	28/11/17	6.90	80.0	513.0	115.0
	Online data	(10AM)	7.17	57.34	140.01	24.32

3. The Unit has installed electromagnetic flow meter at the water consumption point and maintained records.
4. The Unit has installed acoustic enclosure and exhaust pipe at DG sets.

WHEREAS, the above compliance status indicates repeated violation of notified effluent discharge norms and therefore non-compliance of CPCB directions dated 16.8.2017;

NOW THEREFORE, in view of the above and in exercise of the powers delegated to the Chairman, Central Pollution Control Board (CPCB) under section-5 of the Environment (Protection) Act, 1986, M/s Bhartiya Leather Udyog, B-7 MIE, Part II, Jhajjar, Haryana is hereby directed to close down all the manufacturing operations with immediate effect and report compliance to CPCB.

The Unit shall immediately initiate necessary steps to ensure compliance with the following directions and submit report to CPCB:

1. The Unit shall get conducted adequacy assessment of ETP through reputed institutes such as IIT/NEERI/CLRI and submit report to CPCB. ETP shall be modified/upgraded as per advise of the consulting institute to ensure compliance with the notified norms
2. The Unit shall seek guidance from the expert institute to carry out proper operation and maintenance of ETP so as to ensure compliance with notified norms.
3. The Unit shall ensure proper maintenance and calibration of OCEMS so as to obtain continuous accurate results.

In case of default in compliance with the above directions by the Unit, CPCB will be constrained to initiate appropriate action against the Unit, without giving any further notice, in accordance with provisions of the Environment (Protection) Act, 1986.

(S.P. SINGH PARIHAR)

CHAIRMAN

o/c Contd..3/-

M/s Bhartiya Leather Udyog, B-7 MIE, Part II, Jhajjar, Haryana


01.01.2018

Handwritten signature

Copy to:

-3-

1.	The Member Secretary Haryana State Pollution Control Board, Sector 5, Panchkula, Haryana 134109	with a request to ensure closure and submit status report within 15days.
2.	The District Magistrate, Jhajjar, Haryana	for necessary action please.
3.	The Managing Director, Uttar Haryana Bijli Vitran Nigam Limited, Vidyut Sadan, Plot No.: C16, Sector-6, Panchkula, Haryana	with a request to disconnect electricity supply.
4.	The Regional Director, Central Pollution Control Board, Regional Directorate (Lucknow) PICUP Bhawan, Ground Floor Vibhuti Khand, Gomati Nagar, Lucknow-226010	for information.
5.	The Joint Secretary, (CP Division) Ministry of Environment, Forests & Climate Change, Indra Paryavaran Bhavan, Jor Bagh Road, New Delhi - 110 003	for information.
6. ✓	The Divisional Head, IT Division, CPCB	
7.	Master copy, IPC-IV, CPCB	


(A. Sudhakar)
Member Secretary

etc.

