



By Registered A.D.

B-29016/04/IPC-I/ 18894

January 29, 2018

To
M/s Rathi Dye Chem Pvt. Ltd.,
Plot no. 40, M.I.D.C. Dhatav, Roha,
Dist. Raigad- 402116
Maharashtra

Sub: Directions under Section 5 of the Environment (Protection) Act, 1986 – reg.

WHEREAS, Dye & Dye Intermediate units are identified as one of the 17 categories of highly polluting industries which have been discharging environmental pollutants directly or indirectly into the ambient air and water, having potential threat to cause adverse effect on the water and air quality; and

WHEREAS, Central Pollution Control Board, Regional Directorate, Vadodara inspected **M/s Rathi Dye Chem Pvt. Ltd., Plot no. 40, M.I.D.C. Dhatav, Roha, Dist. Raigad- 402116 Maharashtra** on November 23, 2017 w.r.t SMS alert of Online Continuous Effluent monitoring System during the period of September 15 to October 15, 2017 to assess the compliance of the existing pollution control measures; and

WHEREAS, the inspection team observed that the ETP was not fully operational (due to some maintenance) and Effluent analysis results indicate that the unit is not complying with Maharashtra State Pollution Control Board standards for COD (840 > 250 mg/l), BOD (156 > 100 mg/l) & TDS (6365 > 2100 mg/l) that may cause a grave injury to the environment; and

WHEREAS, upon comparison of treated effluent & the effluent from tank where Online Continuous Effluent monitoring System is installed, dilution of effluent in Online Continuous Effluent monitoring System tank is observed; and

WHEREAS, untreated (trade) effluent was found spread on open land and flowing in an earthen channel; and

WHEREAS, it was observed that drain pipelines/ channels were leaking out and fugitive emissions were observed around operational boiler; and

WHEREAS, it was observed that the unit has two alkali scrubbers that are not having stack monitoring facility; and

WHEREAS, the fly ash was also stored in open and the unit could not provide any copy of hazardous waste manifest pertaining to disposal to TSDF; and

WHEREAS, as per Section 4, Sub section (5) of The Environment (Protection) Rules, 1986; In case where the Central Government is of the opinion that in view of the likelihood of a grave injury to the environment it is not expedient to provide an opportunity to file objections against the proposed direction, it may, for reasons to be recorded in writing, issue directions without providing such an opportunity; and


WHEREAS, the Ministry of Environment & Forests, Government of India, vide Notifications No. S. O. 157 (E) of 27.02.1996 and S. O. 730 (E) dated 10.07.2002, has delegated the powers vested under Section 5 of the Environment (Protection) Act, 1986 (29 of 1986) to the Chairman, Central Pollution Control Board, to issue directions to any industry or any local body or any other authority for violations of the standards and rules notified under the Environment (Protection) Rules, 1986 and amendment thereof; and

NOW, THEREFORE, based on all facts and observations, in exercise of powers vested under Section 5 of the Environment (Protection) Act, 1986, **M/s Rathi Dye Chem Pvt. Ltd., Plot no. 40, M.I.D.C. Dhatav, Roha, Dist. Raigad- 402116 Maharashtra** is hereby directed to close all manufacturing / production activities until it complies with the following directions:

1. The Unit shall get the CC&A amended through Maharashtra State Pollution Control Board to remove internal contradictions in CC&A w.r.t condition No. 4 and condition No. D of schedule 1 for treated effluent discharge standard.
2. The Unit shall operate the ETP properly so as to achieve the prescribed standard for consented parameter before disposal through CETP.
3. The Unit shall relocate the Online Continuous Effluent monitoring System at final Effluent Treatment Plant outlet and provide data connectivity to Central Pollution Control Board.
4. The Unit shall properly manage the solid waste. The hazardous waste shall be stored within a shed and immediately dispose to TSDF to prevent land pollution.
5. The Unit shall Store all the chemicals/intermediate chemicals (with proper permanent marking identification).
6. The Unit shall provide stack monitoring facility at alkali scrubber stacks.
7. The Unit shall immediately control all leakages in Effluent Treatment Plant & process area.

In case of failure to comply with the said directions necessary action as deemed fit under the provision of the Environment (Protection) Act 1986 will be taken.



(S.P. Singh Parihar)
Chairman



M/s Rathi Dye Chem Pvt. Ltd., Plot no. 40,
M.I.D.C. Dhatav, Roha, Dist. Raigad- 402116
Maharashtra

Copy to:

1. The Chairman
Maharashtra State Pollution Control Board
Kalpataru Point, 3rd & 4th floors
Sion Matunga Scheme, Road No. 8
Opp. Cine Planet, Sion Circle, Sion (E), Mumbai – 400 022
2. The Chairman
Maharashtra Electricity Board
Hongkong Bank Building,
M.G. Road, Fort, Mumbai-400001
: With request to disconnect industrial
electricity supply of the Unit, allowing
supply only for domestic & security
purposes.
3. The Advisor (CP Division)
Ministry of Environment, Forests and Climate Change
Prithvi Wing, 2nd Floor, Room No. 216, Indira
Paryavaran Bhawan Aliganj, Jqr Bagh Road, New Delhi – 110003
4. The Regional Director
Central Pollution Control Board
Parivesh Bhawan, Opp. VMC Ward Office No. 10
Subhanpura, Vadodra-390 023
- ✓ 5. The Incharge, IT, CPCB
6. IPC-VI, CPCB


(A. Sudhakar)
Member Secretary