

By Speed Post

F.No. B-23012/1/IPC-IV/

2886
May 19, 2017

To

M/s R.J. Fashion (S.S.Printers),
2/17 Angooribagh, Farrukhabad,
Uttar Pradesh

DIRECTION UNDER SECTION 5 OF THE ENVIRONMENT (PROTECTION) ACT, 1986

WHEREAS, the Central Government has notified the standards for discharge of environmental pollutants from various categories of industries under the Environment (Protection) Act, 1986 and the rules framed there under; and

WHEREAS, the Ministry of Environment, Forest and Climate Change, Govt. of India, vide notification S.O.157(E) of 27.02.1996 has delegated powers vested under Section 5 of the Environment (Protection) Act, 1986 (29 of 1986) to the Chairman, Central Pollution Control Board (CPCB), to issue direction to any industry, Municipal Corporation, Municipal Council, Cantonment Board to any local or other Authority for the violation of emission and effluent standards notified under the Environment (Protection) Rules, 1986 and other standards and norms; and

WHEREAS, M/s R.J. Fashion (S.S.Printers), 2/17 Angooribagh, Farrukhabad, Uttar Pradesh (hereinafter referred as 'the Unit') was inspected by the officials of CPCB on April 22, 2017 to verify compliance status of discharge standards and the inspection team made the following salient observations:

1. The Unit is involved in process of printing and dyeing the fabrics in batch process, having processing capacity of 2000m/day. The Unit has 28 nos. of printing tables, 6 nos. of dyeing machines and 1 nos. of drying machine.
2. The Unit has not installed electromagnetic flow meters at tube wells.
3. Unit does not maintain log book for freshwater consumption and wastewater discharge.
4. The Unit has not installed OCEMS (flow and web camera).
5. The Unit did not provided information about the consent of UPPCB.
6. During visit, Unit was found in operation however Unit's ETP was not in operation. ETP outlet effluent sample collected was found with BOD-180mg/l (standards - 30mg/l) and COD -- 261mg/l (standards - 50mg/l) which indicates non-compliance of prescribed norms.

It is evident from the above observations that the Unit is not complying with the prescribed effluent discharge standards and discharge of untreated effluent posing potential threat to the river Ganga;

Contd..2/-

NOW THEREFORE, in view of the above observations and in exercise of the powers delegated to the Chairman, CPCB under section 5 of the Environment (Protection) Act, 1986, the following directions are issued for compliance:

1. The Unit shall close down all the manufacturing operations with immediate effect.
2. The Unit shall report to CPCB regarding closure of manufacturing operations in compliance of the direction immediately on receipt of this direction.

In case of default in compliance with the above directions, CPCB will be constrained to initiate appropriate actions against the Unit, without giving any further notice, in accordance with provisions of the Environment (Protection) Act, 1986.

(S.P. SINGH PARIHAR)
CHAIRMAN

Copy to:

1. **The Member Secretary**
Uttar Pradesh Pollution Control Board
Building No. TC-12V, Vibhuti Khand,
Gomati Nagar, Lucknow : With a request to ensure
compliance of closure
directions, please.
2. **The Incharge, Zonal Office,**
Central Pollution Control Board,
PICUP Bhawan, Ground Floor
Vibhuti Khand, Gomati Nagar,
Lucknow-226010 : for information.
3. **The Advisor (CP Division)**
Ministry of Environment, Forests & Climate Change,
Indra Paryavaran Bhavan,
Jor Bagh Road, New Delhi - 110 003 : for information.
4. The Chief Engineer,
Dakshinanchal Vidyuth Vitran Nigam Ltd.,
Urja Bhavan, Agra - Delhi Bypass Road,
Sikandra, Agra, Uttar Pradesh : With a request to
disconnect electricity
supply
5. District Magistrate,
Distt-Farrukhabad, U.P. : With a request to ensure
closure direction.
6. ✓ I/c IT Division, CPCB, Delhi

(A.B. AKOLKAR)
MEMBER SECRETARY