

By Speed Post

F.NO. B-23012/1/IPC-III / 607

July 24, 2018

To,

M/s Derby Dairy Pvt. Ltd.  
V.P.O Jattal Road, Panipat -132103,  
Haryana

**DIRECTION UNDER SECTION 5 OF THE ENVIRONMENT (PROTECTION) ACT, 1986**

**WHEREAS**, the Central Government has notified the standards for discharge of environmental pollutants from various categories of industries under the Environment (Protection) Act, 1986 and the rules framed there under; and

**WHEREAS**, the Ministry of Environment, Forest, & Climate Change, Govt. of India, vide notification S.O.157(E) of 27.02.1996 has delegated powers vested under Section 5 of the Environment (Protection) Act, 1986 (29 of 1986) to the Chairman, Central Pollution Control Board (CPCB), to issue direction to any industry, Municipal Corporation, Municipal Council, Cantonment Board, to any local or other Authority for the violation of emission and effluent standards notified under the Environment (Protection) Rules, 1986 and other standards and norms; and

**WHEREAS**, M/s Derby Dairy Pvt., Ltd. V.P.O Jattal Road, Panipat, Haryana (*hereafter referred to as 'the Unit'*) is engaged in manufacturing of Poly-pack Milk, Lassi & Dahi; and

**WHEREAS**, the Unit was inspected by a team of officials from CPCB & HSPCB on 01.06.2018 and made following observations:

1. The Unit is engaged in the manufacturing of Poly-pack Milk, Lassi & Dahi with a total production of 12 KLD.
2. The Unit was found operational during the visit.
3. The Unit started its ETP immediately after the team entered the ETP area. No effluent discharge from the process section to ETP was seen during inspection.
4. The Unit was found bypassing the effluent outside the premises. The effluent analysis result of bypass sample showed pH-4.36 (*norms-6.5 - 8.5*); BOD-1124 mg/l (*norms-30 mg/l*); and TSS-726 mg/l (*norms-150 mg/l*) & TDS-1162 mg/l which indicate non-compliance of notified effluent discharge norms w.r.t pH, BOD & TSS parameter. The Unit requires to augment /upgrade its ETP.
5. The Unit representative informed that the treated effluent is used for land application.

**The Unit was found bypassing the untreated effluent outside the premises and also violating the prescribed effluent discharge standards. The ETP was operated only after the team arrived at ETP and no inflow to ETP was seen during the visit. Discharge of untreated effluent through bypass drain and inadequate & poor functioning of ETP is posing a grave injury to the surface water, groundwater quality and environment.**

**NOW, THEREFORE**, in view of the above and in exercise of the powers delegated to the Chairman, CPCB under section 5 of the Environment (Protection) Act, 1986, the **following directions are issued for compliance to M/s Derby Dairy Pvt. Ltd.** Panipat, Haryana:

1. The unit shall immediately close down all the manufacturing operations and shall report to CPCB regarding closure of manufacturing operations in compliance of the closure direction immediately on receipt of this direction.
2. The unit shall dismantle the bypass drain immediately.
3. The unit shall carry out adequacy assessment of ETP through reputed organisation/institute preferably IIT/NIT/NEERI & accordingly upgrade its ETP so as to meet the prescribed standard.
4. The Unit shall obtain Authorisation under Hazardous & other Waste Rules, 2016, from HSPCB.
5. The Unit shall install flow meter at the borewell, ETP inlet & outlet and maintain logbook for the same.
6. The Unit shall provide separate energy meter for ETP operation & shall maintain logbook as per the consent condition.
7. The Unit shall seek permission from CPCB before resumption of the manufacturing operation.

In case of default in compliance with the above directions, CPCB will be constrained to initiate appropriate actions against the Unit, without giving any further notice, in accordance with provisions of the Environment (Protection) Act, 1986.

(S.P. SINGH PARIHAR)  
CHAIRMAN

Copy to:

1. **The Member Secretary,**  
Haryana State Pollution Control Board,  
C-11, Sector-6. Panchkula-134109, Haryana : **To ensure compliance of closure direction pl.**
2. **The Regional Director,**  
Regional Directorate (Lucknow),  
Central Pollution Control Board,  
PICUP Bhawan, Ground Floor, Vibhuti  
Khand, Gomati Nagar, Lucknow-226010 : For information pl.
3. **The Advisor (CP Division)**  
Ministry of Environment, Forest & Climate Change,  
Indra Paryavaran Bhavan, Jor Bagh Road,  
New Delhi-110003 : For information pl.

Contd...3/-

4. **The District Magistrate,**  
District Magistrate Office,  
First Floor, Mini Secretariat, Panipat, : To ensure compliance of closure  
direction pl.
5. **The Managing Director,**  
Uttar Haryana Bijli Vitran Nigam Limited (UHBVNL)  
Vidyut Sadan, Plot No.: C16, Sector-6,  
Panchkula, Haryana, : **To dis-connect the electric  
power supply of the unit** in  
compliance of closure direction  
under section 5 of E(P)Act, 1986  
please.
6. ✓ The Division Head, IT Division, CPCB, Delhi : To upload the direction at CPCB  
website pl.
7. The Division Head, IPC-I Division, CPCB, Delhi : For information pl.
8. The Master file (Pulp & Paper), IPC-III Division, CPCB, : For record purpose  
Delhi

  
(PRASHANT GARGAVA)  
MEMBER SECRETARY