

By Speed Post

F.NO. B-23012/1/IPC-III /2018-19 738

August 09, 2018

To,

**M/S Jyoti Coats Yarn (P) Ltd;
T-9, Industrial Area, Panipat
Haryana**

DIRECTION UNDER SECTION 5 OF THE ENVIRONMENT (PROTECTION) ACT, 1986

WHEREAS, the Central Government has notified the standards for discharge of environmental pollutants from various categories of industries under the Environment (Protection) Act, 1986 and the rules framed there under; and

WHEREAS, it is obligatory on the part of industries to install and operate Effluent Treatment plant (ETP) to comply with the effluent discharge standards as notified under the Environment (Protection) Act, 1986 and the Rules framed there under and also to meet the consent conditions granted by State Pollution Control Board (SPCB)/ Pollution Control Committees (PCCs); and

WHEREAS, the Ministry of Environment, Forest, & Climate Change, Govt. of India, vide notification S.O.157(E) of 27.02.1996 has delegated powers vested under Section 5 of the Environment (Protection) Act, 1986 (29 of 1986) to the Chairman, Central Pollution Control Board (CPCB), to issue direction to any industry, Municipal Corporation, Municipal Council, Cantonment Board, to any local or other Authority for the violation of emission and effluent standards notified under the Environment (Protection) Rules, 1986 and other standards and norms; and

WHEREAS, M/S Jyoti Coats Yarn (P) Ltd; T-9, Industrial Area, Panipat (hereafter referred to as 'the Unit') is a Textile mill producing shoddy Yarn. The Unit was operational during the visit; and

WHEREAS, the Unit was inspected by a joint team of officials from CPCB & Haryana SPCB on 29.05.2018 and made following observations:

1. The Unit is a Textile mill producing shoddy Yarn using synthetic rags as raw material (500 kg/day).
2. The Unit was found operational during the visit.
3. The Unit is not having valid consent under Water and Air Act (s) & valid Authorization for hazardous waste disposal. The consent to operate under Water and Air Act is expired on 31.03.2016.
4. At the time of inspection, it was observed that the ETP of the unit was not in operation, however, it seems that the unit runs its dyeing system intermittently.

Contd...2/-

It is evident from the aforesaid observations that the unit is operating without valid consent to operate from Haryana SPCB and also not operating its ETP and such act of unit is posing a grave injury to the environment.

NOW, THEREFORE, in view of the above and in exercise of the powers delegated to the Chairman, CPCB under section 5 of the Environment (Protection) Act, 1986, the following directions are issued for compliance to **M/s Jyoti Coats Yarn (P) Ltd.**, Panipat, Haryana:

1. The Unit shall immediately close down all the manufacturing operations and shall report to CPCB regarding closure of manufacturing operations immediately on receipt of this closure direction.
2. The Unit shall seek permission from CPCB before resumption of the manufacturing operation.
3. The Unit shall obtain valid consent under Water & Air Act and Authorisation for Hazardous & other Waste rules, 2016.

In case of default in compliance with the above directions, CPCB will be constrained to initiate appropriate actions against the Unit, without giving any further notice, in accordance with provisions of the Environment (Protection) Act, 1986.


(S.P. SINGH PARIHAR)
CHAIRMAN

Copy to:

1. **The Member Secretary,**
Haryana State Pollution Control Board,
C-11, Sector-6. Panchkula-134109, Haryana : To ensure compliance of closure direction & provide your action taken report pl.
2. **The Regional Director,**
Regional Directorate (Lucknow),
Central Pollution Control Board,
PICUP Bhawan, Ground Floor, Vibhuti
Khand, Gomati Nagar, Lucknow-226010 : For information pl.
3. **The Advisor (CP Division)**
Ministry of Environment, Forest & Climate Change,
Indraparyavaran Bhavan, JorBagh Road,
New Delhi-110003 : For information pl.
4. **The District Magistrate,**
District Magistrate Office,
First Floor, Mini Secretariat, Panipat, : To ensure compliance of closure direction pl.
5. **The Managing Director,**
Uttar Haryana Bijli Vitran Nigam Limited
(UHBVNL), Vidyut Sadan, Plot No.: C16, Sector-6,
Panchkula, Haryana, : **To dis-connect the electric power supply of the unit** in compliance of closure direction issued under section 5 of E(P) Act, 1986 by CPCB & provide your action taken report pl.
6. The Division Head, IT Division, CPCB, Delhi : To upload the direction at CPCB website
7. The Division Head, IPC-I, Division, CPCB, : For information, pl
8. The Division Head, IPC-III, Division, CPCB, : For information, pl


(PRASHANT GARGAVA)
MEMBER SECRETARY