

SPEED POST

B-23012/1/IPC-III/ 757

20th August, 2018

To

M/s Swan K Motors (P) Ltd.,
Near Toll Plaza, GT Road, Panipat, Haryana

Sub.: Directions under Section 5 of the Environment (Protection) Act, 1986 -Show cause Notice

WHEREAS, the Central Government has notified the standards for discharge of environmental pollutants from various categories of industries under the Environment (Protection) Act, 1986 and the rules framed there under; and

WHEREAS, it is obligatory on the part of industries to install and operate Effluent Treatment plant (ETP) to comply with the effluent discharge standards as notified under the Environment (Protection) Act, 1986 and the Rules framed there under and also to meet the consent conditions granted by State Pollution Control Board (SPCB)/ Pollution Control Committees (PCCs); and

WHEREAS, the Ministry of Environment, Forest, & Climate Change, Govt. of India, vide notification S.O.157(E) of 27.02.1996 has delegated powers vested under Section 5 of the Environment (Protection) Act, 1986 (29 of 1986) to the Chairman, Central Pollution Control Board (CPCB), to issue direction to any industry, Municipal Corporation, Municipal Council, Cantonment Board, to any local or other Authority for the violation of emission and effluent standards notified under the Environment (Protection) Rules, 1986 and other standards and norms; and

WHEREAS, a team of officers from the Central Pollution Control Board (CPCB), Delhi inspected **M/s Swan K Motors (P) Ltd.**, Near Toll Plaza, GT Road, Panipat, Haryana (herein after referred as the Unit) on 14th May 2018 to assess the adequacy of the existing pollution control measures; and

WHEREAS, the inspecting team found the Unit operational and observed the following:

1. The Unit is engaged in the automobiles servicing & repairing unit. The capacity is 20cars/day.
2. ETP was found operational at the time of inspection.
3. The final ETP treated effluent sample analysis result showed pH-7.56 (*norms-5.5-8.5*); **BOD-36 mg/l (*norms-30 mg/l*)**; COD-74 mg/l, TSS-17 mg/l (*norms-100 mg/l*) & Oil & Grease-BDL (*norms-10mg/l*) which indicate non-compliance of notified discharge norms w.r.t BOD parameter.

NOW, THEREFORE, in view of the above observations & exercising powers delegated to the Chairman, Central Pollution Control Board under Section 5 of the Environment (Protection) Act, 1986, a notice is hereby served to the Unit to **Show cause why the unit should not be closed down for not complying with the prescribed effluent discharge standards notified under**

Environment (Protection) Rules, 1986 and until complying with the following directions:

1. The unit shall take up required corrective measure/augmentation of the ETP to ensure compliance of notified effluent standards for all the parameter including BOD.
2. The unit shall submit treated effluent analysis report from EPA recognised laboratory/HSPCB
3. The Unit shall provide separate energy meter for ETP operation & shall maintain logbook as per the consent condition. .

The compliance of above direction (notice) shall be submitted to this office within 30 days of the receipt of the directions. In case of failure to comply with the said directions necessary action as deemed fit under the provision of the Environment (Protection) Act, 1986 will be taken by CPCB, which includes criminal prosecution of the Unit Head and levying penalty towards environmental compensation.

(S. P. Singh Parihar)
Chairman

Copy to:

1. The Chairman

Haryana State Pollution Control Board
C-11, Sector - 6
Panchkula, Haryana

2. The Advisor (CP Division)

Ministry of Environment, Forests and Climate Change
Prithvi Wing, 2nd Floor, Room No. 216
Indira Paryavaran Bhawan
Aliganj, Jor Bagh Road
New Delhi - 110003

3. The Regional Director

CPCB, Regional Directorate (North)
Central Pollution Control Board
Ground & First Floor, PICUP Bhawan
Vibhuti Khand, Gomti Nagar
Lucknow - 226 020

✓ 4. I/c, IT, CPCB


(PRASHANT GARGAVA)
MEMBER SECRETARY