



SPEED POST

F. No. B-751 (481)/Textile/WQM-II/CPCB/2018-19

12078

16.10.2018
22

To

M/s Surya Udyog,
1008/2, Panni Nagar, Near Railway Line,
Bulandshahr-2030001
Uttar Pradesh

DIRECTION UNDER SECTION 5 OF THE ENVIRONMENT (PROTECTION) ACT, 1986

WHEREAS, the Textile, Dyeing & Bleaching industries have been identified as one the Grossly Polluting Industries (GPI) which have been discharging effluents directly or indirectly on land and into water, having potential threat to cause adverse effect on land and the ambient water quality; and

WHEREAS, there is a need to inculcate habit of self monitoring within the industries for complying with the prescribed standards and this can be achieved by the methods like installing online effluent and emission monitoring devices; and

WHEREAS, for strengthening the monitoring and compliance through self regulatory mechanism, online source emission and effluent monitoring systems need to be installed and operated by the industries on 'polluter pays principle'; and

WHEREAS, a direction under section 18 (1) (b) of the Water (Prevention & control of pollution) Act, 1974 was issued on February 05, 2014 to all 11 Ganga Basin State Pollution Control Board (SPCBs)/Pollution Control Committee (PCC) for installation of online effluent monitoring system w.r.t. pH, BOD, TSS, COD and flow parameters in Textile, Dyeing & Bleaching industries; and

WHEREAS, it was clarified that flow meter & web camera may be installed in case of units with Zero Liquid Discharge (ZLD) by March 31, 2015 vide guidelines uploaded on website of CPCB dated November 7, 2014; and

WHEREAS, M/s Surya Udyog, Panni Nagar, 1008/2, Near Railway Line, Bulandshahr-2030001, Uttar Pradesh (hereafter referred to as the 'Unit') is involved in the textile, dyeing and bleaching industry; and

WHEREAS, the unit was inspected on 30.03.2017 by the officials deputed by the PCRI, BHEL, Raipur, Haridwar and following observations were made:

1. The unit has not OCEMS installation. Thus has not OCEMS data connectivity with CPCB.
2. No detail was shared by company representative during PCRI visit. Which indicate the industry violated the section 10 (2) & 10 (3) under the Environmental (Protection) Rules, 1986.
3. Also no ETP installed in the unit as mentioned in recommendations / suggestion of inspection report.

AND WHEREAS, CPCB issued closure direction on 23.06.2017 under Section 5 of the Environment (Protection) Act, 1986 to the unit; and

WHEREAS, CPCB constituted a three-member committee vide office order dated 27.09.2017 having representative from CPCB, MoEF &CC and NMCG for examination and recommendation for revocation of the closure direction issued by CPCB; and

WHEREAS, three-member committee in its meeting held on 23.08.2018 examined the replies of the Unit dated 08.06.2018, 12.07.2017, 23.07.2018 and 09.08.2018 and recommended that (i) the Unit shall submit adequacy report of newly installed ETP by reputed government institute for further consideration; and

WHEREAS, CPCB vide letter dated 28.08.2018 asked unit to submit adequacy report of newly installed ETP by reputed government institute; and

WHEREAS, the unit vide letter dated 7.09.2018 submitted adequacy report which indicates that the ETP is adequate and installed OCEMS and provide its connectivity to CPCB server; and

WHEREAS, three-member committee in its meeting held on 08.10.2018 examined the reply of the Unit and recommended for revocation with direction that:

- (i) The Unit will submit performance audit report of ETP from Government expert institute annually to CPCB.
- (ii) The Unit will start its manufacturing operation after obtaining valid consent to operate from UPPCB.
- (iii) The Unit will submit logbook data of ETP for 06 months to CPCB.

AND WHEREAS, the Ministry of Environment & Forests, Government of India, vide Notifications No. S. O. 157 (E) of 27.02.1996 and S. O. 730 (E) dated 10.07.2002, has delegated the powers vested under Section 5 of the Environment (Protection) Act, 1986 (29 of 1986) to the Chairman, Central Pollution Control Board, to issue directions to any industry or any local body or any other authority for violations of the standards and rules notified under the Environment (Protection) Rules, 1986 and amendment thereof; and

NOW, THEREFORE, in exercise of powers vested under Section 5 of the Environment (Protection) Act, 1986, the following directions are being issued:

1. The Unit **M/s Surya Udyog, Panni Nagar, 1008/2, Near Railway Line, Bulandshahr-2030001, Uttar Pradesh** shall start its manufacturing operation after obtaining valid consent to operate from UPPCB.
2. The Unit shall report to CPCB regarding start of manufacturing operations.
3. The Unit shall submit performance audit report of ETP from Government expert institute annually to CPCB.
4. The Unit shall submit logbook data of ETP for 06 months to CPCB.

Failure to comply with above directions will attract action in accordance with the provision of the Environment (Protection) Act, 1986.


(S. P. SINGH PARIHAR)
CHAIRMAN

Copy to:

- | | | |
|--|---|--|
| 1. Chairperson ,
Uttar Pradesh Pollution Control Board
Building No. TC-12V, Vibhuti Khand,
Gomati Nagar, Lucknow | : | [For kind information] |
| 2. Joint Secretary (CP Division).
Ministry of Environment, Forests & Climate
Change, Indra Paryavaran Bhavan,
Jor Bagh Road, New Delhi - 110 003 | : | [For kind information] |
| 3. District Magistrate
Distt. Bulandshar, U.P. | : | [For the implementation and compliance of
the direction] |
| 4. Managing Director
Paschimanchal Vidyut Vitran Nigam Limited,
Urja Bhawan, Victoria Park, Meerut-250001, UP | : | [With a request to re-connect the electricity
supply to the Unit] |
| 5. Regional Director ,
Northern Regional Office,
Central Pollution Control Board,
PICUP Bhawan, Vibhuti Khand,
Gomati Nagar, Lucknow | : | [To ensure compliance of the directions] |
| 6. In-charge , IT Division, CPCB, Delhi | : | [For uploading the direction into CPCB
website] |
| 7. Master copy (Textile), WQM-II, CPCB, Delhi | : | [For record] |


(PRASHANT GARGAVA)
MEMBER SECRETARY