



cpqb

B-29016/04/IPC-I/

To

271
M/s Micas Organics Pvt. Ltd. (Unit- II)
Plot No. 3102/3101 & 3108, IV Phase,
GIDC, Vapi- 396195
Gujarat

By Registered A.D.

केन्द्रीय प्रदूषण नियंत्रण बोर्ड
CENTRAL POLLUTION CONTROL BOARD
(पर्यावरण एवं वन मंत्रालय, भारत सरकार)
(MINISTRY OF ENVIRONMENT AND FORESTS, GOVT. OF INDIA)
AUGUST 16, 2017

Sub: Directions under Section 5 of the Environment (Protection) Act, 1986 – reg.

WHEREAS, Dye & Dye Intermediate units are identified as one of the 17 categories of highly polluting industries which have been discharging environmental pollutants directly or indirectly into the ambient air and water, having potential threat to cause adverse effect on the water and air quality; and

WHEREAS, Central Pollution Control Board, Regional Directorate, Vadodara inspected M/s Micas Organics Pvt. Ltd. (Unit- II), Plot No. 3102/3101 & 3108, IV Phase, GIDC, Vapi, Gujarat on April 11th, 2017 and observed that the unit is disposing the treated effluent to CETP. The treated effluent was exceeding the CETP prescribed standard limit w.r.t. TDS (8513 mg/l > 2100 mg/l); and

WHEREAS, on the basis of above stated observations, Central Pollution Control Board on April 11, 2017 issued show cause notice under Section 5 of Environment (Protection) Act 1986, to the unit that why the unit be not directed to close all manufacturing / production activity until it complies with the directions as specified therein; and

WHEREAS, the unit replied to the aforesaid show cause notice on April 28, 2017 and provided point wise compliance status of issued notice; and

WHEREAS, to verify the compliance status of directions of aforesaid show cause notice, Central Pollution Control Board Regional Directorate, Vadodara re inspected the unit on July 13, 2017; and

WHEREAS, during inspection on July 13, 2017 it was observed that the unit is discharging the treated effluent to CETP. The treated effluent is exceeding the CETP inlet norms w.r.t. TDS (5114 mg/l > 2100 mg/l), and CL₋ (2899 mg/l > 600 mg/l); and

WHEREAS, it was observed that the unit has not provided connectivity of flow meter to CPCB server; and

WHEREAS, the proper monitoring facility has not provided by the unit for incinerator & no designated storage for hazardous waste was provided by the unit; and

WHEREAS, the house keeping of the unit was not found satisfactory near sludge handling area & run off from stored sludge was found spread in the area; and

WHEREAS, the Ministry of Environment & Forests, Government of India, vide Notifications No. S. O. 157 (E) of 27.02.1996 and S. O. 730 (E) dated 10.07.2002, has delegated the powers vested under Section 5 of the Environment (Protection) Act, 1986 (29 of 1986) to the Chairman, Central Pollution Control Board, to issue directions to any industry or any local body or any

'परिवेश भवन' पूर्वी अर्जुन नगर, दिल्ली-110032

'Parivesh Bhawan', East Arjun Nagar, Delhi - 110032

Page 1 of 2

दूरभाष/Tel. : 43102030, फ़ैक्स/Fax : 22305793, 22307078, 22307079, 22301932, 22304948


ई-मेल/e-mail : cpcb@nic.in वेबसाइट/Website : www.cpcb.nic.in


other authority for violations of the standards and rules notified under the Environment (Protection) Rules, 1986 and amendment thereof.

NOW, THEREFORE, based on all facts and observations, in exercise of powers vested under Section 5 of the Environment (Protection) Act, 1986 **M/s Micas Organics Pvt. Ltd. (Unit- II), Plot No. 3102/3101 & 3108, IV Phase, GIDC, Vapi, Gujarat** is hereby directed to close all manufacturing / production activities until it complies with the following directions:

1. The Unit shall Upgrade/operate ETP so as to meet the GPCB discharge standards (CETP inlet norms) as per CCA.
2. The unit provide connectivity of the flow meter to the CPCB server.
3. The unit shall provide proper monitoring facility for the monitoring of the stack emission of incinerator
4. The Unit shall improve housekeeping near sludge storage area.
5. The Unit shall provide designated storage for hazardous waste as per Hazardous Waste (Management, Handling & Transboundary Movement) Rules.

In case of failure to comply with the said directions necessary action as deemed fit under the provision of the Environment (Protection) Act 1986 will be taken.


(S.P. Singh Parihar)
Chairman

 17/08/2017

Copy to:

1. The Chairman
Gujarat State Pollution Control Board
Sector 10-A, Gandhi Nagar – 382 043

2. The Chairman
Dakshin Gujarat Vij Company Limited
Valsad circle, GJ SH 701 Valsad,
Kapadia Chal
Gujarat 396001

: With request to disconnect industrial electricity supply of the Unit, allowing supply only for domestic & security purposes.

3. The Advisor (CP Division)
Ministry of Environment, Forests and Climate Change
Prithvi Wing, 2nd Floor, Room No. 216, Indira
Paryavaran Bhawan Aliganj,
Jor Bagh Road, New Delhi – 110003

4. The Regional Director
Central Pollution Control Board
Parivesh Bhawan, Opp. VMC Ward Office No. 10
Subhanpura, Vadodra-390 023

✓ 5. The Incharge, IT, CPCB

6. IPC-VI, CPCB


(A.B. Akolkar)
Member Secretary