



केन्द्रीय प्रदूषण नियंत्रण बोर्ड  
CENTRAL POLLUTION CONTROL BOARD  
पर्यावरण, वन एवं जलवायु परिवर्तन मंत्रालय भारत सरकार  
MINISTRY OF ENVIRONMENT, FOREST & CLIMATE CHANGE GOVT. OF INDIA

**Speed Post**

August 01, 2017

B-33014/7/2017-18/IPC-II/ 8801

To,

**The Unit Head**

M/s Shree Keshav Cements & Infra Ltd.  
Plant I, Sy. No. 346, Kaladagi,  
Bagalkot - 587 204  
Karnataka

**Sub: Show cause Notice under Section 5 of the Environment (Protection) Act, 1986**

WHEREAS, the Central Government has notified standards for discharge of environmental pollutants from various categories of industries under the Environment (Protection) Act, 1986 and the rules framed there under; and

WHEREAS, Ministry of Environment & Forests, Govt. of India, vide notification S.O. 157 (E) of 27.02.1996 has delegated powers vested under section 5 of the Environment (Protection) Act, 1986 (29 of 1986) to the Chairman, Central Pollution Control Board (CPCB), to issue directions to any industry, municipal corporation, municipal council, cantonment board, to any local or other Authority for violation of emission and effluent standards notified under the Environment (Protection) Rules, 1986 and other standards and norms; and

WHEREAS, M/s Shree Keshav Cements & Infra Ltd, Kaladagi, Bagalkot, Karnataka was inspected by a team of Scientists from CPCB, RD-Bengaluru on 08.06.2017 to assess the adequacy of the pollution control measures as well as compliance of the environmental norms and following observations were made :

1. At the time of the inspection , the kiln and cement mills were not in operation. As a result, monitoring could not be conducted.
2. The unit has not provided proper storage facility for raw material such as pet coke and black cotton.
3. Clinkers are transported through conveyor belts which are not covered. Such open operation & transfer of material lead to spillage and fugitive emission
4. House keeping in the process area is poor and all the roads inside the unit need to be paved/concreted to avoid fugitive emissions.
5. The unit needs to provide proper storm water drainage system to channelize rain water and avoid flooding of process area.

'परिवेश भवन' पूर्वी अर्जुन नगर, दिल्ली-110032

Parivesh Bhawan, East Arjun Nagar, Delhi-110032


दूरभाष/Tel : 43102030, 22305792, वेबसाइट/Website : www.cpcb.nic.in

Now, THEREFORE, in view of the above observations and exercising the powers delegated to the Chairman, Central Pollution Control Board under section 5 of the Environment (Protection) Act, 1986, notice is being served herewith to M/s Shree Keshav Cements & Infra Ltd, Kaladagi, Bagalkot, Karnataka to show cause as to why the action under environmental regulations should not be taken for the shortcomings observed during the inspection as referred above.

M/s Shree Keshav Cements & Infra Ltd, Kaladagi, Bagalkot, Karnataka is further directed for the following :

1. The industry shall immediately initiate the remedial measures for rectification of shortcomings as mentioned above.
2. The industry shall intimate CPCB Regional Directorate, Bengaluru about its resuming of the operation so that inspection & monitoring be conducted. During inspection & monitoring , the industry shall operate at optimum production capacity so that efficacy of pollution control system can be assessed.
3. The industry shall submit reply & action taken report within 15 days from the date of issue of this Notice.

In the absence of the compliance report, it will be presumed that the industry has nothing to say in this regard and CPCB will be constrained to take action as deemed fit under the provision of Environment (Protection) Act, 1986.

  
(S.P. S. Parihar)  
Chairman


03/08/2017





**Copy for information to:**

- 1 The Chairman  
Karnataka State Pollution Control Board  
'Parisara Bhawan' 4th & 5th Floor  
49, Church Street,  
Bangalore-560 001  
For information &  
ensuring compliance  
please.
- 2 The Regional Director  
Central Pollution Control Board  
1st & 2nd Floors, Nisarga Bhawan  
A- Block, Thimmaiah Main Road  
7th D Cross, Shivanagar  
Opposite Pushpanjali Theatre  
Bengaluru 560 010  
Fresh inspection &  
monitoring of the  
industry be conducted.
- 3 The Additional Secretary (AKM, CP Division)  
Ministry of Environment, Forests and  
Climate Change  
Prithvi Wing, 2nd Floor, Room No. 216  
Indira Paryavaran Bhawan  
Aliganj, JorBagh Road, New Delhi - 110003  
For information please.
- 4 The Divisional Head, IT, CPCB, Delhi
- 5 The Divisional Head (PKG), IPC-VI, CPCB

  
**(A. B. Akolkar)**  
**Member Secretary**

ಇಲಾಖೆ ಸಹಾಯಕ ನಿರ್ದೇಶಕರು  
ಪಿ.ಐ.ಡಿ. ಉಪನಿರ್ದೇಶಕರು  
ಪಿ.ಐ.ಡಿ. ನಿರ್ದೇಶಕರು  
ಪಿ.ಐ.ಡಿ. ನಿರ್ದೇಶಕರು  
13/11/2

