



By Speed Post

File No: CP-12/1/2023-IPC-III-HO-CPCB-HO March 27, 2023

To,

M/s Sunder Food Product,
Plot No' 1, 2, 3 & 4, MPAKVN,
Growth centre, Borgaon, Teh. Sausar,
Dist. Chhindwara- 480106 (M.P)

**SHOW CAUSE NOTICE UNDER SECTION 5 OF THE ENVIRONMENT
(PROTECTION) ACT, 1986**

WHEREAS, the Central Government has notified the standards for discharge of environmental pollutants from various categories of industries under the Environment (Protection) Act, 1986 and the rules framed there under; and

WHEREAS, CPCB team visited Boregaon Village, Sausar, Dist- Chindwara, Madhya Pradesh on 16.12.2022 to verify a complaint regarding discharge of untreated effluent into storm water drain of Kanhan River; and

WHEREAS, during the inspection CPCB team found that the food processing plant, M/s Sunder Food Product, Plot No. 1, 2, 3 & 4, MPAKVN, growth center, Borgaon, Sausar, Dist. Chhindwara, M.P (*hereinafter referred as 'the Unit'*) was observed to be discharging effluent through bypass pipeline into storm water drain; and

WHEREAS, the Unit was visited by the CPCB team on 16.12.2022 and made the following major observations:

1. The Unit is food processing plant (Bakery and Confectionery) and has obtained consent to operate under the Water (Prevention and Control of Pollution) Act, 1974 & Air (Prevention and Control of Pollution) Act, 1981 from MPPCB which is valid up to 30.09.2023. However, the Unit has not obtained Authorization under Hazardous & Other Waste Rules, 2016 from MPPCB.
2. The Unit has total 10 KLD generation of Process effluent and 02 KLD generation of domestic wastewater as per the CTO. The Unit has Effluent Treatment Plant of 50 KLD capacity including tertiary treatment facility (i.e. Pressure Sand Filter and Activated Carbon Filter).
3. As per the MPPCB Consent condition, industry is required to practice zero discharge and in no case treated effluent should be discharged outside the Unit premises.
4. During the inspection, it was found that industry has installed 01 channel through its premises towards the storm water drain

Handwritten signature/initials

'परिवेश भवन' पूर्वी अर्जुन नगर, दिल्ली-110032

Parivesh Bhawan, East Arjun Nagar, Delhi-110032

दूरभाष/Tel : 43102030, 22305792, वेबसाइट/Website : www.cpcb.nic.in

which is clear violation of consent condition of MPPCB. During the inspection, industrial effluent with 0.016 m³/sec flow rate was found to be discharged through the channel. During inspection, the samples were collected from the bypass channel discharging into storm water drain and the lab analysis result showed pH-6.58 (against 5.5 -9.0); BOD-16 mg/l (against 30 mg/l), COD-78 mg/l (against 250 mg/l), TSS-76 mg/l (against 100 mg/l), O&G - below detection limit; TDS-246 (against 2100 mg/l); and Chloride-70 mg/l (against 1000 mg/l).

5. During the visit, the team also collected effluent sample from the Upstream of Storm water Drain (Boregaon, Teh. Suasar, MP and Downstream of Storm Water Drain (Boregaon, Teh. Suasar, MP) and lab analysis results are tabulated below:

Sample location	pH	BOD	COD	SS	Chloride	O&G	TDS	NH3
Upstream of Storm Water Drain	7.09	05	11	08	74	1.4	457	3.19
Downstream of Storm Water Drain	6.99	22	77	35	210	2.8	702	19

6. The industry has monkey ladder facility with the stack attached to the boiler. The source emission monitoring at Stack could not be performed due to absence of easy ladder, platform and porthole in Stack as per CPCB guideline.
7. As per the MPPCB consent, Unit has to operate sewage treatment system /STP for its sewage water treatment. The same was not available within the plant.
8. The Unit requires to provide flow-meter at the inlet and outlet of the ETP.
9. There was no display board on the main gate of industry showing hazardous waste/other waste status.
10. The Unit does not have proper length of exhaust pipe attached to the DG Set inside the plant.

It is evident from the above that the Unit has provided a bypass channel towards storm water drain & found to be discharging the effluent into the storm water drain which is a violation of conditions of consent to operate (CTO) issued by State Board. As per the CTO, the Unit has to practice zero discharge condition and in no case treated effluent be discharged outside the Unit premises. The Unit has not obtained Authorization under Hazardous & Other Waste Rules, 2016. The Unit has also not provided proper stack monitoring facility as per the CPCB guidelines.

WHEREAS, the Ministry of Environment, Forest, & Climate Change, Govt. of India, vide notification S.O.157(E) of 27.02.1996 has delegated powers vested under Section 5 of the Environment (Protection) Act, 1986 (29 of 1986) to the Chairman, Central Pollution Control Board (CPCB), to issue direction to any industry, Municipal Corporation, Municipal Council, Cantonment Board, to any local or other Authority for the violation of emission and effluent standards notified under the Environment (Protection) Rules, 1986 and amendment thereof; and

NOW, THEREFORE, in view of the above observations and in exercise of the powers delegated to the Chairman, CPCB under section 5 of the Environment (Protection) Act, 1986, notice is hereby served to **M/s Sunder Food Product**, Plot No. 1, 2, 3 & 4, MPAKVN, Growth Centre, Borgaon, Teh. Sausar, Dist. Chhindwara (M.P) to Show Cause as to why operation of the Unit should not be closed down.

You are hereby given an opportunity to file your objections (if any) to the above proposed notice within 15 days from the receipt of this notice, failing which it will be presumed that you have nothing to say and appropriate action, in accordance with the provisions of the Environment (Protection) Act, 1986, will be taken against the Unit without giving any further notice.

M.K.
27/5/23
(TANMAY KUMAR)
CHAIRMAN

Copy to:

1. **The Member Secretary**
Madhya Pradesh Pollution Control Board
E-5, Arera Colony, Paryavaran Parisar,
Bhopal - 462 016 :For information pl.
2. **The Regional Director,**
REGIONAL DIRECTORATE - BHOPAL
Central Pollution Control Board,
Parivesh Bhawan, Paryavaran Parisar E-5, Arera Colony,
Bhopal-462016 : For information, pl
3. **The Director (CP Division)**
Ministry of Environment, Forest & Climate Change,
Indra Paryavaran Bhavan, JorBagh Road,
New Delhi-110003 : For information, pl
4. **The Division Head, IT Division, CPCB, Delhi**
:To upload the direction at
CPCB website

Prashant
(PRASHANT GARGAVA)
MEMBER SECRETARY

Show Cause Notice u/s 5 of E (P) Act, 1986 to M/s Sunder Food Product, Dist. Chhindwara- 480106 (M.P)