



केन्द्रीय प्रदूषण नियंत्रण बोर्ड
CENTRAL POLLUTION CONTROL BOARD
पर्यावरण, वन एवं जलवायु परिवर्तन मंत्रालय भारत सरकार
MINISTRY OF ENVIRONMENT, FOREST & CLIMATE CHANGE GOVT. OF INDIA

Speed Post

B-33014/7/2017-18/IPC-II 13232

October 30, 2017

To

The Unit Head

M/s Birla Corporation Ltd.
Satna Cement Works
P.O. Birla Vikas
Distt: Satna (M.P.)
485005

Sub: Show cause Notice under Section 5 of the Environment (Protection) Act, 1986

WHEREAS, the Central Government has notified standards for discharge of environmental pollutants from various categories of industries under the Environment (Protection) Act, 1986 and the rules framed there under; and

WHEREAS, Ministry of Environment & Forests, Govt. of India, vide notification S.O. 157 (E) of 27.02.1996 has delegated powers vested under section 5 of the Environment (Protection) Act, 1986 (29 of 1986) to the Chairman, Central Pollution Control Board (CPCB), to issue directions to any industry, municipal corporation, municipal council, cantonment board, to any local or other Authority for violation of emission and effluent standards notified under the Environment (Protection) Rules, 1986 and other standards and norms; and

WHEREAS, **M/s Birla Corporation Ltd, Satna Cement Works, Distt: Satna (M.P.)** was inspected by a team of Scientists from CPCB, RD-Bhopal during June 28-29, 2017 to assess the adequacy of the pollution control measures adopted by the unit as well as compliance of the environmental norms and following observations/recommendations are made :

1. The unit needs to improve house keeping at gypsum storage area, Laterite storage area, coal handling area, lime stone ground hopper area.
2. The unit should repair leakages from the plant at clinker silo and cement silo.
3. The display of OCEMS for NO_x parameter in kiln stacks were displaying Nitric Oxide (NO) values, therefore, the unit should take corrective measures to convert the NO to NO_x in mg/Nm³ at the system.
4. The domestic effluent from dairy should be collected and treated in the STP and not by passed to low lying area.
5. The unit should take proper preventive measure to control the leakages of dust from clinker silo & cement silo.
6. Water sprinkler system should be installed at road side, product loading and unloading areas for controlling of fugitive emissions.
7. The industry should stop storing of used oil and grease in open area, the maximum permitted storage limit of 10 kl should not be exceeded and the unit should comply the hazardous waste storage norms.

M/s Birla Corporation Ltd, Satna Cement Works, Distt: Satna (M.P.)

'परिवेश भवन' पूर्वी अर्जुन नगर, दिल्ली-110032
Parivesh Bhawan, East Arjun Nagar, Delhi-110032

दूरभाष/Tel : 43102030 22305792 वेबसाइट/Website : www.cpcb.nic.in

Now, THEREFORE, in view of the above observations / recommendations and exercising the powers delegated to the Chairman, Central Pollution Control Board under section 5 of the Environment (Protection) Act, 1986, **M/s Birla Corporation Ltd, Satna Cement Works, Distt: Satna (M.P.)** is hereby directed to rectify the above shortcomings within 2 months.

The industry shall submit reply & action taken report within 15 days from the date of issue of this Notice. In the absence of the compliance report, it will be presumed that the industry has nothing to say in this regard and CPCB will be constrained to take action as deemed fit including prosecution under the provision of the Environment (Protection) Act, 1986.

hvg
11/11/17
(S.P. S. Parihar)
Chairman
hvg *11/11/17*

Copy to:

1	The Chairman Madhya Pradesh Pollution Control Board Parayavaran Parisar, E-5, Arera Colony Bhopal - 462 016, Madhya Pradesh	For information & ensuring compliance please.
2	The Regional Director Central Pollution Control Board 4th Floor, SahkarBhawan North T.T. Nagar Bhopal - 462 003	For information please.
3	The Additional Secretary (CP Division) Ministry of Environment, Forests and Climate Change Prithvi Wing, 2nd Floor, Room No. 216 Indira ParyavaranBhawan Aliganj, JorBagh Road, New Delhi - 110003	
✓ 4	The Divisional Head, IT, CPCB, Delhi	
5	The Divisional Head (PKG), IPC-VI, CPCB	

23/11/17
(A. Sudhakar)
Member Secretary

hvg
11/11/17