

**SPEED POST**

F. No. B-751(637)/Textile/WQM-II/CPCB/2017-18 6<sup>th</sup> November, 2017

To

M/s Shiva Knit Wear,  
B-15, 16, Site-4, Panki,  
Kanpur

**Directions under Section 5 of the Environment (Protection) Act, 1986 –reg.**

**WHEREAS**, the Textile dyeing and bleaching industries are identified as one of the Grossly Polluting industries (GPIs) which have been discharging environmental pollutants directly or indirectly into the ambient air and water, having potential threat to cause adverse effect on the water and air quality; and

**WHEREAS**, the Central Government has notified the general discharge standards of environmental pollutants from various categories of industries under the Environment (Protection) Act, 1986 and the rules framed there under;

**WHEREAS**, the Ministry of Environment & Forests, Government of India, vide Notifications No.S.O.157(E) of 27.02.1996 and S.O.730(E) dated 10.07.2002, has delegated the powers vested under Section 5 of the Environment (Protection) Act, 1986 (29 of 1986) to the Chairman, Central Pollution Control Board, to issue directions to any industry or any local body or any other authority for violations of the standards and rules notified under the Environment (Protection) Rules, 1986 and amendment thereof; and

**WHEREAS**, M/s Shiva Knit Wear, B-15, 16 Site-4, Panki, Kanpur (here in after referred as 'the unit') is a textile processing unit;

**WHEREAS**, the unit was issued closure directions dated May 15<sup>th</sup>, 2017 for non-installation of OCEMS; and

**WHEREAS**, inspection of the unit was conducted on April 7<sup>th</sup>, 2017 & May 10<sup>th</sup>, 2017 to check the status of compliance of prescribed norms and was issued closure directions dated 27<sup>th</sup> June, 2017 for non-compliance of stipulated norms;

**WHEREAS**, the unit was re-inspected on June 20<sup>th</sup>, 2017 to verify the compliance status and the following observations were made:

- 1) The unit was found operational at the time of the inspection which is in violation of CPCB closure directions dated 15/05/2017 ^27/06/2017 issued under Section 5 of E(P) Act, 1986.
- 2) The ETP was under construction, and the unit was discharging untreated effluent from equalization tank through open channel by closing the ETP inlet line.
- 3) The unit does not have a hazardous waste authorization.
- 4) No water meter was installed at the water extraction points and the EMF meter installed at the outlet was found non-operational.
- 5) The analysis results of the effluent collected from the final outlet of the unit showed pH of 9.27 (against the notified standards of 6.5-8.5), TSS of 137 mg/l (against notified standards of 100 mg/l), BOD of 26.6 mg/l (against notified standards of 30 mg/l), COD of 235

**Contd..**

mg/l (against notified standards of 250 mg/l) which indicate non-compliance with the prescribed norms w.r.t. pH and TSS.

**AND WHEREAS**, the unit was found in operation on 20/06/2017 which is in violation of CPCB closure directions dated 15/05/2017 & 27/06/2017 issued under Section 5 of Environment (Protection) Act, 1986, for which separate legal action shall be initiated.

It is evident from the above that the unit is discharging untreated effluent posing potential threat to river water quality.

**NOW, THEREFORE**, in view of the above and in exercise of the powers delegated to the Chairman, Central Pollution Control Board under Section 5 of the Environment (Protection) Act, 1986, the unit, **M/s Shiva Knit Wear, B-15, 16 Site-4, Panki, Kanpur** is hereby directed to close down all manufacturing operations till the compliance of the following directions.

1. The unit shall remain closed and not operate/start manufacturing without permission of CPCB.
2. The unit shall ensure proper operation and maintenance of its ETP.
3. The unit shall comply with CPCB directions dated 15/05/2017 & 27/06/2017 issued under Section 5 of Environment (Protection) Act, 1986.
4. The unit shall seek permission from CPCB before resumption of operation.

In case of default in compliance with the above directions CPCB may initiate appropriate actions against the unit, without giving any further notice, in accordance with provisions of Environment (Protection) Act, 1986.

(S P SINGH PARIHAR)  
Chairman

Copy to:

1. The Member Secretary,  
Uttar Pradesh Pollution Control  
Board,  
Building No. TC-12V, Vibhuti  
Khand,  
Gomati Nagar, Lucknow.

2. The Regional Directorate, Central  
Pollution Control Board, Lucknow,  
PICUP Bhawan, Ground Floor,  
Vibhuti Khand, Gomati Nagar,  
Lucknow-226010

For kind information

3. The Advisor (CP Division) Ministry  
of Environment, Forests & Climate  
Change,  
Indra Paryavaran Bhavan,  
Jor Bagh Road, New Delhi - 110  
003

4. The Incharge, IT Division, CPCB

For uploading on CPCB's website

5. Master File WQM-II, CPCB

  
(A SUDHAKAR)  
MEMBER SECRETARY