



केन्द्रीय प्रदूषण नियंत्रण बोर्ड  
CENTRAL POLLUTION CONTROL BOARD  
पर्यावरण, वन एवं जलवायु परिवर्तन मंत्रालय भारत सरकार  
MINISTRY OF ENVIRONMENT, FOREST & CLIMATE CHANGE GOVT. OF INDIA

SPEED POST

B-Tannery/IPC-IV/2018-19/ 599

April 13, 2018

To

M/s Indian Leathers,  
18<sup>th</sup> km mile stone, G.T. Road,  
Nathupur, Sonapat,  
Haryana

**Sub.: Directions under Section 5 of the Environment (Protection) Act, 1986 regarding non-compliance of notified norms.**

WHEREAS, the tanneries are identified as one of the 17 categories of highly polluting industries which have been discharging environmental pollutants directly or indirectly into the ambient air and water, having potential threat to cause adverse effect on the water and air quality; and

WHEREAS, the Central Government has notified the standards for discharge of environmental pollutants from various categories of industries under the Environment (Protection) Act, 1986 and the rules framed there under; and

WHEREAS, there is need to inculcate habit of self-monitoring within the industries for complying with the prescribed standards and this can be achieved by the methods like installing online effluent and emission monitoring devices; and

WHEREAS, for strengthening the monitoring and compliance through self-regulatory mechanism, online source emission and effluent monitoring systems need to be installed and operated by the industries on 'polluter pays principle'; and

WHEREAS, a direction under section 18 (1) (b) of the Water (Prevention & Control of Pollution) Act, 1974 and the Air (Prevention & Control of Pollution) Act, 1981 was issued on February 05, 2014 to all the State Pollution Control Boards (SPCBs)/ Pollution Control Committees (PCCs) for installation of online effluent monitoring system w.r.t. pH, BOD, COD, TSS, and Flow parameters in Tanneries; and

WHEREAS, considering the requests/ representations received from industries/ industrial associations/ SPCBs / PCCs, an extension of time up to June 30, 2015 for installation of online monitoring systems was granted vide direction dated March 02, 2015 under section 18 (1) (b) of the Water (Prevention & Control of Pollution) Act, 1974 and the Air (Prevention & Control of Pollution) Act, 1981; and

WHEREAS, a letter vide dated May 29, 2015 was issued by the Chairman CPCB to all the SPCBs/ PCCs informing that no further extension of time will be given after June 30, 2015 and withdrawal of consent to operate along with forfeiture of bank guarantee of non-complying units; and

'परिवेश भवन' पूर्वी अर्जुन नगर, दिल्ली-110032  
Parivesh Bhawan, East Arjun Nagar, Delhi-110032

दूरभाष/Tel : 43102030, 22305792, वेबसाइट/Website : www.cpcb.nic.in

WHEREAS, concerned SPCB/ PCC issued directions under section 33A of the Water (Prevention & Control of Pollution) Act, 1974 and section 31A of the Air (Prevention & Control of Pollution) Act, 1981 to install the online monitoring system by June 30, 2015 and to submit bank guarantee of 100% of the cost of online emission & effluent monitoring system; and

WHEREAS, the Ministry of Environment & Forests, Government of India, vide Notifications No. S. O. 157 (E) of 27.02.1996 and S. O. 730 (E) dated 10.07.2002, has delegated the powers vested under Section 5 of the Environment (Protection) Act, 1986 (29 of 1986) to the Chairman, Central Pollution Control Board, to issue directions to any industry or any local body or any other authority for violations of the standards and rules notified under the Environment (Protection) Rules, 1986 and amendment thereof; and


WHEREAS, your industry, M/s Indian Leathers, 18<sup>th</sup> km mile stone, G.T. Road, Nathupur, Sonapat, Haryana was inspected by a team of Scientists from Regional Directorate - North, CPCB, Lucknow on 16.3.2018 based on exceedance of OCEMS alerts and made the following observations requiring attention of Regulating Authorities:

1. The Unit is engaged in processing of raw hide to finished leather with installed capacity of 500 Pcs/day. During inspection, Unit was not in operation and no industrial activity was observed however, manual wetting of tanned leather was carried out for trading.
2. The Unit's representative reported that Unit is closed since 12.10.2017.
3. The unit is having ETP based on biological treatment system clubbed with Dual Media filter and Carbon filter. During inspection, ETP was not in operation, however, effluent generated from manual wetting was collected at collection tank
4. Samples collected from collection tank were analysed and observed that it is not meeting with the prescribed standards in respect of TSS - 277mg/l (standard - 100 mg/l), BOD - 478mg/l (standard - 30 mg/l), and Total Chromium - 43.2 (standard - 2mg/l).
5. During inspection, no discharge of effluent was observed however, Unit reported that treated effluent from ETP is discharged into adjacent canal which meets river Yamuna.
6. The Unit has installed OCEMS at the ETP outlet and it was found offline.
7. The Unit has installed Chrome Recovery Plant (CRP) for treatment of chrome bearing effluent, however, it was found in defunct condition
8. The Unit has not installed separate energy meters for operation of ETP & CRP.
9. Separate drainage system for segregating chrome bearing effluent was not observed.
10. Hazardous Waste Management was found in poor condition. ETP sludge is disposed off in open land near ETP without sending to TSDF site.
11. Height of the DG set stack installed by the unit is not as per norms and it is not equipped with acoustic enclosures.
12. The Unit has obtained consents under the Water (P&C of Pollution) Act, 1974 and the Air ( P&C of Pollution) Act, 1981 which are valid upto 30.9.2019 and also obtained Authorization under the Hazardous & other Wastes (M & TBM) Rules, 2016 which is valid upto 30.9.2019.

NOW, THEREFORE, in exercise of powers vested delegated to the Chairman, CPCB under Section 5 of the Environment (Protection) Act, 1986, M/s Indian Leathers, 18<sup>th</sup> km mile stone, G.T. Road, Nathupur, Sonapat, Haryana is hereby directed to close down all of its manufacturing activities with immediate effect. The unit is further directed for the following :

1. The unit shall submit a time-targeted action plan within 15 days for rectification of the short comings as described above.
2. The unit shall not re-start its manufacturing activities without written permission from CPCB.


The unit shall ensure compliance of these directions failing which action shall be taken against the Unit, without giving any further opportunity, in accordance with provisions of the National Green Tribunal Act, 2010.

  
18/4/18  
[S. P. S. Parihar]  
Chairman

  
\_\_\_\_\_

Copy for kind information & Compliance to :

1.	The Chairman, Haryana State Pollution Control Board, C-11, Sector-6. Panchkula-134109, Haryana	With a request to ensure compliance of the directions please.
2.	The Chairman cum Managing Director Uttar Haryana Bijli Vitran Nigam Limited (UHBVNL) Vidyut Sadan, Plot No.: C16, Sector-6, Panchkula, Haryana	The electricity supply to the industry be disconnected with immediate effect.
3.	The District Magistrate - Sonipat SH 11, Ashok Vihar, Sonipat, Haryana 131001	With a request to ensure compliance of the directions please.
4.	The Joint Secretary (CP Division), Ministry of Environment, Forest & C.C., Prithvi Block, Indira Paryavaran Bhawan, Jorbagh Road, New Delhi - 110003.	For information and necessary action please
5.	The Regional Director, Regional Directorate- North, Central Pollution Control Board, PICUP Bhawan, Gound Floor, Vibhuti Khand, Gomti Nagar, Lucknow - 226010.	
6. ✓	The Divisional Head , IT Division, CPCB-HO., Delhi	
7.	The Divisional Head , IPC-VI Division, CPCB-HO., Delhi	

  
[A. Sudhakar]  
Member Secretary

