



By Speed Post

F.No. B-23012/1/PCI-III/ 14830

December 20, 2017

To

M/s Frigerio Conserva Allana Pvt. Ltd.,
14/1, Vill. Talaspur,
Mathura Bypass Road,
Aligarh, Uttar Pradesh

SUB: REVOCATION OF SHOW-CAUSE NOTICE ISSUED UNDER SECTION 5 OF THE ENVIRONMENT (PROTECTION) ACT, 1986

WHEREAS, Central Government has notified the standards for discharge of environmental pollutants from various categories of industries under the Environment (Protection) Act, 1986 and the rules framed there under; and

WHEREAS, the Ministry of Environment, Forest and Climate Change, Govt. of India, vide notification S.O.157(E) of 27.02.1996 has delegated powers vested under Section 5 of the Environment (Protection) Act, 1986 (29 of 1986) to the Chairman, Central Pollution Control Board (CPCB), to issue direction to any industry, Municipal Corporation, Municipal Council, Cantonment Board to any local or other Authority for the violation of emission and effluent standards notified under the Environment (Protection) Rules, 1986 and other standards and norms; and

WHEREAS, M/s Frigerio Conserva Allana Pvt. Ltd., 14/1, Vill. Talaspur, Mathura Bypass Road, Aligarh, Uttar Pradesh (hereinafter referred as 'the Unit') has infrastructure for production of frozen boneless buffalo meat, poultry feed supplement (2 nos. rendering plants with capacities 4 TPD each), tallow and blood plasma (2 nos. with capacity 2 ton/day). It carries slaughtering of buffalo and is granted consent for slaughtering of 2000 animals per day; and

WHEREAS, the Unit was inspected by the officials of CPCB on January 6, 2016 to verify compliance status of discharge standards and the inspection team made following salient observations:

1. The Unit was not carrying out slaughtering, during the inspection and only rendering plants and blood meal plants were found in operation.
2. Out of two ETPs, only one ETP was found in operation. The effluent sample collected from ETP was found meeting the prescribed standards: TSS-29mg/l (standard -50mg/l) and BOD-16.1mg/l (standard - 30mg/l).

'परिवेश भवन' पूर्वी अर्जुन नगर, दिल्ली-110032
Parivesh Bhawan, East Arjun Nagar, Delhi-110032

दूरभाष/Tel : 43102030, 22305792, वेबसाइट/Website : www.cpcb.nic.in

3. The Unit has installed OCEMS and has provided connectivity to CPCB server. However, during inspection, data of TSS was not being displayed on OCEMS indicating non-functioning of TSS sensor.
4. The effluent generated from pet food plant was being bypassed and discharged into drain without any treatment. The effluent sample collected was found with BOD-332mg/l (standards - 30mg/l) and TSS - 120mg/l (standards - 50mg/l) which indicates non-compliance of prescribed norms.

WHEREAS, in view of the above, Chairman, CPCB vide letter dtd. 23.2.2017 had issued show-cause notice under section 5 of the Environment (Protection) Act, 1986, to the Unit that why it should not be closed until necessary steps are taken to rectify the short comings; and

WHEREAS, the Unit vide letter dated 14.3.2017 reported that they have closed bypass drain permanently and rectified TSS sensor; and

WHEREAS, the Unit was re-inspected by CPCB officials on 17.07.2017 to verify the compliance status and the team made the following observations:

1. The Unit was found in operation and was slaughtering 1700 big animals per day against the consented slaughtering of 2000 animals/day.
2. The ETP was found in operation and the treated effluent discharged from ETP was found confirming to the prescribed standards: TSS-15mg/l (standard - 50mg/l) and BOD-03mg/l (standard - 30mg/l).
3. The Unit has provided one designated outlet for discharge of treated effluent into the open drain which joins Aligarh drain.
4. No effluent bypass was observed during the inspection. Further the condensate bypass drain of pet food plant was found to be closed.
5. OCEMS data display was working properly and the data for all parameters was being displayed.

WHEREAS, Hon'ble NGT vide order dated 17.8.2017 in O.A.No.341/2017 issued directions for joint inspection of the Unit and disposed off the application; and

WHEREAS, the Unit was again inspected by officials of CPCB and UPPCB jointly on 05.10.2017 to verify the compliance status and made the following observations:

1. The Unit was found in operation and was slaughtering 1800 big animals per day against the consented slaughtering of 2000 animals/day.
2. All the ETP units of the Unit were found in operation and the treated effluent discharged from ETP was found confirming to the prescribed standards: TSS-13mg/l (standard - 50mg/l) and BOD-30mg/l (standard - 30mg/l).
3. The Unit has provided one designated outlet for discharge of treated effluent into the open drain which joins Aligarh drain and no bypass of effluent was observed.

4. OCEMS data display was working properly and the data for all parameters was being displayed.

NOW, THEREFORE, in view of the above observations and in exercise of the powers delegated to the Chairman, Central Pollution Control Board (CPCB) under section 5 of the Environment (Protection) Act, 1986, the showcause notice dated 23.2.2017 issued to the Unit : M/s Frigerio Conserva Allana Pvt. Ltd., 14/1, Vill. Talaspur, Mathura Bypass Road, Aligarh, Uttar Pradesh, is hereby revoked subject to following conditions :

- i. The Unit shall complete installation of electromagnetic flow meter at the ETP outlet and integrate it with OCEMS within 15 days from the date of issue of these directions.
- ii. The Unit shall ensure all time compliance with the prescribed discharge standards and proper functioning of OCEMS.
- iii. The Unit shall submit the compliance report within 21 days from the date of issue of these directions.

In case of failure to comply with the directions, action as deemed fit under the provision of Environment (Protection) Act, 1986 shall be launched taken against the Unit.



[S.P. SINGH PARIHAR]
CHAIRMAN

21.12.17



Copy to:

1. **The Member Secretary** : for information.
Uttar Pradesh Pollution Control Board
Building No. TC-12V, Vibhuti Khand,
Gomati Nagar, Lucknow
2. **The Regional Director,** : for information.
Central Pollution Control Board,
PICUP Bhawan, Ground Floor
Vibhuti Khand, Gomati Nagar,
Lucknow-226010
3. **The Joint Secretary (CP Division)** : for information.
Ministry of Environment, Forests & Climate Change,
Indra Paryavaran Bhavan,
Jor Bagh Road, New Delhi - 110 003
4. ✓ The Divisional Head, IT Division, CPCB
5. The Divisional Head, IPC-VI Division, CPCB


(A. Sudhakar)
Member Secretary

