



केन्द्रीय प्रदूषण नियंत्रण बोर्ड
CENTRAL POLLUTION CONTROL BOARD
पर्यावरण, वन एवं जलवायु परिवर्तन मंत्रालय भारत सरकार
MINISTRY OF ENVIRONMENT, FOREST & CLIMATE CHANGE GOVT. OF INDIA

SPEED POST

F.No.B-751(595)/Textile/WQM-II/2016-17/

07.02.2019
14

To,

M/s Meenar Polydyed Yarn Ltd.,
12, Bakhara, Bijuliabir, Dandi,
Chandauli-232101, Uttar Pradesh.

Compliance Directions under Section 5 of the Environment (Protection) Act, 1986-reg.

WHEREAS, the Textile, Dyeing & Bleaching industry is identified as one of the Grossly Polluting industries (GPIs) which has been discharging environmental pollutants directly or indirectly into the ambient air and water, having potential threat to cause adverse effect on the water and air quality; and

WHEREAS, the Ministry of Environment & Forests, Government of India, vide Notifications No. S.O. 157 (E) of 27.02.1996 and S.O. 730 (E) dated 10.07.2002, has delegated the powers vested under Section 5 of the Environment (Protection) Act, 1986 (29 of 1986) to the Chairman, Central Pollution Control Board, to issue directions to any industry or any local body or any other authority for violation of standards and rules notified under the Environment (Protection) Rules, 1986 and amendment thereof; and

WHEREAS, M/s Meenar Polydyed Yarn Ltd., 12, Bakhara, Bijuliabir, Dandi, Chandauli-232101, Uttar Pradesh (hereafter referred as the unit) is a textile industry; and

WHEREAS, CPCB issued directions under Section 5 of the Environment (Protection) Act, 1986 dated 21.11.2017 to the unit to comply with following directions:

1. The unit shall resume the manufacturing operation and inform immediately to CPCB.
2. The unit shall ensure all time compliance of the standards of treated effluent as per Gazette notified dated 10.10.2016 under the Environment (Protection) Act, 1986.
3. The unit shall submit treated effluent analysis report from laboratory recognized under the Environment (Protection) Act, 1986 within 30 days of resumption of operation.

AND WHEREAS, Show Cause notice under Environment (Protection) Act, 1986 dated 14.11.2018 was issued to the unit for not complying with directions dated 21.11.2017; and

WHEREAS, the unit vide its letters dated 07.12.2018 and 26.12.2018 has submitted treated effluent analysis report in compliance of CPCB directions dated 21.11.2017 and 14.11.2018 which indicate compliance of treated effluent with the prescribed norms ; and

NOW THEREFORE, in view of the above observations and exercising powers delegated to the Chairman, Central Pollution Control Board under Section 5 of the Environment (Protection) Act, 1986, the unit is hereby directed to comply with the following directions:

1. The unit shall operate its ETP properly so as to achieve compliance of stipulated standards.
2. The unit shall ensure regular connectivity of OCEMS with CPCB server.

In case of non-compliance of the above directions, CPCB will be constrained to initiate appropriate action in accordance with the provisions of Environment (Protection) Act, 1986 against the unit, **M/s Meenar Polydyed Yarn Ltd., 12, Bakhara, Bijuliabir, Dandi, Chandauli-232101, Uttar Pradesh** without giving any further notice.



(S P SINGH PARIHAR)
CHAIRMAN

11/02/2019

Copy to:

1. Member Secretary
Uttar Pradesh Pollution Control Board,
Building No. TC-12V, Vibhuti Khand, Gomti Nagar,
Lucknow – 226 010
2. Joint Secretary (CP Division)
Ministry of Environment, Forest & Climate Change
Prithvi Block, Indira Paryavaran Bhawan,
Jorbagh Road,
New Delhi – 110 003
3. Regional Director,
Regional Directorate (North),
Central Pollution Control Board,
PICUP Bhawan, Ground Floor,
Vibhuti Khand, Gomti Nagar,
Lucknow – 226 010.
- ✓ 4. In-charge, IT Division, CPCB Delhi
5. Master File-WQM-II Div., CPCB Delhi

For kind information pls.

For uploading the directions on CPCB website



(PRASHANT GARGAVA)
MEMBER SECRETARY