



केन्द्रीय प्रदूषण नियंत्रण बोर्ड  
CENTRAL POLLUTION CONTROL BOARD  
पर्यावरण, वन एवं जलवायु परिवर्तन मंत्रालय भारत सरकार  
MINISTRY OF ENVIRONMENT, FOREST & CLIMATE CHANGE GOVT. OF INDIA

SPEED POST

August 09, 2018

B-Tannery/IPC-IV/2018-19/ 9849

To

M/s K K Enterprises,  
Plot No. 7B/5, MIE Part-B,  
Bahadurgarh,  
Haryana

**Sub: Closure Directions under Section 5 of the Environment (Protection) Act, 1986.**

WHEREAS, the Central Government has notified the standards for discharge of environmental pollutants from various categories of industries under the Environment (Protection) Act, 1986 and Rules framed there under; and

WHEREAS, all industries are required to install and regularly operate the requisite pollution control facilities to comply with the standards for discharge of environmental pollutants; and

WHEREAS, CPCB has developed a protocol for selection of industries for inspection based on SMS alerts generated from OCEMS due to non-compliance of effluent discharge norms and non-connectivity of OCEMS; and

WHEREAS, the Ministry of Environment & Forests, Government of India, vide Notifications No. S. O. 157 (E) of 27.02.1996, has delegated the powers vested under Section 5 of the Environment (Protection) Act, 1986 (29 of 1986) to the Chairman, Central Pollution Control Board, to issue directions to any industry or any local body or any other authority for violations of the standards and rules notified under the Environment (Protection) Rules, 1986 and amendment thereof; and

WHEREAS, M/s K K Enterprises, Plot No. 7B/5, MIE Part-B, Bahadurgarh, Haryana was selected for inspection in view of SMS alerts generated from OCEMS [ Online Continuous Effluent Monitoring Systems] due to non-compliance of effluent discharge norms; and

WHEREAS, inspection of M/s K K Enterprises, Plot No. 7B/5, MIE Part-B, Bahadurgarh, Haryana (hereafter referred as "Unit") was conducted by a team of officers from CPCB Regional Directorate Lucknow on July 21, 2018 to check the status of compliance of prescribed norms; and

WHEREAS, it was observed during inspection that the unit has full-fledged infrastructure for processing wet blue skins of small animals (goats / sheeps) to finished leather with reported installed capacity of 1000 skins/day . During inspection, the unit was in operation. Other observations requiring attention of Regulating Authority are as follows:

1. Source of water is the bore-well which is not fitted with electro-magnetic flow meter. Further, the unit has not obtained NOC from CGWA for extraction of ground water.
2. During inspection, samples were collected from the equalization tank, aeration tank, outlet of secondary tube-settler and final outlet. It is observed from the analysis results that the operation of ETP is not upto mark. It is evident from the following :
  - a. BOD values at the final outlet is 82 mg/l which is not meeting with the stipulated norms of 30 mg/l.
  - b. The values of TDS is as high as 7199 mg/l .
  - c. Active Biomass i.e. MLSS in the aeration tank is very low and to the tune of 2065 mg/l only and it is indicating poor operation/unstabilization of ETP.
3. The unit has not provided separate energy meter for the operation of ETP. Log book is also not maintained.
4. The unit has been granted Authorization under the Hazardous & Other Wastes ( Management & Transboundary Movement ) Rules , 2016 for handling of 3 kg/month of chrome bearing residues / sludge. But the unit is generating approx. 400 kg per month of ETP Sludge, which is not in line with the Authorization granted by Haryana State Pollution Control Board.
5. Overall HW Management of the unit is very poor and even proper storage facilities are not provided. Also, the unit has not maintained any log book on HW generation and disposal.
6. The unit has one DG set (Capacity 125 KVA), which is not equipped with stack of adequate height.

**NOW, THEREFORE**, in exercise of powers delegated to the Chairman, CPCB under Section 5 of the Environment (Protection) Act, 1986, **M/s K K Enterprises, Plot No. 7B/5, MIE Part-B, Bahadurgarh, Haryana** is hereby directed to close down its manufacturing activities with immediate effect. The Unit is further directed for the following:

1. The Unit shall submit a time-targeted action plan within 15 days for rectification of short comings as described above.
2. The unit shall rectify the shortcomings as per time targeted action plan.
3. The Unit shall not re-start its manufacturing activities unless required corrective measures are taken and without written permission from CPCB.


The Unit shall ensure compliance of these directions failing which action shall be taken against the Unit, without giving any further opportunity, in accordance with provisions of the Environment (Protection) Act, 1986.

  
13.8.18  
(S.P. Singh Parihar)  
Chairman



Copy for kind information & Compliance to :

1.	The Chairman, Haryana State Pollution Control Board, C-11, Sector-6. Panchkula-134109, Haryana	With a request to ensure compliance of the directions please.
2.	The Managing Director Uttar Haryana Bijli Vitran Nigam (UHBVN) H21-City-I Bahadurgarh Bahadurgarh, Haryana	The electricity supply to the industry be disconnected with immediate effect.
3.	The Deputy Commissioner Mini Secretariat, DC Office Jhajjar	With a request to ensure compliance of the directions please.
4.	The Joint Secretary (CP Division), Ministry of Environment, Forest & C.C., Prithvi Block, Indira Paryavaran Bhawan, Jorbagh Road, New Delhi - 110003.	For information , please.
5.	The Regional Director, Regional Directorate- North, Central Pollution Control Board, PICUP Bhawan, Gound Floor, Vibhuti Khand, Gomti Nagar, Lucknow - 226010.	For information and necessary action please
6.	The Divisional Head , IT Division, CPCB- HO., Delhi	
7.	The Divisional Head , IPC-VI Division, CPCB-HO., Delhi	

  
[Prashant Gargava ]  
Member Secretary