



केन्द्रीय प्रदूषण नियंत्रण बोर्ड
CENTRAL POLLUTION CONTROL BOARD

पर्यावरण, वन एवं जलवायु परिवर्तन मंत्रालय भारत सरकार
MINISTRY OF ENVIRONMENT, FOREST & CLIMATE CHANGE GOVT. OF INDIA

SPEED POST

September 27, 2018

B-29016/04/06/IPC-I/

11259

To,

M/s Anil Spinners,
Plot no. H-19-20, Industrial Area,
Panipat, Haryana- 132103

Sub: Directions under Section 5 of the Environment (Protection) Act, 1986- reg.

WHEREAS, Textile dyeing and bleaching industries are identified as one of the Grossly Polluting industries (GPIs) which have been discharging environmental pollutants directly or indirectly into the ambient air and water, having potential threat to cause adverse effect on the water and air quality; and

WHEREAS, the Central Government has notified general discharge standards of environmental pollutants from various categories of industries under the Environment (Protection) Act, 1986 and the rules framed there under; and

WHEREAS, Hon'ble Supreme Court of India in the matter of Paryavaran Suraksha Samiti Vs Union of India & Others dated 22/02/2017 directed that no industry which requires "consent to operate" from the concerned Pollution Control Board, is permitted to function, unless it has a functional effluent treatment plant, which is capable to meet the prescribed norms for removing the pollutants from the effluent, before it is discharged; and

WHEREAS, the Ministry of Environment & Forests, Government of India, vide Notifications No.S.O.157(E) of 27.02.1996 and S.O.730(E) dated 10.07.2002, has delegated the powers vested under Section 5 of the Environment (Protection) Act, 1986 (29 of 1986) to the Chairman, Central Pollution Control Board, to issue directions to any industry or any local body or any other authority for violations of the standards and rules notified under the Environment (Protection) Rules, 1986 and amendment thereof; and

WHEREAS, M/s Anil Spinners, Plot no. H-19-20, Industrial Area, Panipat, Haryana (here in after referred as 'the unit') is a textile processing unit; and

WHEREAS, the unit was inspected on 24th May, 2018 by CPCB officials and following observations are made:

- 1) The unit was found non-operational at the time of inspection.
- 2) The unit is involved in the bleaching of polyester yarn at an installed capacity of 3-4 MTD as per the inspection report.
- 3) The unit has a borewell to meet its water requirements and generates about 18 KLD of waste water.
- 4) The ETP was also found to be non-operational at the time of the inspection.
- 5) The ETP consists of a collection tank, reaction tank, tube settler, sludge drying bed, filter feed tank and filter water tank.
- 6) The treated effluent is sent to a STP through sewer lines and after treatment is disposed to Panipat drain and then to River Yamuna.
- 7) The ETP sludge is disposed to Gujrat Enviro Protection and Infrastructure Pvt. Ltd.
- 8) The air, water and hazardous waste consents of the unit are valid upto 30th September, 2020.

Page 1 of 3

'परिवेश भवन' पूर्वी अर्जुन नगर, दिल्ली-110032

Parivesh Bhawan, East Arjun Nagar, Delhi-110032

दूरभाष/Tel : 43102030, 22305792, वेबसाईट/Website : www.cpcb.nic.in

- 9) During the visit, untreated effluent was found in the underground storage tank. However, it was requested to operate ETP during the visit and effluent was collected from the outlet.
- 10) The analysis results of the samples collected from collection tank showed the following results: pH - 10.62 (against stipulated standards of 6-.5-8.5), TSS- 143 mg/l (against stipulated standards of 100 mg/l), BOD -190 mg/l (against stipulated standards of 30 mg/l), COD-732 mg/l (against stipulated standards of 250 mg/l), Colour-103 PCU (against stipulated standards of 150 PCU), TDS- 1412 mg/l (against stipulated standards of 2100 mg/l), SAR- 6.70 (against stipulated standards of 26), Oil & Grease -21mg/l (against stipulated standards of 10 mg/l), Phenol -0.20 mg/l (against stipulated standards of 1.0 mg/l), Ammonical Nitrogen -6 mg/l (against stipulated standards of 50 mg/l) and Chromium -0.03 mg/l (against stipulated standards of 2 mg/l) which show non-compliance wrt pH, TSS, BOD, COD and Oil and Grease.

WHEREAS, a direction under section 5 of Environment (Protection) Act 1986 was issued vide letter no. B-29016/04/06/IPC-1/739 dated August 10, 2018 to the Unit to remain closed and not to restart the operations without permission of CPCB; and

WHEREAS, a reply from the Unit received on September 04, 2018 that the Unit has complied with all the direction dated August 10, 2018 issued by CPCB, the Unit has submitted Third Party analysis reports & Adequacy report of ETP, the plant operations has already been closed down w.e.f. August 30, 2018 after receipt of CPCB direction and requested to revoke the closure direction; and

WHEREAS, CPCB constituted a Three-member committee vide office order dated 03.10.2017 having representative(s) from CPCB and MoEF&CC for examination and recommendation for revocation of the closure direction issued by CPCB; and

WHEREAS, the three-member committee in its meeting held on 14.09.2018 examined the compliance report submitted by the Unit and recommended that the Unit may be allowed to resume its operations with conditions that:

1. The Unit shall provide dosing pump in dosing tank as suggested in adequacy report, on immediate basis.
2. The Unit shall submit performance audit report of ETP from expert Government Institution to CPCB within 60 days of start of operation.
3. The Unit shall submit monthly log book data of ETP for one month to CPCB.
4. The Unit shall get compliance verification from Haryana State Pollution Control Board and submit the report to CPCB within three months.

WHEREAS, the Ministry of Environment & Forests, Government of India, vide Notifications No. S. O. 157 (E) of 27.02.1996 and S. O. 730 (E) dated 10.07.2002, has delegated the powers vested under Section 5 of the Environment (Protection) Act, 1986 (29 of 1986) to the Chairman, Central Pollution Control Board, to issue directions to any industry or any local body or any other authority for violations of the standards and rules notified under the Environment (Protection) Rules, 1986 and amendment thereof.

NOW, THEREFORE, in exercise of powers vested to Chairman CPCB under Section 5 of the Environment (Protection) Act, 1986, and in view of compliance with relevant direction under reference, the direction issued under the Section 5 of the Environment

(Protection) Act, 1986 to the Unit (M/s Anil Spinners, Plot no. H-19-20, Industrial Area, Panipat, Haryana) vide letter dated August 10, 2018 is hereby revoked with condition that:

1. The Unit shall provide dosing pump in dosing tank as suggested in adequacy report prior to restarting its operation.
2. The Unit shall submit performance audit report of ETP from expert Government Institution to CPCB within 60 days of start of operation.
3. The Unit shall submit monthly log book data of ETP for one month to CPCB.
4. The Unit shall get compliance verification from Haryana State Pollution Control Board and submit the report to CPCB within three months.

In case of non-compliance by the Unit action as deemed fit under the provisions of Environment (P) Act, 1986 shall be taken


(Arun Kumar Mehta)
Chairman

Copy to:

1. The Chairman
Haryana State Pollution Control Board
C-11, Sector - 6
Panchkula, Haryana
2. The Advisor (CP Division)
Ministry of Environment, Forests and Climate Change
Prithvi Wing, 2nd Floor, Room No. 216
Indira Paryavaran Bhawan
Aliganj, Jor Bagh Road
New Delhi - 110003
3. The Incharge, Regional Directorate
Central Pollution Control Board
Ground & First Floor, PICUP Bhawan
Vibhuti Khand, Gomti Nagar
Lucknow - 226 020
4. The Chairman,
Uttar Haryana Bijli Vitran Nigam Ltd.
(UHBVNL), Vidyut Sadan, Plot No.: C 16,
Sector-6, Panchkula, Haryana- 134109
5. ✓ I/c, IT, CPCB
6. ✓ I/c, IPC-I

: With a request to restore
electricity supply of the Unit


(Prashant Gargava)
Member Secretary