

By Speed Post

F.No. B-536 (T)/IPC-III/2019-20/ 566

April 05, 2019

To,

**M/s. Chroma Processor**, (Textile Dyeing)  
Village-Sewah Near Choutala Road,  
**Panipat, Haryana**

**DIRECTION UNDER SECTION 5 OF THE ENVIRONMENT (PROTECTION) ACT, 1986**

**WHEREAS**, the Central Government has notified the standards for discharge of environmental pollutants from various categories of industries under the Environment (Protection) Act, 1986 and the rules framed there under; and

**WHEREAS**, the Ministry of Environment, Forest, & Climate Change, Govt. of India, vide notification S.O.157(E) of 27.02.1996 has delegated powers vested under Section 5 of the Environment (Protection) Act, 1986 (29 of 1986) to the Chairman, Central Pollution Control Board (CPCB), to issue direction to any industry, Municipal Corporation, Municipal Council, Cantonment Board, to any local or other Authority for the violation of emission and effluent standards notified under the Environment (Protection) Rules, 1986 and other standards and norms; and

**WHEREAS**, it is obligatory on the part of industries to install effluent treatment plants (ETPs) to comply with the effluent discharge standards as notified under the Environment (Protection) Act, 1986 and the Rules framed there under and also to meet the consent conditions granted by State Pollution Control Board (SPCBs) / Pollution Control Committees (PCCs); and

**WHEREAS**, **M/s Chroma Processor**, Village-Sewah Near Choutala Road, Panipat, Haryana (*hereafter referred to as 'the Unit'*) was inspected by a team of officials from CPCB & Haryana SPCB on 01.06.2018 and was found non-complying with the effluent discharge norms w.r.t pH, BOD & TDS parameters. Hence, CPCB had issued a Show Cause Notice u/s 5 of the E(P)A, 1986 dated 21.08.2018 for the non compliance noticed during the inspection.

**WHEREAS**, the Unit was again inspected by the officials of CPCB on 21.02.2019 to verify the compliance to direction issued by CPCB and the following major observations are made;

1. The Unit is a textile dyeing industry.
2. The Unit and its ETP was found operational during visit. ETP comprises of collection tank, dosing tank, tube settler (2 no.), treatment water tank/collection tank, clarifier, GFCG/AT Filter. The treated effluent is being discharged into the drain.

P

3. Analysis results of the sample collected from the inlet of ETP showed pH-8.84, BOD-157 mg/l, COD-443 mg/l, TDS-3024 mg/l, TSS-208 mg/l. The ETP outlet (treated effluent) sample analysis result showed pH-8.6 (*norms-6.5-8.5*); BOD-111 mg/l (*norms-30 mg/l*); COD-254 mg/l (*norms-250 mg/l*); and TSS-22 mg/l (*norms-100 mg/l*) & TDS-2232 mg/l (*norms-2100 mg/l*) which indicate non-compliance of notified discharge norms w.r.t pH, BOD, COD & TDS parameter.

**WHEREAS, it is evident that the unit was found non-complying with the prescribed effluent discharge norms w.r.t. pH, BOD, COD & TDS parameters; and**

**NOW, THEREFORE,** in view of the events, as described above and exercising the powers delegated to the Chairman, Central Pollution Control Board (CPCB) under section 5 of the Environment (Protection) Act, 1986, **M/s Chroma Processor, Vill- Sewah Near Choutala Road, Panipat, Haryanat is hereby directed to "close down all its manufacturing operations and not to restart manufacturing" till it complies with effluent discharge standards and the following directions:**

1. The unit should carry out adequacy assessment report of ETP through reputed Government institutes such as IIT/NEERI & accordingly augment the ETP provided so as to achieve the prescribed discharge standards.
2. The unit shall report to CPCB regarding closure of manufacturing operations in compliance of the direction immediately on receipt of this direction.
3. The unit shall seek permission from CPCB before resumption of the manufacturing operations.

In case of default in compliance with the above directions, CPCB will be constrained to initiate action against the unit, in accordance with the provisions of the Environment (Protection) Act, 1986, without giving any further notice.

  
**(S.P. SINGH PARIHAR)**  
**CHAIRMAN**

Copy to:

1. **The Member Secretary,** : For information pl.  
Haryana State Pollution Control Board,  
C-11, Sector-6. Panchkula-134109, Haryana
2. **The Regional Director,** : For information pl.  
Regional Directorate (Lucknow),  
Central Pollution Control Board,  
PICUP Bhawan, Ground Floor, Vibhuti  
Khand, Gomati Nagar, Lucknow-226010



3. **The Advisor (CP Division)** : For information pl.  
Ministry of Environment, Forest & Climate  
Change, Indra Paryavaran Bhavan,  
JorBaghRoad, New Delhi-110003
4. The Division Head, IT Division, CPCB, Delhi : To upload the direction at CPCB website pl.
5. The Division Head, IPC-I Division, CPCB, Delhi : For information pl.
6. The Division Head, IPC-III Division, CPCB, Delhi : For record purpose

  
**(PRASHANT GARGAVA)**  
**MEMBER SECRETARY**