

**BY REGD. AD**

**F. No. B-751(570)/Textile/WQM-II/2017-18**

**August 10, 2017**

To

**M/s Jeet Dying (Unit 2)  
Plot No, 1759, 1761, Maswasi Road,  
Magarwara, Unnao,  
Uttar Pradesh.**

**Sub: Directions under Section 5 of the Environment (Protection) Act, 1986**

**WHEREAS**, the Central Government has notified the standards for discharge of environmental pollutants from various categories of industries under the Environment (Protection) Act, 1986 and the rules framed there under; and

**WHEREAS**, the Ministry of Environment & Forests, Govt. of India, vide notification S.O.157(E) of 27.02.1996 has delegated powers vested under Section 5 of the Environment (Protection) Act, 1986 (29 of 1986) to the Chairman, Central Pollution Control Board (CPCB), to issue direction to any industry, Municipal Corporation, Municipal Council, Cantonment Board to any local or other Authority for the violation of emission and effluent standards notified under the Environment (Protection) Rules, 1986; and

**WHEREAS**, M/s Jeet Dying (UNIT 2), (hereafter referred as the unit) is a Textile industry located at Maswasi Road, Magarwara, Unnao, Uttar Pradesh.

**WHEREAS**, the representative (s) of Central Pollution Control Board conducted inspection of the unit on 11/04/2017. During the visit, the following observations were made;

- I. The unit is not having valid Consent under water (Prevention & Control of Pollution), 1974 Act & Air (Prevention & Control of Pollution) Act, 1981.
- II. Multiple discharge points were found during the inspection.
- III. Flow meters are not attached with the Effluent Treatment Plant.
- IV. Online Emission Monitoring System is not having connectivity with the CPCB server.

**WHEREAS**, CPCB issued closure direction dated 30/5/2017 Under Section 5 of Environment (Protection) Act, 1986.

**WHEREAS**, unit replies vide letter dated 12 June 2017, and following observations were made;

- I. The unit has provided consent validity up to 31.12.2018 of Air and Water.
- II. The unit has informed that no multiple sources are in functioning at present.

**(Contd..2/-)**

- III. The unit has installed flow meter at ETP.
- IV. The unit has provided its connectivity to CPCB server and the same has been verified by IT Division.

**NOW THEREFORE**, in view of the compliance made by the unit to the direction issued by CPCB and in exercise of powers delegated under Section 5 of the Environment (Protection) Act, 1986, the unit, M/s. Jeet Dying (Textile Division) is allowed to resume its manufacturing operations subject to the following conditions;

1. It shall be ensured that the installed online monitoring devices are functioning properly and continuously and that data from the devices are uninterruptedly transferred to CPCB. Any failure in this regard shall be intimated to CPCB with reasons thereof and shall be rectified at the earliest.

In case of default in compliance with the above directions or any other exigencies, CPCB will be constrained to initiate further stringent action against the Unit, in accordance with the provisions of the Environment (Protection) Act, 1986, without any further notice.

**(S.P. SINGH PARIHAR)**  
**CHARIMAN**

Copy to;

1. **Member Secretary,**  
**Uttar Pradesh Pollution Control Board,**  
Building No. TC-12V, Vibhuti Khand,  
Gomti Nagar, Lucknow (UP) – 226 010

With request to ensure that the unit complies with the directions.

2. **Regional Director,**  
**Regional Directorate (CP Division)**  
Central Pollution Control Board.  
PICUP Bhawan, Vibhuti Khand,  
Gomti Nagar, Lucknow - 226 010

For information please

3. **Managing Director,**  
Madhyanchal Vidyut Vitran Nigam Ltd.,  
Head office 4-A, Gokhale Marg,  
Lucknow 226001, U.P.

With request to restore the power supply to the unit, pl

(Contd...3/-)

4. **District Magistrate,**  
Collectorate, Unnao,  
Distt- Unnao (U.P.)

For information regarding revoked  
closure direction, pl.

5. In-charge IT Division, CPCB Delhi

For information please

6. WQM-II Division, CPCB Delhi



**(A B AKOLKAR)**  
**MEMBER SECRETARY**