



Speed Post

B-33014/7/2017-18/IPC-II 10806

September 14, 2017

To

The Unit Head
M/s Zuari Cements Ltd.
Krishna Nagar,
Yerraguntla
Kadapa Distt
Andhra Pradesh

Sub: Show cause Notice under Section 5 of the Environment (Protection) Act, 1986

WHEREAS, the Central Government has notified standards for discharge of environmental pollutants from various categories of industries under the Environment (Protection) Act, 1986 and the rules framed there under; and

WHEREAS, Ministry of Environment & Forests, Govt. of India, vide notification S.O. 157 (E) of 27.02.1996 has delegated powers vested under section 5 of the Environment (Protection) Act, 1986 (29 of 1986) to the Chairman, Central Pollution Control Board (CPCB), to issue directions to any industry, municipal corporation, municipal council, cantonment board, to any local or other Authority for violation of emission and effluent standards notified under the Environment (Protection) Rules, 1986 and other standards and norms; and

WHEREAS, **M/s Zuari Cements Ltd., Krishna Nagar, Yerraguntla Kadapa Distt, Andhra Pradesh** was inspected by a team of Scientists from CPCB, RD-Bangalore during July 11-12, 2017 to assess the compliance status w.r.t. high SMS alert/offline for the period of May 2017 and following observations/recommendations were made by the inspecting team:

1. The unit needs to control fugitive emissions by asphaltting existing mud road approaching mines from garage.
2. The unit should take corrective measures to arrest fugitive emissions in extraction gates located at right and left extreme corners of clinker silo.
3. The unit needs to provide rubber curtains in Hoppers at crushers 1 & 2 and to improve housekeeping around crusher 1, 2 & 3.
4. The unit should store lime stone and other raw materials of Line-1 in closed shed instead of stocking in open area.
5. The unit should provide sampling port and sampling platforms in all the stacks as per Emission Regulation Part-III of CPCB.

614

6. The unit should install analysers in all three CAAQMS to monitor SO₂ & NO_x to comply the consent conditions.
7. The unit should improve the operation & maintenance of STP and the housekeeping in STP area.
8. The unit should maintain the records of Hazardous Wastes generated and disposed as per the consent conditions. It has been observed that the quantity of generation of waste grease as per Manifest dated 06.04.2017 is more than the permitted quantity.
9. The unit should take corrective measures to activate SMS alerts during exceedance of values.
10. The unit should inform CPCB whenever there is shut down.
11. The unit should rectify the problems associated with SO₂ & NO_x analysers installed at Line -2 kiln stacks and intimate the action taken to CPCB.

Now, THEREFORE, in view of the above observations / recommendations and exercising the powers delegated to the Chairman, Central Pollution Control Board under section 5 of the Environment (Protection) Act, 1986, notice is being served herewith to **M/s Zuari Cements Ltd., Krishna Nagar, Yerraguntla Kadapa Distt, Andhra Pradesh** to show cause as to why action be not taken against the industry for shortcoming as mentioned above; and

M/s Zuari Cements Ltd., Krishna Nagar, Yerraguntla Kadapa Distt, Andhra Pradesh is further directed for the following:

1. The industry shall immediately initiate the remedial measures for rectification of shortcomings as mentioned above.
2. The industry shall submit reply & action taken report within 15 days from the date of issue of this Notice.

In the absence of the compliance report, it will be presumed that the industry has nothing to say in this regard and CPCB will be constrained to take action as deemed fit including prosecution under the provision of the Environment (Protection) Act, 1986.

(S.P. S. Parihar)
Chairman

15/09/17





Copy to:

| | | |
|---|---|---|
| 1 | The Chairman A.P. Pollution Control Board Paryavarana Bhavan A-3, Industrial Estate Sanath Nagar Hyderabad - 500 018, Andhra Pradesh | For information & ensuring compliance please. |
| 2 | The Regional Director Central Pollution Control Board 1st & 2nd Floors, Nisarga Bhawan A- Block, Thimmaiah Main Road 7th D Cross, Shivanagar Opposite Pushpanjali Theatre Bangalore 560 010 | For information please. |
| 3 | The Additional Secretary (AKM) Ministry of Environment, Forests and Climate Change Prithvi Wing, 2nd Floor, Room No. 216 Indira Paryavaran Bhawan Aliganj, JorBagh Road, New Delhi - 110003 | |
| 4 | The Divisional Head, IT, CPCB, Delhi | |
| 5 | The Divisional Head (PKG), IPC-VI, CPCB | |
| | | |


(A. Sudhakar)
Member Secretary

