

SPEED POST

F. No. B-751 (690)/Chemical & Others/WQM-II/CPCB/2017-18

September 11, 2017

To

**M/s Ordnance Factory,  
Metal Finishing Unit, Kalpi Road,  
Kanpur-208009, Uttar Pradesh**

10529

**DIRECTION UNDER SECTION 5 OF THE ENVIRONMENT (PROTECTION) ACT,  
1986**

**WHEREAS**, the Central Government has notified the general discharge standards of the environment pollutants from various categories of industries under the Environment (Protection) act, 1986 and rules framed there under; and

**WHEREAS**, the Ministry of Environment & Forests, Government of India, vide Notifications No. S. O. 157 (E) of 27.02.1996 and S. O. 730 (E) dated 10.07.2002, has delegated the powers vested under Section 5 of the Environment (Protection) Act, 1986 (29 of 1986) to the Chairman, Central Pollution Control Board, to issue directions to any industry or any local body or any other authority for violations of emission and effluent standards and rules notified under the Environment (Protection) Rules, 1986 and amendment thereof; and

**WHEREAS**, a team of officials from CPCB carried out inspection of the industrial unit namely **M/s Ordnance Factory, Metal Finishing Unit, Kalpi Road, Kanpur -208009, Uttar Pradesh** on dt. 27.03.2017 for verification of compliance to the norms stipulated under the Environment (Protection) Rules, 1986; and

**WHEREAS**, CPCB issued closure direction dated 30.05.2017 under section 5 of the Environment (Protection) Act, 1986 to the unit for not installation of online continuous effluent monitoring system; and

**WHEREAS**, the unit's reply vide letters dated 17.06.2017, 07.07.2017, 17.07.2017 and 09.08.2017 were examined and following observation are made:

1. The disposal of the paint sludge is being done at proper place through authorized agency. The spillage of acid/alkali has been arrested.
2. All three aerators of aeration tank will be made functional by 30.06.2017.
3. The CETP/Main ETP is working as per design.
4. Deposition of leaves and other organic matter have been removed from the secondary clarifier tank & BOD is within the limits. Fiber mesh has been placed to cover the secondary clarifier tank.
5. The unit has installed OCEMS and provides connectivity to CPCB server.
6. The log book is being maintained by the unit.
7. The unit has submitted self certificate indicating that the unit has stopped all the relevant operations with effect from 16.06.2017.

**AND NOW THEREFORE**, in view of the above mentioned observations and in exercise of the powers delegated to the Chairman CPCB, under section 5 of the Environment (Protection) Act, 1986, the unit is directed to comply with the following direction:


1. The unit **M/s Ordnance Factory, Metal Finishing Unit Kalpi Road, Kanpur - 208009, Uttar Pradesh** shall resume operation and shall treat their effluent to meet the effluent discharge standards as notified under Environment (Protection) Rules, 1986.
2. The unit shall ensure continuous connectivity with CPCB server.

In case of default in compliance with the above directions, CPCB will be constrained to initiate action without any further notice, in accordance with the provisions of the Environment (Protection) Act, 1986.

(S. P. SINGH PARIHAR)  
CHAIRMAN

**Copy to:**

1. **Chairman,**  
Uttar Pradesh Pollution Control Board,  
Building No. TC-12V,  
Vibhuti Khand, Gomti Nagar, Lucknow-226010  
: [For information please ]
2. **The Advisor (CP Division).**  
Ministry of Environment, Forests & Climate Change,  
Indra Paryavaran Bhavan,  
Jor Bagh Road, New Delhi - 110 003  
: [for information please]
3. **The Regional Director,**  
Regional Directorate (N),  
Central Pollution Control Board,  
Zonal Office (North) PICUP  
Bhawan Vibhuti Khand, Gomti Nagar,  
Lucknow - 226 010, Uttar Pradesh  
: [For the implementation and  
compliance of the direction]
4. **District Magistrate,**  
Kanpur Nagar, Uttar Pardesh  
: [for information please]
5. **Managing Director,**  
Kanpur Electricity Supply Company Limited,  
Headquarter, Kesa House,  
14/71 Civil Lines, Kanpur  
:[With direction re-connect the  
power supply of the unit]
6. ✓ The Incharge IT Division, CPCB, Delhi
7. Master copy (Others), CPCB, Delhi

  
(A. SUDHAKAR)  
MEMBER SECRETARY

M/s Ordnance Factory, Metal Finishing Unit, Kalpi Road, Kanpur -208009, Uttar Pradesh