



केन्द्रीय प्रदूषण नियंत्रण बोर्ड
CENTRAL POLLUTION CONTROL BOARD
पर्यावरण, वन एवं जलवायु परिवर्तन मंत्रालय भारत सरकार
MINISTRY OF ENVIRONMENT, FOREST & CLIMATE CHANGE GOVT. OF INDIA

SPEED POST

B-29016/04/06/IPC-I/ 40737

September 22, 2017

To

M/s. Syn Finechem Laboratories Pvt. Ltd.,
D-151, Phase-III, IDA, Jeedimetla
Hyderabad, Telangana - 500055

Sub: Directions under Section 5 of the Environment (Protection) Act, 1986 regarding installation of on-line effluent and emission monitoring system.

WHEREAS, the Pharmaceutical industries are identified as one of the 17 categories of highly polluting industries which have been discharging environmental pollutants directly or indirectly into the ambient air and water, having potential threat to cause adverse effect on the water and air quality; and

WHEREAS, M/s. Syn Finechem Laboratories Pvt. Ltd., Telangana (herein after referred as the Unit) has installed online monitoring system; and

WHEREAS, the Online effluent Monitoring system of the Unit was in offline mode during the month of April-May 2017; and

WHEREAS the Unit was inspected by a team of official(s) from the CPCB Regional Directorate, Bangalore on July 26, 2017 to assess the adequacy of the existing pollution control measures and online effluent monitoring system, observations of team are as follows:

1. The Unit has not provided the water meter to verify the quantity of water consumed and also not maintained the log book.
2. The Unit has not segregating the HTDS & LTDS streams as per the consent issued from the Telangana State Pollution Control Board however the solvent generated from the process is pumped to the syntax tanks through flexible pipes.
3. The Unit has not provided the proper labelling to the solvent storage area and not provided boundary wall to collect the spillages.
4. The containers and used drums are kept haphazardly and these drums are sold to recyclers without detoxification.
5. The Unit has not provided the proper space for the storage of hazardous waste as it was stored near the wood fired boiler.
6. The Unit has not installed the online pH monitoring system for the scrubber as per the consent and also not provide the log books.
7. The unit has not provided any emission monitoring device to monitor the nature of emission discharged by the stack.

WHEREAS, based upon observations of inspecting team & non compliance w.r.t point 1 to 7 a closure direction issued to the Unit on August 31, 2017; and

WHEREAS, the Unit informed vide letter dated September 05, 2017 that the Unit has segregate the HTDS & LTDS stream and provided separate collection tanks for both streams, sending the effluents to JETL for further treatment; and

WHEREAS, the Unit vide letter dated September 05, 2017 submitted the undertaking duly notarized, Effluent monitoring laboratory analysis report, copy of consent valid upto March 31, 2021 and requested to revoke the closure direction; and

WHEREAS, the Unit has submitted an undertaking on September 05, 2017 that "the Unit has complied with all directions issued by CPCB and if plant is found non-compliant during verification by CPCB officials, the Unit accept to close down operations immediately and shall not operate till full compliance is achieved; and

WHEREAS, the Unit has submitted treated effluent analysis report (effluent before sending to JETL) dated August 31, 2017 from Lawn Enviro Associates, Hyderabad and the results are within the norms prescribed by TSPCB;

WHEREAS, the Ministry of Environment & Forests, Government of India, vide Notifications No. S. O. 157 (E) of 27.02.1996 and S. O. 730 (E) dated 10.07.2002, has delegated the powers vested under Section 5 of the Environment (Protection) Act, 1986 (29 of 1986) to the Chairman, Central Pollution Control Board, to issue directions to any industry or any local body or any other authority for violations of the standards and rules notified under the Environment (Protection) Rules, 1986 and amendment thereof.

NOW, THEREFORE, in exercise of powers vested to Chairman CPCB under Section 5 of the Environment (Protection) Act, 1986, and in view of undertaking of compliance submitted by the Unit with relevant direction under reference, the direction issued under the Section 5 of the Environment (Protection) Act, 1986 to the Unit (M/s. Syn Finechem Laboratories Pvt. Ltd., Telangana) vide letter dated August 31, 2017 is hereby revoked. The Unit will ensure compliance with the norms. In case of non-compliance by the Unit action as deemed fit under the provisions of Environment (P) Act, 1986 shall be taken.

(S. P. Singh Parihar)
Chairman

ambin 22/09/2017

Copy to:

1. The Chairman
Telangana State Pollution Control Board
Paryavaran Bhawan, A-3, Industrial
Estate, Sanathnagar, Hyderabad-500018

2. The Chairman
Southern Power Distribution
Telangana Limited
Corporate Office: # 6-1-50,
Mint Compound, Hyderabad-500063

3. The Advisor (CP Division)
Ministry of Environment, Forests and Climate Change
Prithvi Wing, 2nd Floor, Room No. 216, Indira
Paryavaran Bhawan Aliganj, JorBagh Road,
New Delhi - 110003

4. The Regional Director
Central Pollution Control Board
1st & 2nd Floors, Nisarga Bhavan A-Block,
Thimmaiah Main Road, 7th D Cross, Shivanagar,
Opp. Pushpanjali Theatre, Bangalore -560 010

5. The Incharge, IT, CPCB

6. The Incharge, IPC-VI, CPCB

:With request to restore electricity
supply of the Unit.

: With a request to ensure inspection
of this Unit within 30 days and to
report the findings to HO.

A. Sudhakar
(A. Sudhakar)
Member Secretary