

17965
Email/ Speed post

February 28, 2018

CPCB/B-33014/40/2017/IPC-II/ 17965

To:

The Member Secretary
Jharkhand State Pollution Control Board
T.A. Bldg., HEC, P.O. Dhurwa,
Ranchi - 834004, Jharkhand

Sub: Inspection carried out to M/s. Vaishnavi Ferro Tech Pvt. Ltd., Rauta Marar, Ramgarh, Jharkhand w.r.t. OCEMS related non-compliance.

Ref:

1. CPCB Direction to all SPCB u/s 18 (1)(b) Ref. No. B-29016/04/06/PCI-I/5401, dated 05.02.2014.
2. CPCB Direction to all SPCB u/s 18 (1)(b) Ref. No. B-29016/04/06/PCI-I/7176-7216, dated 02.03.2015.
3. Revocation of SCN Order Ref No. B-33014/40/2017/IPC-II/10970, dated 21.09.2017.
4. Industry letter to JSPCB, vide Ref. No. Nil, dated 31.01.2018 regarding non-operational status.

Sir,

Please refer to the letter dated 31.1.2018 of M/s Vaishnavi Ferro Tech Pvt Ltd. regarding shut down of manufacturing activities since 31.12.2017 due to expansion of the existing project. The unit was inspected on 31.01.2018 and found not in operation due to above mentioned reason. It is requested to ensure that the unit restart operation after renewing CTO from JSPCB and installing OCEMS as per CPCB guidelines if the expansion of such nature that unit is converted into an Integrated Iron & Steel Plant or Sponge Iron Plant.

Yours Faithfully,

Nazimuddin

[Nazimuddin]

Div. Head, IPC-II

Copy to:

1. M/s. Vaishnavi Ferro Tech Pvt. Ltd.,
Rauta Marar Ramgarh,
Jharkhand
2. The Regional Director (East)
Central Pollution Control Board
Southend Conclave, Block 502,
5th & 6th Floors, 1582 Rajdanga Main Road,
Kolkata-700107 (West Bengal)
3. The Divisional Head- IT, CPCB, Delhi
4. The Divisional Head- IPC-VI, CPCB, Delhi