



**Central Pollution Control Board**

**Zonal Office (South), Bangalore**

**Project Head – VI Waste Management and Urban Pollution Control (plastic waste, Hazardous Waste, Municipal Solid Waste, Bio-Medical Waste, E-Waste & Vehicular Pollution**

**Scheme 34**

**Monitoring of Common Effluent Treatment Plant 2013-14**

<b>S No</b>	<b>Name of the CETP</b>	<b>Address</b>	<b>State</b>	<b>Date of Inspection</b>	<b>Direction / Notice Issued under sections</b>	<b>Date of Directions Issue</b>	<b>Present Status</b>	<b>Reports</b>
1	M/s Pallavaram Tanners Industrial Effluent Treatment Co Ltd	105, Anna Salai, Nagalkeni, Chrompet, Chennai 600044	Tamil Nadu	26 <sup>th</sup> & 27 <sup>th</sup> September 2013			Report Sent to HO on 5th December 2013	<a href="#">Report</a>
2	M/s Vaniyambadi Tanners Enviro Control Systems Ltd,	183 Cutchery Road Extention, Valayampet Sector, Valayampet, Vaniambadi - 635751	Tamil Nadu	June 21, 2013	Directions under section 5 of E (P)A 1986	August 24, 2011 Modified directions issued on June 13, 2012	The CETP was inspected under follow up of directions issued. Compliance report sent to H.O vide letter dated August 05, 2013. Status of action taken by H.O. is not known.	<a href="#">Report</a>

3	M/s Talco Pernambut Tannery Effluent Treatment Co. Ltd.,	Bakkalapalli, Pernambut - 635810	Tamil Nadu	June 21, 2013	Directions under section 5 of E (P)A 1986	June 14, 2011	The CETP was inspected under follow up of directions issued. Compliance report sent to H.O vide letter dated August 05, 2013. Status of action taken by H.O. is not known.	<a href="#">Report</a>
4	M/s Ranipet SIDCO Finished Leather Effluent Treatment Co. Ltd (Phase -1)	Plot No. 199, SIDCO Industrial Estate, Ranipet-632403, Vellore District,	Tamil Nadu	June 19, 2013	Directions under section 5 of E (P)A 1986	September 08, 2011	The CETP was inspected under follow up of directions issued. Compliance report sent to H.O vide letter dated August 05, 2013. Status of action taken by H.O. is not known.	<a href="#">Report</a>
5	M/s SIPCOT & SIDCO Phase II, Entrepreneur Finished Leather Effluent Treatment Company (P) Ltd.,	Plot No. 105, SIDCO Industrial Estate, phase-II, Pulyanthangal, Ranipet-632403 Vellore District,	Tamil Nadu	June 20, 2013	Directions under section 5 of E (P)A 1986	August 10, 2011	The CETP was inspected under follow up of directions issued. Compliance report sent to H.O vide letter dated August 05, 2013. Status of action taken by H.O. is not known.	<a href="#">Report</a>

6	M/s Govind Solvents Pvt. Ltd.,	No. 19(P) - 22, Kunigal Industrial Area, Kallanayakana Village, Kunigal - 572 130, Tumkur Dist.,	Karnataka	February 10, 2014	Pending in H.O.		The inspection report sent to H.O vide letter dated March 07, 2014. Status of action taken by H.O. is not known.	<a href="#">Report</a>
7	M/s Eco Green Solutions Systems (P) Ltd.,	No. 48/A-4, KIADB Industrial Area, Doddaballapur - 561 203,	Karnataka	February 11, 2014	Pending in H.O.		The inspection report sent to H.O vide letter dated March 07, 2014. Status of action taken by H.O. is not known.	<a href="#">Report</a>
8	M/s Malur CETP,	Malur Industrial Estate, Malur, Kolar	Karnataka	May 03, 2013	directions under section 18(1)(b) of Water Act	January 01, 2014	Action taken report awaited from KSPCB	<a href="#">Report</a>
9	M/s Jeedimetla Effluent Treatment Ltd	Hyderabad, Andhra Pradesh	Andhra Pradesh	February 26, 2014	Pending in H.O		The inspection report sent to H.O.	<a href="#">Report</a>
10	M/s Pattancheru Enviro-Tech Ltd	Hyderabad, Andhra Pradesh	Andhra Pradesh	February 26, 2014	Pending in H.O.			