

Speed Post

File No. B-751 (473)/Textile/WQM-II/CPCB/2017-18

Date: 14-03-2018

To,

18246
76

**M/s. Shikher Textile & Bleaching,
18 B, Dada Nagar,
Kanpur, UP**

DIRECTIONS UNDER SECTION 5 OF THE ENVIRONMENT (PROTECTION) ACT, 1986

WHEREAS, Textile dyeing and bleaching industries have been identified as one of the Grossly Polluting Industries (GPI) which have been discharging environmental pollutants directly or indirectly on land and into water, having potential threat to cause adverse effect on land and the ambient water quality and;

WHEREAS, a direction under section 18 (1) (b) of the water (Prevention & Control of Pollution) Act, 1974 and the Air (Prevention & Control of Pollution) Act, 1981 was issued on February 05, 2014 to all 11 Ganga Basin State Pollution Control Board (SPCBs) / Pollution Control Committees (PCCs) for installation of online effluent monitoring systems w.r.t. pH, BOD, COD, TSS & flow parameters in Textile dyeing and bleaching industries; and

WHEREAS, M/s. Shikher Textile & Bleaching, 18 B, Dada Nagar Kanpur, UP (hereafter referred as 'the Unit') is a Textile, dyeing industry and it was inspected by team deputed by CPCB on April 10, 2017 and following observation were made:

1. The Unit was found non-complying w.r.t. prescribed discharge standards as outlet sample analysis shows TDS; 2356 against 2100 mg/l, COD; 496 against 250 mg/l, BOD; 170 against 30 mg/l, sulphide 32 against 2 mg/l, Oil & grease 44 against 10 mg/l, and SAR value as 178 against 26.

WHEREAS, CPCB issued closure direction dated 29.06.2017 under Section 5 of Environment (Protection) Act, 1986 to the unit; and

WHEREAS, the unit replies vide letter dated 24.06.2017, 13.07.2017, 01.12.2017, 11.12.2017 and 09.02.2018 Nil were examined and following observations are made:

1. The unit was modified its ETP and provided details for the same.
2. The unit has installed flow meter, web camera at ETP outlet and connected to CPCB server.

AND WHEREAS, CPCB constituted a three-member committee vide office order dated 27.09.2017 having representative from CPCB, MoEF & CC and NMCG for examination and recommendation for revocation of the closure direction issued by CPCB; and

WHEREAS, the three member committee in its meeting held on 27.02.2018 examined the reply of the Unit and recommended that performance audit report of ETP be submitted within 45 days of start of the operations from reputed government institutions: and

NOW THEREFORE, in view of the above mentioned observations and in exercise of the powers delegated to the Chairman CPCB, under section 5 of the Environment (Protection) Act, 1986, the unit is directed to comply with the following direction:

1. The Unit shall resume operation and shall treat their effluent to meet the effluent discharge standards as notified under Environment (Protection) Rules, 1986.


2. The Unit **M/s. Shikher Textile & Bleaching, 18 B, Dada Nagar Kanpur, UP** shall submit treated effluent analysis report from laboratory recognized under Environment (Protection) Act, 1986 within 45 days of resumption of operations.
3. The Unit shall submit performance audit report of ETP be submitted within 45 days of start of the operations from reputed government institutions.
4. The Unit shall ensure continuous connectivity with CPCB server.
5. The Unit shall immediately inform to CPCB regarding the resumption of operations.

In case of default in compliance with the above directions, CPCB will be constrained to initiate action without any further notice, in accordance with the provisions of the Environment (Protection) Act, 1986.

(S. P. SINGH PARIHAR)
CHAIRMAN

Copy to:

- | | |
|--|---|
| <ol style="list-style-type: none"> 1. Member Secretary,
Uttar Pradesh Pollution Control Board,
Building No. TC-12V,
Vibhuti Khand, Gomti Nagar, Lucknow-226010 | <p>:With request to arrange inspection of the Unit for compliance verification within 60 days of resumption of operation, please.</p> |
| <ol style="list-style-type: none"> 2. Joint Secretary (CP Division).
Ministry of Environment, Forests & Climate Change,
Indira Paryavaran Bhavan,
Jor Bagh Road, New Delhi - 110 003 | <p>:For information please</p> |
| <ol style="list-style-type: none"> 3. The Regional Director,
Regional Directorate (N),
Central Pollution Control Board,
Zonal Office (North) PICUP
Bhawan Vibhuti Khand, Gomti Nagar,
Lucknow - 226 010, Uttar Pradesh | <p>:For information please</p> |
| <ol style="list-style-type: none"> 4. District Magistrate
Amroha, Uttar Pradesh | <p>:For information please</p> |
| <ol style="list-style-type: none"> 5. Managing Director
Dakshimanchal Vidyut Vitran Nigam Ltd.,
Urja Bhawan, NH-2 (Agra-Delhi Bypass Raod)
Sikandra, Agra-282007,
Uttar Pradesh | <p>: With the direction to reconnect power supply to the unit</p> |
| <ol style="list-style-type: none"> 6. Incharge, IT Division, CPCB, Delhi | <p>: For uploading the direction on CPCB website.</p> |
| <ol style="list-style-type: none"> 7. Master copy (Textile), CPCB, Delhi | <p>: For record.</p> |


(A. SUDHAKAR)
MEMBER SECRETARY