



केन्द्रीय प्रदूषण नियंत्रण बोर्ड  
CENTRAL POLLUTION CONTROL BOARD  
पर्यावरण, वन एवं जलवायु परिवर्तन मंत्रालय भारत सरकार  
MINISTRY OF ENVIRONMENT, FOREST & CLIMATE CHANGE GOVT. OF INDIA

By Speed Post

F.No. B-23012/1/IPC-IV/ 1039

April 20, 2018

To

M/s Bhartiya Leather Udyog,  
B-7 MIE, Part II. Jhajjar,  
Haryana

**Sub : Revocation of Closure Directions issued under Section 5 of the Environmental (Protection) Act, 1986.**

WHEREAS, the Central Government has notified the standards for discharge of environmental pollutants from various categories of industries under the Environment (Protection) Act, 1986 and the rules framed there under; and

WHEREAS, the Ministry of Environment, Forest and Climate Change, Govt. of India, vide notification S.O.157(E) of 27.02.1996 has delegated powers vested under Section 5 of the Environment (Protection) Act, 1986 (29 of 1986) to the Chairman, Central Pollution Control Board (CPCB), to issue direction to any industry, Municipal Corporation, Municipal Council, Cantonment Board to any local or other Authority for the violation of emission and effluent standards notified under the Environment (Protection) Rules, 1986 and other standards and norms; and

WHEREAS, M/s Bhartiya Leather Udyog, B-7 MIE, Part II. Jhajjar, Haryana (hereinafter referred as 'the Unit') is engaged in processing of wet blue skin to finished leather through dyeing and fat liquoring process at a processing capacity of 800 skin of (sheep/goat) per day; and

WHEREAS, CPCB had conducted inspection of the Unit on July 3, 2017 to verify the compliance status of discharge standards and made the following observations:

1. The Unit has ETP based on ASP at a capacity of 25 kld.
2. The Unit found complying the prescribed effluent norms with pH - 7.47 (Standards: 6.5 to 9) and TSS - 27.9 mg/l (Standards: 100mg/l) but not complying for the parameter of BOD - 36mg/l (Standards: 30mg/l) and treated effluent is partially recycled into process and rest discharged into HUDA drain.
3. The Unit has installed DG sets which are not equipped with acoustic enclosure and exhaust pipe.
4. The Unit has valid consent under Air/Water acts upto 30.9.2020 and Authorisation under the Hazardous and other Wastes (Management, & Transboundary Movement) Rules, 2016.
5. The Unit has installed OCEMS at final outlet of ETP, and OCEMS data indicates improper maintenance.

'परिवेश भवन' पूर्वी अर्जुन नगर, दिल्ली-110032  
Parivesh Bhawan, East Arjun Nagar, Delhi-110032

दूरभाष/Tel : 43102030, 22305792, वेबसाइट/Website : www.cpcb.nlc.in

WHEREAS, in view of the non-compliance of prescribed norms, Chairman, CPCB vide letter dated August 16, 2017 had issued following directions under section 5 of the Environment (Protection) Act, 1986 to Unit for compliance:

1. The Unit shall operate and maintain effluent treatment plant (ETP) properly to treat the entire generated effluent and shall provide proper mixing arrangement at equalization tank of ETP and shall ensure compliance with the prescribed effluent discharge standards.
2. The Unit shall ensure proper maintenance and operation & calibration of OCEMS so as to obtain continuous accurate results.
3. The Unit shall install electromagnetic flow meter at the water consumption point and shall maintain records of the same.
4. The Unit shall install acoustic enclosures and adequate exhaust pipe system at DG sets.
5. The Unit shall submit compliance report to CPCB on the direction points 1 to 4 within 45 days.

WHEREAS, the Unit vide letter dated 24/9/2017 and e-mail dated 26/9/2017 had submitted compliance report to CPCB on aforementioned directions; and

WHEREAS, officials from CPCB Regional Director, Lucknow, had carried out inspection of the Unit on 28/11/2017 to verify compliance of CPCB direction issued on 16.08.2017 and following compliance status was observed:

1. The treated effluent discharged by the Unit was found complying with the notified effluent discharge norms for parameters: pH - 6.9 (Standards: 6.5 to 9), TSS - 80 mg/l (Standard: 100mg/l) and Total Cr.: BDL but not complying for the parameter of BOD -115 mg/l (Standard: 30mg/l). The Unit has provided proper mixing arrangement at equalization tank of ETP.
2. The OCEMS was found in operation but there is substantial difference in OCEMS data and laboratory results:

Sampling location	Analysis results	Date/time	Parameters (All Parameters are in mg/l except pH)			
			pH	TSS	COD	BOD
Final outlet	Lab data	28/11/17 (10 AM)	6.90	80.0	513.0	115.0
	Online data		7.17	57.34	140.01	24.32

3. The Unit has installed electromagnetic flow meter at the meter at the water consumption point and maintained records.
4. The Unit has installed acoustic enclosure and exhaust pipe at DG sets.

WHEREAS, the above compliance status had indicated repeated violation of notified effluent discharge norms. In view of this, the Chairman, CPCB has issued following directions to the Unit under section 5 of the Environment (Protection) Act, 1986 on 29.12.2017 :

1. To close down all the manufacturing operations with immediate effect and report compliance to CPCB.
2. The Unit shall immediately initiate necessary steps to ensure compliance in respect of the following issues and submit report to CPCB:

- a. The Unit shall get conducted adequacy assessment of ETP through reputed institutes such as IIT/NEERI/CLRI and submit report to CPCB. The ETP shall be modified/upgraded as per advise of the consulting institute to ensure compliance with the notified norms.
- b. The Unit shall seek guidance from the expert institute to carry out proper operation and maintenance of ETP so as to ensure compliance with notified norms.
- c. The Unit shall ensure proper maintenance and calibration of OCEMS so as to obtain continuous accurate results.

WHEREAS, the Unit vide letter dated 19/2/2018 has submitted ETP adequacy report prepared by CSIR-CLRI, Chennai, Self Certificate of closure indicating closure of their Unit from 10.01.2018, copy of Water consent having validity upto 30.09.2020 issued by Haryana State Pollution Control Board and photographs of upgraded/modified ETP; and

WHEREAS, the Unit vide letter dated 03.04.2018 submitted the detailed statement on compliance / implementation of the suggestions / recommendations made by CLRI, Chennai; and

WHEREAS, the case of revocation of the closure directions issued to the unit was examined by the 'Committee' constituted by CPCB during its meeting convened on April 17, 2018 and the Committee has recommended for revocation of Closure Directions issued to the Unit on 29.12.2017 subject to certain conditions;

NOW THEREFORE, in view of the above and in exercise of the powers delegated to the Chairman, Central Pollution Control Board under Section 5 of the Environment (Protection) Act, 1986, the closure directions issued on 29.12.2017 to the Unit: M/s Bhartiya Leather Udyog, B-7 MIE, Part II, Jhajjar, Haryana are hereby revoked and the unit is permitted to restart the manufacturing operations, subject to following conditions :

1. The Unit shall submit ETP performance audit report from a Government institute such as IIT/NEERI/CLRI to CPCB within 45 days of resuming operation.
2. The Unit shall ensure all time compliance with the prescribed discharge norms and proper functioning of OCEMS.
3. The unit shall be inspected within a period of two months from the date of issue of these revocation directions by CPCB. Regional Directorate - North, Lucknow shall verify compliance.
4. The unit shall run only with valid Consent from Haryana State Pollution Control Board under the Water (Prevention & Control of Pollution) Act, 1974, Air (Prevention & Control of Pollution) Act, 1981 and Authorization under the Hazardous & Other Wastes (Management & Transboundary Movement) Rules, 2016.

In case of failure of the Unit to comply with directions, action as deemed fit under the provisions of Environment (Protection) Act, 1986 shall be taken against the Unit.


  
(S.P. Singh Parihar)  
Chairman

M/s Bhartiya Leather Udyog, B-7 MIE, Part II, Jhajjar, Haryana



Copy to:

1.	<b>The Chairman</b> Haryana State Pollution Control Board, Sector 5, Panchkula, Haryana 134109	For information & necessary action please.
2.	<b>The District Magistrate,</b> Jhajjar, Haryana	For information please.
3.	<b>The Managing Director,</b> Uttar Haryana Bijli Vitran Nigam Limited, Vidyut Sdan, Plot No. C16, Sector-6, Panchkula, Haryana	With request to re-connect electricity supply.
4.	<b>The Joint Secretary, (CP Division)</b> Ministry of Environment, Forest & Climate Change, Indra Prayavaran Bhawan, Jor Bagh Road, New Delhi-110003	For information please.
5.	<b>The Regional Director,</b> Central Pollution Control Board, Regional Directorate (Luknow) PICUP Bhawan, Ground Floor Vibhuti Khand, Gomit Nagar, Luknow-226010	With request to inspect the Unit and submit the inspection report within 02 months from the date of issue of these revocation directions .
✓ 6.	<b>The Divisional Head, IT Division, CPCB</b>	For necessary action please.
7.	<b>The Divisional Head, IPC-VI Division, CPCB</b>	For information please.

  
(A. Sudhakar)  
Member Secretary

