

BY REGISTERED AD

B-883(S)/IPC-III/2017-18/

November 16, 2017

To

M/s Shri Ram Jawahar SSK Ltd;  
Phaltan, Ramnagar, Distt-Satara  
Maharashtra-415523

**Sub: Closure Directions under Section 5 of the Environment (Protection) Act, 1986 regarding installation of on-line effluent monitoring system-Revoked thereof.**

**WHEREAS**, the Ministry of Environment & Forests, Government of India, vide Notifications No. S. O. 157 (E) of 27.02.1996 and S. O. 730 (E) dated 10.07.2002, has delegated the powers vested under Section 5 of the Environment (Protection) Act, 1986 (29 of 1986) to the Chairman, Central Pollution Control Board, to issue directions to any industry or any local body or any other authority for violations of the standards and rules notified under the Environment (Protection) Rules, 1986 and amendment thereof; and

**WHEREAS**, in view of the above and in exercise of the powers delegated to the Chairman, Central Pollution Control Board under section 5 of the Environment (Protection) Act, 1986, noticed dated 24.07.2015 was served to the unit to **Show Cause why the unit should not be closed down if the unit has not complied fully with the directions issued w.r.t. installation of online effluent monitoring system by June 30, 2015 and further directions to comply with; and**

**WHEREAS**, no reply as recorded was filed by the said unit in response of the same; and

**WHEREAS**, in view of the above and in exercise of the powers delegated to the Chairman, Central Pollution Control Board under section 5 of the Environment (Protection) Act, 1986, **the unit vide letter no. B-400(S)/2016-17/4258/ dated 22.08.2016 was directed to close down their Sugar mill and not to resume their manufacturing operation till installation and commissioning of online 24x7 monitoring system and networking of data with SPCB & CPCB, and to submit compliance to CPCB within 15 days on the receipt of the Closure Direction; and**

**WHEREAS**, the unit has responded to the above said Closure Direction vide its letter dated 31-08-2017 and informed to have complied with the directions regarding installation, commissioning and Connectivity of online continuous effluent monitoring system (OCEMS) and the same was verified by IT Division of CPCB; and

**However, it has been observed that the unit has closed its manufacturing operations on 19-01-2017, only after operating it during crushing season 2016-17 which is non-compliance of the closure direction issued by CPCB vide letter dated 22-08-2016 under Section 5 of the E(P) Act, 1986 and for which action as per law shall be initiated separately.**

**WHEREAS**, CPCB constituted a three-member committee vide office order dated 03.10.2017 having representative(s) from CPCB and MoEF&CC for examination and recommendation for revocation of Closure Direction issued by CPCB; and

**WHEREAS**, the committee in its meeting held on 25.10.2017 reviewed the compliance made by the unit & verified the submitted supporting documents in line with the agreed criteria and recommended that the unit may be allowed to resume its manufacturing operation with certain conditions; and

**NOW THEREFORE**, in view of the compliance made by the unit to the direction issued by CPCB and in exercise of powers vested under Section 5 of the Environment (Protection) Act, 1986, the unit **M/s Shri Ram Jawahar SSK Ltd; Phaltan, Ramnagar, Distt-Satara Maharashtra-415523** is allowed to resume its manufacturing operations subject to following condition:

1. It shall be ensured that the installed OCEMS devices are functioning properly & continuously and that data from that device are uninterruptedly transferred to CPCB. Any failure in his regard shall be intimated to CPCB with reasons thereof & shall be rectified at the earliest.
2. Ensure periodic calibration of the analyzers as per Standard Operating Procedure/recommendations of the supplier and submit the calibration results.
3. Submission of treated effluent sample analysis result from EPA approved laboratory within one month of commencement of manufacturing operations and once per month during the entire crushing period.

In case of failure of the unit to comply with the above directions action as deemed appropriate will be taken with the provisions under Environment (Protection) Act, 1986.

**(S.P. SINGH PARIHAR)**  
**CHAIRMAN**

Copy to:

- 1 The Member Secretary,**  
Maharashtra Pollution Control Board,  
certificate provided by industry). 2nd,  
3rd & 4th floor, Opp. Cine planet,  
Near Sion Circle, Sion (E)  
**Mumbai- 400 022** : To ensure compliance of  
directions please
- 2 The Advisor (CP Division)**  
Ministry of Environment, Forest & C.C  
Prithvi Block, Indira  
Paryavaran Bhawan, Jorbagh Road,  
**New Delhi - 110 003** : For information please
- 3 The District Magistrate**  
Collectorate office,  
Near LIC Buiding, Powai Naka,  
Satara, **Maharashtra-415001** : For information and necessary action  
please
- 4 The Superintendent Engineer,**  
Maharashtra State Electricity Distribution Cor.  
Ltd., Tal. Phaltan, Distt-satara  
**Maharashtra-415001** : With direction to re-connect  
power supply
- 5 The Regional Directorate, (West)**  
Central Pollution Control Board  
Parivesh Bhawan, Opp. VMC Ward  
Offic No.10, Subhanpura  
**Vadodara - 390 023** : For information please
- 6 The Div Head, IT Division, CPCB** : For uploading on CPCB website



**(A. SUDHAKAR)**  
**MEMBER SECRETARY**