



SPEED POST

F.No.B-751(538)/Textile/WQM-II/2016-17/ 16026

29.01.2019
01.02.2019

To,

M/s Shri Bihari Lal Kargha Udyog,
Rajvansh Vihar, Garh Road,
Meerut, Uttar Pradesh.

Compliance Directions under Section 5 of the Environment (Protection) Act, 1986-reg.

WHEREAS, the Textile, Dyeing & Bleaching industry is identified as one of the Grossly Polluting industries (GPIs) which has been discharging environmental pollutants directly or indirectly into the ambient air and water, having potential threat to cause adverse effect on the water and air quality; and

WHEREAS, the Ministry of Environment & Forests, Government of India, vide Notifications No. S.O. 157 (E) of 27.02.1996 and S.O. 730 (E) dated 10.07.2002, has delegated the powers vested under Section 5 of the Environment (Protection) Act, 1986 (29 of 1986) to the Chairman, Central Pollution Control Board, to issue directions to any industry or any local body or any other authority for violation of standards and rules notified under the Environment (Protection) Rules, 1986 and amendment thereof; and

WHEREAS, M/s Shri Bihari Lal Kargha Udyog, Rajvansh Vihar, Garh Road, Meerut, Uttar Pradesh (hereafter referred as the unit) is a textile industry; and

WHEREAS, CPCB issued directions dated 01.12.2017 under Section 5 of the Environment (Protection) Act, 1986, to the unit to comply with following directions:

1. The unit may resume operation and shall inform the date of resumption of operation to CPCB.
2. The unit shall ensure uninterrupted connectivity of the OCEMS to the CPCB and SPCB server for treated effluent monitoring.
3. The unit shall operate ETP properly so as to ensure compliance of the standards of treated effluent as per Gazette notified dated 10.10.2016 under the Environment (Protection) Act, 1986. At any stage, if the treated effluent does not meet notified discharge standards the unit shall close down manufacturing operations immediately and report to CPCB.
4. The unit shall submit treated effluent analysis report from laboratory recognized under the Environment (Protection) Act, 1986 within 30 days of resumption of operation.

WHEREAS, Show Cause notice dated 16.11.2018 was issued to the unit for not complying with directions dated 01.12.2017 under Environment (Protection) Act, 1986; and

WHEREAS, the unit vide its letters dated 04.12.2018 and 26.12.2018 has submitted treated effluent analysis report in compliance of CPCB directions dated 01.12.2017; and

NOW THEREFORE, in view of the above observations and exercising powers delegated to the Chairman, Central Pollution Control Board under Section 5 of the Environment (Protection) Act, 1986, the unit M/s Shri Bihari Lal Kargha Udyog, Rajvansh Vihar,

Garh Road, Meerut, Uttar Pradesh is hereby directed to comply with the following directions:

1. The unit shall operate its ETP properly so as to achieve compliance of stipulated standards.
2. The unit shall ensure regular connectivity of OCEMS with CPCB server.

In case of non-compliance of the above directions, CPCB will be constrained to initiate appropriate action against the unit, **M/s Shri Bihari Lal Kargha Udyog, Rajvansh Vihar, Garh Road, Meerut, Uttar Pradesh** without giving any further notice in accordance with the provision of Environment (Protection) Act, 1986.



(S P SINGH PARIHAR)
CHAIRMAN


31.01.19

Copy to:

- 1 Member Secretary
Uttar Pradesh Pollution Control Board,
Building No. TC-12V, Vibhuti Khand, Gomti
Nagar, Lucknow – 226 010
- 2 Joint Secretary (CP Division)
Ministry of Environment, Forest & Climate
Change
Prithvi Block, Indira Paryavaran Bhawan,
Jorbagh Road,
New Delhi – 110 003
- 3 In-charge, IT Division, CPCB Delhi
- 4 Master File-WQM-II Div., CPCB Delhi

For kind information pls.

For uploading the directions
on CPCB website



(PRASHANT GARGAVA)
MEMBER SECRETARY

o/c