



B-29016/04/06/IPC-I/ 739

केन्द्रीय प्रदूषण नियंत्रण बोर्ड
CENTRAL POLLUTION CONTROL BOARD
पर्यावरण, वन एवं जलवायु परिवर्तन मंत्रालय भारत सरकार
MINISTRY OF ENVIRONMENT, FOREST & CLIMATE CHANGE GOVT. OF INDIA
August 10, 2018

To,
M/s Anil Spinners,
Plot no. H-19-20, Industrial Area,
Panipat, Haryana- 132103

Sub: Directions under Section 5 of the Environment (Protection) Act, 1986- reg.

WHEREAS, Textile dyeing and bleaching industries are identified as one of the Grossly Polluting industries (GPIs) which have been discharging environmental pollutants directly or indirectly into the ambient air and water, having potential threat to cause adverse effect on the water and air quality; and

WHEREAS, the Central Government has notified general discharge standards of environmental pollutants from various categories of industries under the Environment (Protection) Act, 1986 and the rules framed there under; and

WHEREAS, Hon'ble Supreme Court of India in the matter of Paryavaran Suraksha Samiti Vs Union of India & Others dated 22/02/2017 directed that no industry which requires "consent to operate" from the concerned Pollution Control Board, is permitted to function, unless it has a functional effluent treatment plant, which is capable to meet the prescribed norms for removing the pollutants from the effluent, before it is discharged; and

WHEREAS, the Ministry of Environment & Forests, Government of India, vide Notifications No.S.O.157(E) of 27.02.1996 and S.O.730(E) dated 10.07.2002, has delegated the powers vested under Section 5 of the Environment (Protection) Act, 1986 (29 of 1986) to the Chairman, Central Pollution Control Board, to issue directions to any industry or any local body or any other authority for violations of the standards and rules notified under the Environment (Protection) Rules, 1986 and amendment thereof; and

WHEREAS, M/s Anil Spinners, Plot no. H-19-20, Industrial Area, Panipat, Haryana (here in after referred as 'the unit') is a textile processing unit; and

WHEREAS, the unit was inspected on 24th May, 2018 by CPCB officials and following observations are made:

- 1) The unit was found non-operational at the time of inspection.
- 2) The unit is involved in the bleaching of polyester yarn at an installed capacity of 3-4 MTD as per the inspection report.
- 3) The unit has a borewell to meet its water requirements and generates about 18 KLD of waste water.
- 4) The ETP was also found to be non-operational at the time of the inspection.
- 5) The ETP consists of a collection tank, reaction tank, tube settler, sludge drying bed, filter feed tank and filter water tank.
- 6) The treated effluent is sent to a STP through sewer lines and after treatment is disposed to Panipat drain and then to River Yamuna.
- 7) The ETP sludge is disposed to Gujrat Enviro Protection and Infrastructure Pvt. Ltd.
- 8) The air, water and hazardous waste consents of the unit are valid upto 30th September, 2020.
- 9) During the visit, untreated effluent was found in the underground storage tank. However, it was requested to operate ETP during the visit and effluent was collected from the outlet.

Page 1 of 2

10) The analysis results of the samples collected from collection tank showed the following results: **pH – 10.62** (against stipulated standards of 6-.5-8.5), **TSS- 143 mg/l** (against stipulated standards of 100 mg/l), **BOD -190 mg/l** (against stipulated standards of 30 mg/l), **COD-732 mg/l** (against stipulated standards of 250 mg/l), **Colour-103 PCU** (against stipulated standards of 150 PCU), **TDS- 1412 mg/l** (against stipulated standards of 2100 mg/l), **SAR- 6.70** (against stipulated standards of 26), **Oil & Grease -21mg/l** (against stipulated standards of 10 mg/l), **Phenol -0.20 mg/l** (against stipulated standards of 1.0 mg/l), **Ammonical Nitrogen -6 mg/l** (against stipulated standards of 50 mg/l) and **Chromium -0.03 mg/l** (against stipulated standards of 2 mg/l) which show non-compliance wrt pH, TSS, BOD, COD and Oil and Grease.

It is evident from above observations that the unit is discharging partially treated/ untreated effluent into the drain, thereby posing serious threat to the surface and groundwater quality.

NOW, THEREFORE, in view of the above and in exercise of the powers delegated to the Chairman, Central Pollution Control Board under Section 5 of the Environment (Protection) Act, 1986, the unit, **M/s Anil Spinners, Plot no. H-19-20, Industrial Area, Panipat, Haryana** is hereby directed to remain closed till the compliance of the following directions:

1. The unit shall operate ETP to conform the prescribed standards as per Consent to Operate from HSPCB.
2. The unit shall not restart its operation until compliance of above direction and written permission is obtained from CPCB.

In case of non-compliance of the above directions, CPCB will be constrained to initiate appropriate action against the unit without giving any further notice in accordance with the provision of Environment (Protection) Act, 1986.


13.8.18
(S. P. Singh Parihar)
Chairman


Copy to:

1. The Chairman
Haryana State Pollution Control Board
C-11, Sector – 6
Panchkula, Haryana
2. The Advisor (CP Division)
Ministry of Environment, Forests and Climate Change
Prithvi Wing, 2nd Floor, Room No. 216
Indira Paryavaran Bhawan
Aliganj, Jor Bagh Road
New Delhi – 110003
3. The Incharge, Regional Directorate
Central Pollution Control Board
Ground & First Floor, PICUP Bhawan
Vibhuti Khand, Gomti Nagar
Lucknow – 226 020
4. The Chairman,
Uttar Haryana Bijli Vitran Nigam Ltd.
(UHBVNL), Vidyut Sadan, Plot No.: C 16,
Sector-6, Panchkula, Haryana- 134109
5. I/c, IT, CPCB

: With a request to disconnect
Electricity supply of the Unit
and allowing supply only for
domestic & security purposes.


(Prashant Gargava)
Member Secretary