



केन्द्रीय प्रदूषण नियंत्रण बोर्ड
CENTRAL POLLUTION CONTROL BOARD
पर्यावरण, वन एवं जलवायु परिवर्तन मंत्रालय भारत सरकार
MINISTRY OF ENVIRONMENT FOREST & CLIMATE CHANGE GOVT OF INDIA

EMAIL & SPEED POST

CP-14/31/2024-IPC-II-HO-CPCB-HO 2482

June 14, 2024

To,

M/s Aditi Industries
Vill-Hatigaon, Kaliabor,
Nagaon, Assam – 782137

Sub: Directions under Section 5 of the Environment (Protection) Act, 1986 to M/s Aditi Industries, Nagaon, Assam - reg.

WHEREAS, the cement industries are identified as one of the 17 categories of highly polluting industries which have been discharging environmental pollutants directly or indirectly into the ambient air and water, having potential threat to cause adverse effect on the water and air quality; and

WHEREAS, Ministry of Environment, Forests & Climate Change has notified emission norms for Particulate matter, SO₂ & NO_x vide GSR 612 (E) dated 25.08.2014; and amended it vide GSR 496 (E) dated 09.05.2016 for all cement industries and vide GSR 497 (E) dated 10.05.2016 for cement industries, carrying out co-processing of wastes in their cement kilns; and

WHEREAS, in order to verify the environmental compliance and the status of OCEMS, M/s Aditi Industries, Nagaon, Assam, has been inspected by a team of CPCB RD, Shillong, on 21.03.2024 under the environmental surveillance of 17 categories of high pollution potential industries and common facilities based on OCEMS data. The salient observations based on the inspection carried out by CPCB inspecting team are as below:

1. The Authorization for Hazardous Waste was valid until 31.03.2024. The Unit did not provide application for the renewal of the authorization.
2. The stack monitoring was not carried out as the Unit had not provided a sampling porthole to the stack attached to cement mill.
3. Fugitive dust emission was observed as the conveyor to cement mill was not enclosed. Also, the dust extraction cum bag filter for cement mill area, is not maintained properly.
4. Cement grinding being a dry process, the Unit generates no effluent. Water is consumed only for domestic purposes.
5. The Unit did not have a designated area for the storage of hazardous waste (used oil), as required by the H & OW (M&TM) Rules, 2016.
6. The display board was found placed inside the industry premises, instead of outside.
7. OCEMS has been installed in the stack attached to the cement mill for the emission

‘परिवेश भवन’ परवी अर्जुन नगर, दिल्ली-110032

Parivesh Bhawan, East Arjun Nagar, Delhi-110032

दूरभाष/Tel : 43102030, 22305792, वेबसाइट/Website : www.cpcb.nic.in

parameter PM and connected to CPCB & SPCB server. It was observed that the OCEMS data was not being transmitted to the CPCB server; however, it was being transmitted to the SPCB server. Further, the Unit did not provide the calibration certificate of the OCEMS.

WHEREAS, the Ministry of Environment, Forest & Climate Change Government of India, vide Notifications No. S. O. 157 (E) of 27.02.1996 and S. O. 730 (E) dated 10.07.2002, has delegated the powers vested under Section 5 of the Environment (Protection) Act, 1986 (29 of 1986) to the Chairman, Central Pollution Control Board, to issue directions to any industry or any local body or any other authority for violations of the standards and rules notified under the Environment (Protection) Rules, 1986 and amendment thereof.

NOW, THEREFORE, in exercise of the powers vested under Section 5 of the Environment (Protection) Act, 1986, the following directions are hereby issued to M/s Aditi Industries, Nagaon, Assam:

1. The Unit shall obtain the renewal of Authorization for Hazardous Waste from the concerned SPCB.
2. The Unit should provide the necessary facilities (porthole and platform) to carry out isokinetic sampling of stack, as per the Emission Regulations Part-III.
3. The Unit shall take measures to control fugitive emissions. The conveyor shall be adequately covered and the bag filter connected to the cement mill shall be properly maintained.
4. The Unit shall store hazardous waste at designated area, as per CPCB guidelines. Further, the Unit shall maintain records of hazardous waste and submit annual reports as per the H & OW (M&TM) Rules, 2016
5. The Unit shall place display board at the entrance gate and ensure it is regularly updated, in compliance of the Hon'ble Supreme Court order in WP 657/1995.
6. The Unit shall ensure calibration of OCEMS as per CPCB guidelines for CEMS (Section 9.5 of August 2018 edition) and ensure uninterrupted data transmission to CPCB server.


M/s Aditi Industries, Nagaon, Assam, shall ensure compliance of the above directions and submit compliance report along with documentary evidence within 30 days from the date of issue of the directions.

In case of failure, CPCB will be constrained to initiate action as deemed necessary and appropriate in the circumstances under the Environment (Protection) Act, 1986.

13/4/16
(Tanmay Kumar)
Chairman
L.K.

Copy to:

1. The Chairman,
Assam Pollution Control Board,
Bamunimaidan, Guwahati,
Assam – 781021
2. The Director (CP Division),
Ministry of Environment, Forest and Climate Change,
Indira Paryavaran Bhawan, Aliganj,
Jor Bagh Road, New Delhi – 110 003
3. The Regional Director, Shillong
Central Pollution Control Board,
Opp. Government Press, Ground Floor,
CTO Building, BSNL Shillong- 793001
4. The District Magistrate
Old Trunk Road, Christianpatty,
Nagaon, Assam 782001
5. The Divisional Head - IT, CPCB HO
6. The Divisional Head – IPC VI, CPCB HO


(Bharat Kumar Sharma)
Member Secretary

