

BY SPEED POST

B-29016/IPC-I/Dye/

2637

November 03, 2021

To

M/s. Panoli Intermediates (India) Pvt. Limited,
Plot No. 157, 156 A & B, GIDC Nandesari,
District Vadodra- 391340
Gujarat

Sub: Directions under Section 5 of the Environment (Protection) Act, 1986 -reg.

WHEREAS, Dye and Dye Intermediate units are identified as one of the 17 categories of highly polluting industries which have been discharging environmental pollutants directly or indirectly into the ambient air and water, having potential threat to cause adverse effect on the water and air quality; and

WHEREAS, the Central Government has notified the standards for discharge of environmental pollutants from various categories of industries under the Environment (Protection) Act, 1986 and the rules framed there under; and

WHEREAS, in order to investigate a complaint made against M/s Panoli Intermediates (India) Pvt. Ltd., Plot No. 157, 156 A & B, GIDC Nandesari, Vadodara, Gujarat, the Unit) were jointly inspected by Central Pollution Control Board, Regional Directorate, Vadodara and Gujarat Pollution Control Board on 27.09.2021 to assess the adequacy of the existing pollution control measures; and

WHEREAS, the inspecting team observed the following:

1. The Unit was found operational during visit.
2. The Unit has provided ammonia recovery system for the mother liquor generated from PNA Plant. During the visit, the ammonia recovery system was in operation and high intensity of odour of ammonia was felt inside the plant. This may be due to leakages during operation.
3. During visit, haziness in the environment near chlorine dosing tank and ammonia recovery system were observed. This may be due to uncontrolled dosing of chlorine in open tank leading to release of excess chlorine gas which mixes with fugitive ammonia gas and creates haziness and produces odour. Improper way of chlorine dosing is a threat to the environment and is related to operational safety also.
4. During the visit, huge yellow-orange fumes from the stack attached to spray dryer were observed indicating in-adequacy/non-functioning of APCD (Air Pollution Control Devices).

5. Fugitive emission/fumes from the salts stored in the spray dryer section were observed.
6. It was observed that roof of hazardous waste storage shed did not properly cover the entire required area. The hazardous waste storage area was not having any provision for collection of leachate and its transfer back to ETP.
7. Proper records for the presently stored quantity of hazardous waste, wastewater treated, MEE operation, spray dryer operation was not found at site during visit. Huge quantum of different types of hazardous waste was found stored.
8. Storage tank with name of Nitrobenzene was observed near hazardous waste storage shed. Nitrobenzene is not used in the Unit as raw-material or generated as product. Details about the permission, quantity etc. about the storage of such material was not available with the Unit. Organic layer on the accumulated water near the tank area indicates leakage from the tank.
9. The Unit has not provided online connectivity of PTZ camera and flow meter as per condition of consolidated consent and authorization granted by Gujarat Pollution Control Board.


WHEREAS, the Ministry of Environment & Forests, Government of India, vide Notifications No. S. O. 157 (E) of 27.02.1996 and S. O. 730 (E) dated 10.07.2002, has delegated the powers vested under Section 5 of the Environment (Protection) Act, 1986 (29 of 1986) to the Chairman, Central Pollution Control Board, to issue directions to any industry or any local body or any other authority for violations of the standards and rules notified under the Environment (Protection) Rules, 1986 and amendment thereof.

NOW, THEREFORE, based on above facts and observations, in exercise of powers vested under Section 5 of the Environment (Protection) Act, 1986, following directions are issued to the Unit M/s Panoli Intermediate (India) Pvt. Ltd. Plot No. 157, 156 A & B, GIDC Nandesari, Vadodara, Gujarat:

1. The Unit shall immediately close its operations and shall not resume its operations till remedial measures on above observation are made, environmental norms are complied with and written permission to operate is obtained from Central Pollution Control Board.
2. The Unit shall take necessary steps to prevent the leakage of Ammonia from the Ammonia recovery system.
3. The Unit shall provide proper dosing system for carrying out the dosing of Chlorine in an environmentally sound and safe manner.
4. The Unit shall submit the safety audit report from an auditor competent under the Factory Act.

5. The Unit shall provide proper Air Pollution Control System to the stack of spray dryer as per consolidated consent and authorization granted by Gujarat Pollution Control Board.
6. The Unit shall take adequate steps to prevent fugitive emissions in the spray dryer section.
7. The Unit shall take adequate steps for proper storage and management of hazardous waste as per Hazardous & other Waste (Management and Transboundary Movement) Rules, 2016 with proper record maintenance.
8. The Unit shall provide adequate system for collection and treatment of the leachate generated from the hazardous waste storage area.
9. The Unit shall maintain proper records of effluent generation, treatment and reuse.
10. The Unit shall not store any chemical without the permission of Gujarat Pollution Control Board.
11. The Unit shall take adequate steps to prevent the leakage of any stored chemical.
12. The Unit shall provide online flow meter to the effluent treatment system and web (PTZ) camera in the effluent treatment area with online connectivity to Central Pollution Control Board / Gujarat Pollution Control Board.

In case of failure to comply with the aforesaid directions, necessary action as deemed fit under the provision of the Environment (Protection) Act, 1986 including imposition of environmental compensation / legal action will be taken by Central Pollution Control Board.


 (Tanmay Kumar)
 Chairman

Copy to:

1. The Chairman
Gujarat State Pollution Control Board
Sector 10-A, Gandhi Nagar- 382 043,
Gujarat
2. The Chairperson
Madhya Gujarat Vij Co. Ltd.
Sardar Patel Vidyut Bhavan,
Race Course, Vadodara-390007

To ensure that the Unit remains closed till written permission to operate is obtained from CPCB

With request to disconnect industrial electricity supply of Unit, allowing supply only for domestic & security purposes.

3. The Joint Secretary (CP Division)
Ministry of Environment, Forests and Climate Change,
Prithvi Wing, 2nd Floor,
Room No. 216, Indira Paryavaran Bhawan
Aliganj, Jor Bagh Road, New Delhi-110003
4. The Regional Director
Central Pollution Control Board
Parivesh Bhawan
Opp VMC Ward office no 10
Subhanpura, Vadodara - 390 023
- ✓ 5. D.H., IT, CPCB
6. D.H. IPC- VI, CPCB


(Prashant Gargava)
Member Secretary