



केन्द्रीय प्रदूषण नियंत्रण बोर्ड
CENTRAL POLLUTION CONTROL BOARD
पर्यावरण, वन एवं जलवायु परिवर्तन मंत्रालय भारत सरकार
MINISTRY OF ENVIRONMENT, FOREST & CLIMATE CHANGE GOVT. OF INDIA

SPEED POST

September 05, 2017

B-29016/04/06/IPC-I/9499

To

M/s. S. S. Organics Limited,
Sy. No. 252/1, Aroor, Sadasivapet,
Medak (dist)-502291, Telangana

Sub: Directions under Section 5 of the Environment (Protection) Act, 1986 regarding installation of on-line effluent and emission monitoring system-reg.

WHEREAS, the Pharmaceutical industries are identified as one of the 17 categories of highly polluting industries which have been discharging environmental pollutants directly or indirectly into the ambient air and water, having potential threat to cause adverse effect on the water and air quality; and

WHEREAS, M/s. S. S. Organics Limited, Telangana (herein after referred to as the Unit) has installed online monitoring system; and

WHEREAS, the Online effluent Monitoring system of the Unit was in offline mode during the month of April-May 2017; and

WHEREAS, the Unit was inspected by a team of official(s) from the CPCB Regional Directorate, Bangalore on July 27, 2017 to assess the adequacy of the existing pollution control measures and online effluent monitoring system, observed as following:

- 1) The Unit was not in operation from past two days and also not in operation at the time of inspection.
- 2) The effluent treatment plant (ETP) was not in operation at the time of inspection. The effluent stored in collection tanks (old & new) shows that the ETP was not operated regularly.
- 3) The unit informed that the HTDS is treated in ETP & LTDS effluent stream is reused in the process. However there was no separate collection tank for collection of HTDS & LTDS effluent streams.
- 4) The raw materials are stored without sign board, roof of the walls are stained from the rain water.
- 5) The solvent Dimethyl carbonate (liquid) stored without level in open area near the raw material since 2016, which is not utilized by the industry in manufacturing of any of the product.
- 6) The flooring of the filter press used in the process is damaged.
- 7) The used and filled drums are scattered haphazardly in the unit premises.
- 8) The plastic and other waste materials are stored near the ETP.
- 9) The unit has not provided the proper space for the storage of hazardous waste.

WHEREAS, camera feed was not available at the time of data connectivity verification as per the online data connectivity verification report of the IT division of the CPCB dated August 22, 2017; and

WHEREAS, the Ministry of Environment & Forests, Government of India, vide Notifications No. S. O. 157 (E) of 27.02.1996 and S. O. 730 (E) dated 10.07.2002, has delegated the powers vested under Section 5 of the Environment (Protection) Act, 1986 (29 of 1986) to the Chairman, Central Pollution Control Board, to issue directions to any industry or any local body or any other authority for violations of the standards and rules notified under the Environment (Protection) Rules, 1986 and amendment thereof.

NOW, THEREFORE, in exercise of powers vested under Section 5 of the Environment (Protection) Act, 1986, the following directions are being issued:

1. The Unit shall immediately close down all the plant operations and shall not resume till permission is obtained from the CPCB for the same.
2. The Unit shall properly operate the effluent treatment plant efficiently so as to achieve the notified standards.
3. The Unit shall properly operate the online monitoring system (flow meter & web camera).
4. The Unit shall provide separate collection tanks for HTDS and LTDS streams.
5. The Unit shall provide the proper labelling to the raw material and repair of walls of the storage room.
6. The Unit shall safely dispose the unutilized solvent Dimethyl carbonate (liquid) to the TSDF as per the guidelines of Hazardous Waste Management (HWM) rules.
7. The Unit shall provide the impervious flooring with adequate liquid/solid collection system at the filter press area.
8. The Unit shall provide the proper space for the used and filled drums.
9. The Unit shall improve the house keeping by segregating all type of solid waste scattered haphazardly in the Unit premises and also provide the dedicated storage area.
10. The Unit shall provide proper storage space for the Hazardous waste.

The Unit M/s. S. S. Organics Limited, Telangana shall submit the compliance report for the direction at point (1 to 8) above immediately on receipt of direction. Failure to comply with the above directions will attract action in accordance with the provision of the Environment (Protection) Act, 1986.

(S. P. Singh Parihar)
Chairman

Copy to:

1. The Chairman
Telangana State Pollution Control Board
Paryavaran Bhawan, A-3, Industrial
Estate, Sanathnagar, Hyderabad-500018
2. The Chairman
Southern Power Distribution
Company of Telangana Limited
Corporate Office: # 6-1-50,
Mint Compound, Hyderabad-500063
:With request to disconnect industrial
electricity supply of Unit, allowing supply
only for domestic & security purposes.
3. The Advisor (CP Division)
Ministry of Environment, Forests and Climate Change
Prithvi Wing, 2nd Floor, Room No. 216, Indira
Paryavaran Bhawan Aliganj, Jor Bagh Road, New Delhi - 110003
4. The Regional Director
Central Pollution Control Board
1st & 2nd Floors, Nisarga Bhavan A-Block,
Thimmaiah Main Road, 7th D Cross, Shivanagar,
Opp. Pushpanjali Theatre, Bangalore -560 010
5. The Incharge, IT, CPCB
6. The Incharge IPC-VI, CPCB

(A. Sudhakar)
Member Secretary