

**SPEED POST**

**F. No. B-751 (595)/Textile/ WQM-II/CPCB/2017-18      September 12, 2017**

To  
M/s. Meenar Polydyed Tarn Ltd.,  
12 Bakhara, Bijuliabir, Dandi,  
Chandauli-232101, Uttar Pradesh

10558

**Closure Directions under Section 5 of the Environment (Protection) Act, 1986 –reg.**

**WHEREAS**, the Textile dyeing and bleaching industries are identified as one of the Grossly Polluting industries (GPIs) which have been discharging environmental pollutants directly or indirectly into the ambient air and water, having potential threat to cause adverse effect on the water and air quality; and

**WHEREAS**, there is need to inculcate habit of self-monitoring within the industries for complying with the prescribed standards and this can be achieved by the methods like installing online effluent & emission monitoring devices; and

**WHEREAS**, the Ministry of Environment & Forests, Government of India, vide Notifications No.S.O.157(E) of 27.02.1996 and S.O.730(E) dated 10.07.2002, has delegated the powers vested under Section 5 of the Environment (Protection) Act, 1986 (29 of 1986) to the Chairman, Central Pollution Control Board, to issue directions to any industry or any local body or any other authority for violations of the standards and rules notified under the Environment (Protection) Rules, 1986 and amendment thereof; and

**WHEREAS**, M/s. Meenar Polydyed Tarn Ltd., 12 Bakhara, Bijuliabir, Dandi, Chandauli-232101, Uttar Pradesh, (herein after referred as the Unit) is involved in the processing of polyester yarns spinning and dyeing units; and

**WHEREAS**, CPCB issued closure direction dated 25.04.2017 to the unit due to non-compliance; and

**WHEREAS**, inspection of the unit was conducted on 20.06.2017 by CPCB officials and following observations are made;

1. At the time of inspection, the unit was found operational and both wet and dry industrial activities were going on as a normal day of production, which is in violence of CPCB closure direction dated 25.04.2017 issued under Section 5 of the Environmental (Protection) Act, 1986.
2. The unit was operational without achieving compliance from points 1 to 8, as CPCB direction and the unit was found violating the CPCB closure direction dated 25.04.2017.
3. The unit has not installed OCEMS.
4. The unit is not complying with stipulated norms of effluent discharge w. r. t. pH (11.29 against norm of 6.5-8.5), TSS (262mg/l against norm of 100mg/l), BOD (89.9mg/l against norm of 30mg/l), COD (1106mg/l against norm of 250mg/l) and Phenol as C<sub>6</sub>H<sub>5</sub>OH (1.82mg/l against norm of 1mg/l).

Contd.....

AND WHEREAS, the unit was found in operation which is in violation of CPCB direction dated 25.04.2017 issued under Section 5 of Environmental (Protection) Act, 1986, for which appropriate legal action shall be initiated separately; and

**NOW, THEREFORE**, in view of the above and in exercise of the powers delegated to the Chairman, Central Pollution Control Board under section 5 of the Environment (Protection) Act, 1986, the unit is hereby directed to close down all manufacturing operations immediately till compliance of following directions;

1. The unit shall carryout augmentation and upgradation of ETP system for treatment of generated wastewater so as to meet the prescribed effluent discharge norms and shall submit the time bound action plan to CPCB.
2. The unit shall install and connect the OCEMS with CPCB portal server.
3. The unit shall obtain valid consents to operate and submit copy to CPCB
4. The unit remain close until permitted by the CPCB.

In case of default in compliance with the above directions, appropriate actions against the unit, M/s. Meenar Polydyed Tarn Ltd., 12 Bakhara, Bijuliabir, Dandi, Chandauli-232101, Uttar Pradesh will be initiated without giving any further notice, in accordance with provisions of the Environment (Protection) Act, 1986.

  
(S P SINGH PARIHAR)  
CHAIRMAN

Copy to:

- 1 **Member Secretary**  
Uttar Pradesh Pollution Control Board,  
Building No. TC-12V, Vibhuti Khand,  
Gomti Nagar, **Lucknow – 226 010**  
With a request to ensure compliance of the directions.
- 2 **Advisor (CP Division)**  
Ministry of Environment, Forest & Climate Change  
Prithvi Block, Indira Paryavaran Bhawan,  
Jorbagh Road,  
**New Delhi – 110 003**  
For kind information pls.
- 3 **The District Magistrate**  
Collectorate Office, Dist. Chandauli,  
Uttar Pradesh  
To ensure closure of the unit as per direction
- 4 **Managing Director**  
Chandauli Electricity Supply Company Ltd.,  
Chandauli, UP  
With the direction to disconnect power supply except residential, street light and security system  
For information.
- 5 **Regional Directorate (North),  
Central Pollution Control Board,**  
PICUP Bhawan, Ground Floor,  
Vibhuti Khand, Gomti Nagar,  
**Lucknow – 226 010.**
- 6 In-charge, IPC-III Div., CPCB Delhi  
For information.
- ✓7 In-charge, IT Division, CPCB  
For information.
- 8 In-charge, WQM-II Div., CPCB Delhi  
For information.



(A SUDHAKAR)  
**MEMBER SECRETARY**