



SPEED POST

F.No.B-751(161)/Tannery/WQM-II/CPCB/2016-17 13 September, 2017

To

M/s Leder Fabric,  
D-16, Site-2,  
Industrial Area, Unnao  
Uttar Pradesh

**Directions Under Section 5 of the Environment (Protection) Act, 1986**

**WHEREAS**, the Ministry of Environment & Forests, Government of India, vide Notifications No.S.O.157(E) of 27.02.1996 and S.O.730(E) dated 10.07.2002, has delegated the powers vested under Section 5 of the Environment (Protection) Act, 1986 (29 of 1986) to the Chairman, Central Pollution Control Board, to issue directions to any industry or any local body or any other authority for violations of the standards and rules notified under the Environment (Protection) Rules, 1986 and amendment thereof; and

**WHEREAS**, the tannery and leather industries are also identified as one of the 17 categories of highly polluting industries which have been discharging environmental pollutants directly or indirectly in to ambient Air and Water, having potential to threat to cause adverse effects on the water and air quality; and

**WHEREAS**, it is obligatory on the part of industries to install effluent treatment plants (ETPs) to comply with the effluent discharge standards as notified under Environment (Protection) Act, 1986 and rules framed there under and also to meet the consent conditions granted by State Pollution Control Board (SPCBs)/ Pollution control Committees (PCCs); and

**WHEREAS**, M/s, Leder Fabric, D-16, Site-2, Industrial Area, Unnao, Uttar Pradesh (here after referred to as the 'Unit') is a Tannery (leather processing); and

**WHEREAS**, the unit was inspected by a team of officials authorized by CPCB on 11.04.2017 to verify the compliance status; and

**WHEREAS**, CPCB issued closure direction dated May 31, 2017 under section 5 of Environment (Protection) Act, 1986 to the unit; and

**WHEREAS**, unit replies vide letter dated 14.06.2017, 26.07.2017 and 24.08.2017 was examined and following observations are made:

1. The unit has stopped manufacturing operations.
2. The unit has proper connectivity with CPCB server.
3. The unit has applied for consent under Water Act and Hazardous waste authorization to UPPCB.

Cont.....

4. Unit replied that ETP treated effluent test report is not possible until the unit is operational & has promised to provide with in a week after restart of the operation.
5. Unit has provided self certificate as per the requirement.

**AND NOW, THEREFORE**, in view of the above observations and in exercise of the powers, delegated to the Chairman, CPCB under section 5 of the Environment (Protection) Act, 1986, the following directions are issued for compliance:

1. The unit M/s, Leder Fabric, D-16, Site-2, Industrial Area, Unnao, Uttar Pradesh, shall **resume manufacturing operations** only after seeking valid consent from UPPCB and inform to CPCB.
2. Unit shall ensure to provide continuous data connectivity on CPCB server.
3. The unit shall provide treated effluent analysis report from Environment (Protection) Act, 1986 recognized laboratory.


In case of default in compliance with the above directions CPCB will be constrained to initiate appropriate actions against the unit, without giving any further notice, in accordance with provisions of Environment (Protection) Act, 1986.



(S P SINGH PARIHAR)  
CHAIRMAN

Copy to:

1. The Member Secretary : [For kind information]  
Uttar Pradesh Pollution Control Board  
Building No. TC-12V, Vibhuti Khand,  
Gomati Nagar, Lucknow
2. The Incharge, Zonal Office : [For kind information]  
Central Pollution Control Board,  
PICUP Bhawan, Ground Floor  
Vibhuti Khand, Gomati Nagar,  
Lucknow-226010
3. The Advisor (CP Division) : [For kind information]  
Ministry of Environment, Forests & Climate Change,  
Indra Paryavaran Bhavan,  
Jor Bagh Road, New Delhi - 110 003
- ✓ 4. The Incharge, IT Division, CPCB : [For uploading on CPCBs  
website]
5. Master copy WQM-II, CPCB



(A. SUDHAKAR)  
MEMBER SECRETARY

