

**SPEED POST**

F. No. B-751(639)/Textile/WQM-II/CPCB/2017-18

8<sup>th</sup> November, 2017

To

M/s M.J. Dyeing & Finishing,  
F-8, SITE 5, Panki Industrial Area,  
Kanpur, Uttar Pradesh-221401.

13570

**Directions under Section 5 of the Environment (Protection) Act, 1986 –reg.**

**WHEREAS**, the Textile dyeing and bleaching industries are identified as one of the Grossly Polluting industries (GPIs) which have been discharging environmental pollutants directly or indirectly into the ambient air and water, having potential threat to cause adverse effect on the water and air quality; and

**WHEREAS**, the Central Government has notified the general discharge standards of environmental pollutants from various categories of industries under the Environment (Protection) Act, 1986 and the rules framed there under;

**WHEREAS**, the Ministry of Environment & Forests, Government of India, vide Notifications No.S.O.157(E) of 27.02.1996 and S.O.730(E) dated 10.07.2002, has delegated the powers vested under Section 5 of the Environment (Protection) Act, 1986 (29 of 1986) to the Chairman, Central Pollution Control Board, to issue directions to any industry or any local body or any other authority for violations of the standards and rules notified under the Environment (Protection) Rules, 1986 and amendment thereof; and

**WHEREAS**, M/s M.J. Dyeing & Finishing, Panki Industrial Area, Kanpur, U.P. (here in after referred as 'the unit') is a textile processing unit; and

**WHEREAS**, CPCB issued directions dated 30<sup>th</sup> July, 2015 to the Unit under Section 5 of the Environment (Protection) Act, 1986 for installation of online effluent monitoring system; and

**WHEREAS**, inspection of the unit was conducted on April 20<sup>th</sup>, 2017 to check the status of compliance of prescribed norms and was issued closure directions dated 18<sup>th</sup> May, 2017 for non compliance with discharge standards as well as non-installation of OCEMS; and

**WHEREAS**, the unit was re-inspected on 25<sup>th</sup> August, 2017 to verify the compliance of CPCB directions and the following observations were made:

- 1) The unit was found operational at the time of the inspection.
- 2) The unit has valid consents upto 31<sup>st</sup> December, 2017, under Water and Air Acts, issued by UPCCB. The unit has installed a flowmeter at the ETP outlet but was not connected to the server of CPCB/UPCCB.
- 3) The media filter in the ETP was found to be non-operational during the inspection.
- 4) The unit has applied for CGWA permission.
- 5) The analysis report of the treated effluent being discharged, indicated non-compliance w.r.t. pH 8.67 (norms. 6.5-8.5), TSS 397 mg/l (norms 100 mg/l), BOD – 184 mg/l (norms. 30 mg/l) and COD- 672 mg/l (norms 250 mg/l).
- 6) The Unit has also not installed web camera to provide connection with CPCB server.

**Contd.**

- 7) The Unit has not maintained log book of production, fresh water consumption, effluent generation, etc.

**AND WHEREAS**, the Unit was found in operation on August 25<sup>th</sup> 2017, which is in violation of CPCB closure direction dated 18<sup>th</sup> May, 2017, issued under Section 5 of the Environment (Protection) Act 1986, for which appropriate legal action shall be initiated separately.

It is evident that the Unit is discharging untreated effluent posing potential risk to river water quality.

**NOW, THEREFORE**, in view of the above and in exercise of the powers delegated to the Chairman, Central Pollution Control Board under Section 5 of the Environment (Protection) Act, 1986, the unit, **M/s M.J. Dyeing & Finishing, Panki Industrial Area, Kanpur, U.P.** is hereby directed to close down its operation till the compliance of the CPCB directions dated 18<sup>th</sup> May, 2017. The Unit shall seek permission from CPCB before resumption of manufacturing operations. CPCB may initiate appropriate actions against the unit, without giving any further notice, in accordance with provisions of Environment (Protection) Act, 1986.

**(S P SINGH PARIHAR)**  
Chairman

**Copy to:**

1. The Member Secretary,  
Uttar Pradesh Pollution Control Board,  
Building No. TC-12V, Vibhuti Khand,  
Gomati Nagar, Lucknow.
2. The Regional Directorate, Central  
Pollution Control Board, Lucknow,  
PICUP Bhawan, Ground Floor, Vibhuti  
Khand, Gomati Nagar, Lucknow-226010
3. The Advisor (CP Division) Ministry of  
Environment, Forests & Climate Change,  
Indra Paryavaran Bhavan,  
Jor Bagh Road, New Delhi - 110 003

For kind information

- ✓ 4. The Incharge, IT Division, CPCB

For uploading on CPCB's website

5. Master File WQM-II, CPCB

*A Sudhakar*  
**(A SUDHAKAR)**  
for **MEMBER SECRETARY**